

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FX 8629L

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR TAIL PIPE (CONSISTENT)	BROKEN	258.00	258.00
1	REAR LOCK (CONSISTENT)	BENT	150.00	150.00
1	TAIL LAMP (CONSISTENT)	SCRATCHED / CUT	178.00	178.00
1	REAR LH SIGNAL LAMP (CONSISTENT)	BROKEN	125.00	125.00
1	HANDLE BAR (CONSISTENT)	BENT	195.00	195.00
1	CLUTCH LEVER (CONSISTENT)	сит	95.00	95.00
1	SET MIRROR (CONSISTENT)	N/S CUT / O/S NOT NECESSARY	220.00	110.00
2	SHROUD L/RH (CONSISTENT)	N/S CUT / O/S NOT NECESSARY	270.00	135.00
1	SET CRASH BAR (CONSISTENT)	СИТ	330.00	330.00
1	FRONT MUDGUARD (CONSISTENT)	TO REPAIR SEE LABOUR	235.00	-
1	HEAD LAMP (CONSISTENT)	NOT NECESSARY	1,100.00	-
1	FUEL TANK (CONSISTENT)	TO REPAIR SEE LABOUR	350.00	-
1	FRONT COWLING (CONSISTENT)	CUT	285.00	285.00
	LESS 10% DISCOUNT		-379.10	-186.10
			3,411.90	1,674.90
	SPECIAL NETT ITEMS			
1	REAR NUMBER PLATE (SN) (CONSISTENT)	BENT	25.00	15.00
			25.00	15.00
	LABOUR			
	TOWING FEE.	NOT NECESSARY	40.00	_
	REMOVE & REPLACE PARTS ,ALIGN & ETC.INCLUSIVE OF THE REPAIR OF FRONT MUDGUARD AND FUEL TANK .		250.00	220.00
	PUTTY & TOUCH UP PAINT WORK.		380.00	200.00
	DISMANTLE & REPRESS FORK TUBE ,FORK UNDER BRACKET ,LABOUR.	NOT NECESSARY	180.00	-
			850.00	420.00
	GRAND TOTAL		4,286.90	2,109.90

Report Ref No. CC4/ASM20006177/Dpa3q2



Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS		1,650.00
(TO ITS PRE-ACCIDENT CONDITION)		

Report Ref No. CC4/ASM20006177/Dpa3q2



**ANG BRYAN TANI** 

Automotive Assessor / Investigator