Adjuster Report Page 1 of 4

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

CC4/III20006180/R1PA3Q2 Our File No:

015017000341204PT

Date: 22/09/2020

Engine No:

REFERENCE

Handling Insurer: India International Insurance Pte Ltd MCOM0015 Policy No: Claimant SKZ99Z Insured Vehicle No: SHA2124M

Vehicle No:

Date of Loss: TP 04/06/2020 Nature of Claim: Claim No: MCT20060042

DESCRIPTION & IDENTIFICATION OF VEHICLE

SKZ99Z Reg No:

LAND ROVER DISCOVERY SPORT, 2.0 SE Si4 Make & Model:

(L550) (A)

SALCA2AG3GH555210 Reg. Date: 17/12/2015 (Man. Year: 2015) Chassis No:

Colour: Brown Odometer: 172091 km

Engine Capacity: 1999 cc Market Value/New Car N/A

Price:

Market Value/New Car Price Sum Insured (S\$):

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 235/60R18 Rear Tyre Size: 235/60R18 Front Left Side: Pirelli 6 mm Rear Left Side: Pirelli 6 mm Front Right Side: Rear Right Side: Pirelli 6 mm Pirelli 6 mm

The above values represent the remaining tyre treads depth

Repairer's	Adjuster's	Difference	Diff %
17,241.68	8,442.72	8,798.96	51.03
0.00	0.00	0.00	
10,005.00	6,305.00	3,700.00	36.98
0.00	0.00	0.00	
0.00	0.00	0.00	
27,246.68	14,747.72	12,498.96	45.87
1,907.27	1,032.34	874.93	45.87
29,153.95	15,780.06	13,373.89	45.87
	17,241.68 0.00 10,005.00 0.00 0.00 27,246.68 1,907.27	17,241.68 8,442.72 0.00 0.00 10,005.00 6,305.00 0.00 0.00 0.00 0.00 27,246.68 14,747.72 1,907.27 1,032.34	17,241.68 8,442.72 8,798.96 0.00 0.00 0.00 10,005.00 6,305.00 3,700.00 0.00 0.00 0.00 0.00 0.00 0.00 27,246.68 14,747.72 12,498.96 1,907.27 1,032.34 874.93

+ Car Rental (5.0 x S\$130.00/day + 7.00% GST) (S\$) 695.50

> **Nett Liability (S\$)** 16,475.56

INSPECTION

Date of Assignment: 09/06/2020

29/06/2020 Date Inspected: Inspected At: Wearnes Automotive Pte Ltd

45 LENG KEE ROAD Singapore 159103

Estimated Period of Repair: 5.0 days

Adjuster: MOHD RASUL Manager: CHEW HSIAO TONG Adjuster Report Page 2 of 4

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 4

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 02 Sep 2020)

LAND ROVER DISCOVERY SPORT 2.0 SE Si4 (L550) (A) (Catalogue:Merimen Singapore Parts: M1-SUV

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SKZ99Z)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page

numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE PANEL DSPOR	Bent	3,447.60 FS	*3,102.84 FS
2	1		*LLR058514/REAR WINDS	Necessary	1,091.30 FS	*982.17 FS
3	2		*ADHESIVE AND SEALER	Necessary	310.20 FS	*279.18 FS
4	1		**D* PRIMER GLASS & P	Necessary	39.30 FS	*35.37 FS
5	1		*BADGE REAR DISCO D	Necessary	167.10 FS	*150.39 FS
6	1		*BADGE REAR VERY DS	Necessary	149.90 FS	*134.91 FS
7	1		*BADGE OVAL REAR RR3	Necessary	89.00 FS	*80.10 FS
8	1		*BOOT LAMP RH	Serviceable	615.30 FS	*- FS
9	1		*BOOT LAMP LH	Serviceable	612.30 FS	*- FS
10	1		*LLR073071/BUMPER-R	Deformed	1,723.80 FS	*1,551.42 FS
11	1		*TOW EYE COVER REAR	Deformed	557.80 FS	*502.02 FS
12	1		*BRACKET -BUMPER MOU	Serviceable	121.10 FS	*- FS
13	1		*BRACKET -BUMPER MOU	Serviceable	121.10 FS	*- FS
14	1		*LLR059014/REINFORCEM	Bent	625.60 FS	*563.04 FS
15	1		*LLR060910/LAMP -FOG	Serviceable	354.10 FS	*- FS
16	1		*LLR060910/LAMP -FOG	Serviceable	354.10 FS	*- FS
17	1		*WIRING -BUMPER	Cut	441.00 FS	*396.90 FS
18	1		*BODY PANEL SEALANT	Not Necessary	928.00 FS	*-FS
19	1		*ADHESIVE SEALER FL2	Necessary	703.00 FS	*632.70 FS
20	1		*MUFFLER -REAR RH	Serviceable	2,192.30 FS	*- FS
21	1		*MUFFLER -REAR LH	Serviceable	2,192.30 FS	*- FS
22	2		*CLAMP	Serviceable	373.80 FS	*- FS
23	1		*BEZAL LATCH	Necessary	31.68 FS	*31.68 FS
F=Franchise part. S=SpcNett.						
				Total Parts (S\$)	17,241.68	8,442.72

Report was unsubmitted during this print-out.

Adjuster Report Page 4 of 4

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	TO REPLACE REAR BOOTLID ,REAR BUMPER ,REAR REFLECTOR ,LOWER TOW COVER ,EXHAUST ,ETC	New	4,800.00	2,400.00
2	TO SPRAYPAINT & BLEND ON REAR BOOTLID ,REAR BUMPER ,ETC	New	3,000.00	2,000.00
3	TO INSTALL REAR WINDSCREEN FIL	New	280.00	280.00
4	TO REPLACE REAR WINDSCREEN	New	900.00	600.00
5	TO REMOVE ,REFIT & TRANSFER REAR BOOTLID PARTS	New	500.00	500.00
6	TO CHECK WIRING INCLUDE RESETTING OF ALL ELECTRICAL MODULES	New	525.00	525.00
	Gross Labour Cost (S\$)		10,005.00	6,305.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >