

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS3/AIG20006185/R1TF3E2

**Date:** 23/06/2020

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1900007198-01

**Claimant Vehicle No :** SJT1421M **Insured Vehicle No :** SKE8763Y

Date of Loss: 21/04/2020 Nature of Claim: TP Claim No: 6678416755SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SJT1421M</b>	Engine No:	2ZR0431430
Make & Model:	TOYOTA WISH, 1.8 (A)	Chassis No:	ZGE200010177
Reg. Date:	25/09/2009 (Man. Year: 2009)	Odometer:	299509 km
Colour:	White		
Engine Capacity:	1797 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	LIONSPORT HP 5 mm	Rear Left Side:	LIONSPORT HP 5 mm
Front Right Side:	LIONSPORT HP 5 mm	Rear Right Side:	LIONSPORT HP 5 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

### INSPECTION

Date of Assignment: 12/06/2020

Date Inspected: 15/06/2020 Inspected At:

A Auto Services (HQ)  
A AUTO SERVICES, 5 SOON LEE  
STREET #06-31 PIONEER POINT  
Singapore 627607

Estimated Period of Repair: 4.0 days

**Adjuster:** MOHD RASUL

**Manager:** DENISE TAY KWEE CHENG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Torn	0.00 F	*- F
2	1		*REAR BUMPER CLIPS	Necessary	0.00 F	*- F
3	1		*REAR END PANEL	Repair	0.00 F	*- F
4	1		*REAR END PANEL TOP GARNISH	Cracked	0.00 F	*- F
5	1		*TAILGATE	Bent	0.00 F	*- F
6	2		*TAILGATE EMBLEM	Necessary	0.00 F	*- F
7	1		*TAILGATE GLASS MOULDING	Necessary	0.00 F	*- F
8	1		*TAILGATE GLASS SEALANT	Necessary	0.00 F	*- F
9	1		*TAILGATE LOCK	Cut	0.00 F	*- F
10	1		*TAILGATE INNER BOARD	Cracked	0.00 F	*- F

F=Franchise part.

<b>Total Parts (S\$)</b>	<b>0.00</b>	<b>0.00</b>
--------------------------	-------------	-------------

Report was unsubmitted during this print-out.
---

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.
---

**< END OF ESTIMATES >**