

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20006186/UPA3Q2

Date: 09/03/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1700089583

Claimant
Vehicle No : FBP5609D **Insured Vehicle No :** SLV1924U

Date of Loss: 05/03/2020 Nature of Claim: TP Claim No: 8592586003SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FBP5609D	Engine No:	G3E6E0485864
Make & Model:	YAMAHA SNIPER T150, 150cc	Chassis No:	MH3UG0740K0152864
Reg. Date:	25/04/2019 (Man. Year: 2019)	Odometer:	48521 km
Colour:	Black		
Engine Capacity:	150 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	80-90-17	Rear Tyre Size:	100-80-17
Front Left Side:	Dunlop 7 mm	Rear Left Side:	Dunlop 7 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,474.20	833.30	2,640.90	76.01
Miscellaneous Items	0.00	0.00	0.00	
Labour	860.00	250.00	610.00	70.93
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	4,334.20	1,083.30	3,250.90	75.01
Approved Total (Overridden) (\$\$)		800.00		
Nett Amount (\$\$)	4,334.20	800.00	3,534.20	81.54
+ Loss of Use (5.0 x S\$20.00/day) (\$\$)		100.00		
Nett Liability (\$\$)		900.00		
Global Sum Settlement (\$\$)		900.00		

INSPECTION

Date of Assignment: 10/06/2020

Date Inspected: 12/06/2020 Inspected At:

Erofia Motor Trading Pte Ltd (KAKI BUKIT)
1 KAKI BUKIT AVE 6 #02-62
Singapore 417883

Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA

Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	2		*FORNT FORK TUBE ASSY	Serviceable	640.00 FL	*- FL
2	1		*HORN COVER INNER	Not Necessary	80.00 FL	*- FL
3	1		*FRONT WHEEL RIM	Not Necessary	280.00 FL	*- FL
4	1		*FORK UNDER BRACKET	Not Necessary	185.00 FL	*- FL
5	1		*FRONT RIM SHAFT	Not Necessary	45.00 FL	*- FL
6	1		*FRONT RIM BEARING	Not Necessary	38.00 FL	*- FL
7	1		*FRONT BRAKE DISC	Not Necessary	155.00 FL	*- FL
8	1		*HANDLE BAR	Serviceable	88.00 FL	*- FL
9	1		*HANDLE BAR END -R/H	Not Necessary	32.00 FL	*- FL
10	1		*SET HAND GRIP	Not Necessary	55.00 FL	*- FL
11	1		*HANDLE BAR INNER BRACKET	Not Necessary	68.00 FL	*- FL
12	1		*SIDE MIRRORS	O/S Cut	110.00 FL	*55.00 FL
13	1		*BRAK LEVER	Scratched	32.00 FL	*32.00 FL
14	1		*SET FAIRING ASSY (LOCAL REPAIR)	Scratched	445.50 FS	*120.00 FS
15	1		*FRONT FOOTREST BRACKET -R/H	Cut	65.00 FL	*65.00 FL
16	1		*BRAKE PEDAL	Cut	35.00 FL	*35.00 FL
17	1		*REAR FOOTREST -R/H	Cut	42.00 FL	*42.00 FL
18	1		*REAR FOOTREST BRACKET	Serviceable	40.00 FL	*- FL
19	1		*EXHAUST ASSY	Repair	78.00 FL	*- FL
20	1		*EXHAUST PROTECTOR -REAR	Scratched	485.00 FL	*78.00 FL
21	1		*EXHAUST PROTECTOR -FRONT	Scratched	60.00 FL	*60.00 FL
22	1		*EXHAUST PIPE END COVER	Scratched	55.00 FL	*55.00 FL
23	1		*FRONT FAIRING REAR COVER LH	Cracked	65.00 FL	*65.00 FL
24	1		*SET NUMBER PLATE	Not Necessary	28.00 FS	*- FS
25	2		*FORK OILS	Not Necessary	30.00 FS	*- FS
26	2		*FORK OIL SEALS	Not Necessary	56.00 FS	*- FS
27	1		*SET STEERING CONE	Not Necessary	90.00 FS	*- FS
28	1		*REAR BOX	Cut	180.00 FS	*180.00 FS
29	1		*REAR BOX BRACKET	Not Necessary	90.00 FS	*- FS
30	1		*SET STICKER	Necessary	95.00 FS	*95.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	3,747.50	882.00
- List Item Discount on L Items 10.00/10.00% (\$)	273.30	48.70
Total Parts (\$)	3,474.20	833.30

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO PROVIDE TOWING SERVICE	New	50.00	0.00
2	TO CHECK WIRING AND RESET HEADLAMP FOCUSING	New	80.00	0.00
3	TO PROVIDE LABOUR	New	380.00	250.00
4	TO REPAIR BODY FRAME	New	350.00	0.00
Gross Labour Cost (\$\$)			860.00	250.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >