

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG20006191/KGA3Q2**Date:** 18/04/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900258396
Claimant Vehicle No :	GBA6589A	Insured Vehicle No :	GBA386H
Date of Loss:	10/06/2020	Nature of Claim:	TP
		Claim No:	6829962729SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBA6589A	Engine No:	1KD1657631
Make & Model:	TOYOTA HIACE, 3.0 D (M)	Chassis No:	JTFHT02P600005649
Reg. Date:	26/09/2007 (Man. Year: 2007)	Odometer:	498568 km
Colour:	White		
Engine Capacity:	2982 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195 R15X8	Rear Tyre Size:	195 R15X8
Front Left Side:	Maxmiler 9 mm	Rear Left Side:	Maxmiler 9 mm
Front Right Side:	Maxmiler 9 mm	Rear Right Side:	Maxmiler 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	14,949.20	6,919.74	8,029.46	53.71
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,800.00	2,280.00	1,520.00	40.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	18,749.20	9,199.74	9,549.46	50.93
Approved Total (Overridden) (S\$)		7,000.00		
(S\$)	18,749.20	7,000.00	11,749.20	62.67
+ GST 7.00/7.00% (S\$)	1,312.44	490.00	822.44	62.66
Nett Amount (S\$)	20,061.64	7,490.00	12,571.64	62.67
+ Car Rental (12.0 x S\$85.60/day) (S\$)		1,027.20		
Nett Liability (S\$)		8,517.20		
Global Sum Settlement (S\$)		8,500.00		

INSPECTION

Date of Assignment:	11/06/2020	Chew Goon Motor (AMK)
Date Inspected:	12/06/2020 Inspected At:	Blk 10 Ang Mo Kio Industrial Park 2A, #01-15/16 & 17, AMK Autopoint
Estimated Period of Repair:	9.0 days	Singapore 568047

Adjuster: KENNETH KONG**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Bent	2,162.00 FL	*1,942.10 FL
2	1		*TAILGATE EMBLEM	Necessary	81.00 FL	*81.00 FL
3	1		*TAILGATE OUTER GARNISH	Warped	149.00 FL	*149.00 FL
4	1		*TAILGATE LOCK	Dented	286.00 FL	*286.00 FL
5	1		*TAILGATE LOCK CATCH	Distorted	98.00 FL	*98.00 FL
6	1		*TAILGATE WEATHERSTRIP (\$268.00) (50%)	Dented / Cut	357.00 FS	*134.00 FS
7	1		*TAILGATE WEATHERSTRIP TOP PLATE	Dented	390.00 FL	*198.00 FL
8	1		*TAILGATE TRIM BOARD	Buckled / Cracked	536.00 FL	*536.00 FL
9	1		*TAILGATE TRIM BOARD CLIPS	Necessary	81.90 FS	*60.00 FS
10	1		*TAILGATE CENTRAL LOCKING DEVICE	Serviceable	393.00 FL	*- FL
11	1		*TAILGATE GLASS	Serviceable	1,565.40 FL	*- FL
12	1		*REAR BUMPER	Bent	192.00 FL	*192.00 FL
13	10		*REAR BUMPER CLIPS	Necessary	57.80 FL	*57.80 FL
14	1		*REAR BUMPER BRACKETS	O/S Distorted	154.40 FL	*38.60 FL
15	1		*REAR BUMPER CORNER RETAINERS	O/S Cracked	156.00 FL	*78.00 FL
16	1		*END PANEL	Bent	522.00 FL	*466.82 FL
17	1		*END PANEL INNER PANEL	Serviceable	1,095.00 FL	*- FL
18	2		*TAILLAMPS	Serviceable	792.00 FL	*- FL
19	2		*TAILLAMP GASKETS	Serviceable	50.00 FL	*- FL
20	1		*BONNET	Bent	899.00 FL	*856.62 FL
21	1		*BONNET EMBLEM	Necessary	81.00 FL	*81.00 FL
22	1		*GRILLE	Dented / Cracked	642.00 FL	*496.80 FL
23	1		*FRONT BUMPER	Buckled	570.00 FL	*510.20 FL
24	10		*FRONT BUMPER CLIPS	Necessary	57.80 FL	*57.80 FL
25	1		*FRONT BUMPER BRACKET LH	Repair	81.00 FL	*- FL
26	1		*FRONT BUMPER REINFORCEMENT	Bent	379.00 FL	*304.42 FL
27	1		*FRONT BUMPER CENTER AIR GRILLE LH	Serviceable	204.00 FL	*- FL
28	1		*FRONT BUMPER SIDE AIR GRILLE LH	Serviceable	99.00 FL	*- FL
29	1		*FRONT BUMPER TOW COVER	Serviceable	24.00 FL	*- FL
30	1		*FRONT BUMPER LOWER BEAM	Bent	372.00 FL	*145.50 FL
31	2		*HEADLAMPS	Mtg Cracked	1,772.00 FL	*1,488.00 FL
32	1		*WIPER TANK	Dented	152.00 FL	*152.00 FL
33	1		*AIR CON CONDENSER	Serviceable	1,635.00 FL	*- FL
34	1		*RADIATOR	Serviceable	2,465.00 FL	*- FL
35	1		*TAILGATE GLASS SEALANT	Necessary	50.00 FS	*40.00 FS
36	1		*TAILGATE OUTER FASTENER	Necessary	50.00 FS	*30.00 FS
37	1		*TAILGATE STICKER 70KM	Necessary	18.00 FS	*12.00 FS
38	1		*TAILGATE STICKER 10PAX	Necessary	18.00 FS	*12.00 FS
39	1		*TAILGATE STICKER	Necessary	120.00 FS	*60.00 FS
40	1		*TAILGATE TRIM BOARD STICKER	Necessary	120.00 FS	*50.00 FS
41	1		*REAR BUMPER REVERSE SENSOR	Dented	280.00 FS	*200.00 FS
42	1		*REAR FLOOR PANEL TOP WOODEN BOARD	Cracked	180.00 FS	*120.00 FS
43	1		*REAR NUMBER PLATE	Dented	45.00 FS	*20.00 FS
44	1		*FRONT NUMBER PLATE	Dented	45.00 FS	*20.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	19,477.30	8,973.66
- List Item Discount on L Items 25.00/25.00% (\$)	4,528.10	2,053.92
Total Parts (\$)	14,949.20	6,919.74

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CONDUCT ELECTRICAL CHECK ,FOCUS HEADLAMP	New	30.00	30.00
2	TO REMOVE/REFILL AIR CON CONDENSER GAS	New	120.00	0.00
3	TO REMOVE /REFIT ,RADIATOR SYSTEM ,BLEED ,REFILL COOLANT	New	60.00	0.00
4	TO DISMANTLE /REFIT TAILGATE FITTINGS /ANCILLARY ACCESSORIES	New	150.00	60.00
5	TO DISMANTLE /REPLACE TAILGATE GLASS	New	160.00	120.00
6	TO CONDUCT REAR ELECTRICAL CHECK ,REPLACE REVERSE SENSORS MODULES REWIRING ETC	New	120.00	50.00
7	TO SUPPLY REAR PANEL BODY SEALANT	New	80.00	30.00
8	TO APPLY RUST PROOFING /RESEAL TUFF COATING TREATMENT TO RESPRAY /REPLACED /REPAIR PANEL	New	150.00	90.00
9	TO DISMANTLE /REPAIR EXHAUST SILENCER	New	80.00	0.00
10	LABOUR CHARGE -PANEL BEATING, REPAIRING OF SUPPORT PANEL,HEADLAMP PANEL ,REAR CABIN FLOOR PANEL ,INNER PANEL ETC ,CUT ,WELD REAR END PANEL ,INNER PANEL AND PARTS REPLACEMENT	New	1,650.00	1,000.00
11	TO RESPRAY AFFECTED AREAS	New	1,200.00	900.00
Gross Labour Cost (\$\$)			3,800.00	2,280.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >