

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	08 Jun 2020 Edit Reg		08 Jun 2020 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured: SECK MUN CHOONG SAMUEL , ID: S1791407C									
Main Claimant: -									
Vehicle Reg. No.: SGS4004E		Date of Loss: 05/06/2020 00:00 - :59 [158 Months and 22 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / 4910615553SG		Policy/Cover Note No.: 1800066816 (Comprehensive) Coverage: 16/06/2019 - 15/06/2020							
Vehicle Reg. No. (Insured): SGP240G		Policy No. (Claimant):							
		Excess:							
Repairer: Harmony Motor Pte Ltd (HQ) BLK 10 ANG MO KIO IND. PARK 2A #02-12 AMK AUTOPOINT, 568047 Ang Mo Kio - Tel: 6482 2444									
Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by MdNoor, Norsiah]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 17/06/2020]									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SGS4004E (4910615553SG)**
[SGP240G]
TP
-

Jun 5 2020 12:00AM
[SECK MUN CHOONG SAMUEL]
Harmony Motor Pte Ltd

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)
[Upload Video](#)
[Upload Audio](#)

View [View in Browser](#) ☐

Video 1 per page ☐

No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	09/06/20 12:04	Video - Accident	 Load MP4	☐

Photos/Images 3 per page ☐

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	09/06/20 09:54	General View	 Load JPG	☒
2	09/06/20 09:54	General View	 Load JPG	☒
3	09/06/20 09:54	General View	 Load JPG	☒
4	09/06/20 09:54	General View	 Load JPG	☒
5	09/06/20 09:54	General View	 Load JPG	☒
6	09/06/20 09:54	General View	 Load JPG	☒
7	09/06/20 09:54	General View	 Load JPG	☒
8	09/06/20 09:54	General View	 Load JPG	☒
9	09/06/20 09:54	General View	 Load JPG	☒
10	09/06/20 09:54	General View	 Load JPG	☒
11	09/06/20 09:54	General View	 Load JPG	☒
12	09/06/20 09:54	General View	 Load JPG	☒
13	09/06/20 09:54	General View	 Load JPG	☒
14	09/06/20 09:54	General View	 Load JPG	☒
15	09/06/20 09:54	General View	 Load JPG	☒
16	09/06/20 09:54	General View	 Load JPG	☒
17	09/06/20 09:54	General View	 Load JPG	☒
18	09/06/20 09:54	General View	 Load JPG	☒
19	09/06/20 09:54	General View	 Load JPG	☒
20	09/06/20 09:54	General View	 Load JPG	☒
21	09/06/20 09:54	General View	 Load JPG	☒
22	09/06/20 09:54	General View	 Load JPG	☒
23	09/06/20 09:54	General View	 Load JPG	☒
24	09/06/20 09:54	General View	 Load JPG	☒
25	09/06/20 09:54	General View	 Load JPG	☒
26	09/06/20 09:54	General View	 Load JPG	☒
27	09/06/20 09:54	General View	 Load JPG	☒
28	09/06/20 09:54	General View	 Load JPG	☒
29	09/06/20 09:54	General View	 Load JPG	☒
30	09/06/20 09:54	General View	 Load JPG	☒
31	09/06/20 09:54	General View	 Load JPG	☒
32	09/06/20 09:54	General View	 Load JPG	☒
33	09/06/20 09:54	General View	 Load JPG	☒
34	09/06/20 09:54	General View	 Load JPG	☒
35	09/06/20 09:54	General View	 Load JPG	☒
36	09/06/20 09:54	General View	 Load JPG	☒
37	09/06/20 09:54	General View	 Load JPG	☒

Video				1 per page	☒
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail	Print
38	09/06/20 09:55	Odometer Reading		Load JPG	☒
39	09/06/20 09:55	Chassis Number		Load JPG	☒
Documentation					
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail	Print
1	09/06/20 12:04	OI GIA REPORT		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

Reset

Save

Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To:

☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS3/AIG20006194/GYF3S2**Date:** 24/06/2020REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800066816
Claimant Vehicle No :	SGS4004E	Insured Vehicle No :	SGP240G
Date of Loss:	05/06/2020	Nature of Claim:	TP
		Claim No:	4910615553SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SGS4004E	Engine No:	G4EE6H078842
Make & Model:	KIA RIO, 1.4 (A)	Chassis No:	KNADE221376215104
Reg. Date:	14/03/2007 (Man. Year: 2006)	Odometer:	160953 km
Colour:	Black		
Engine Capacity:	1399 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	175/70 R14	Rear Tyre Size:	175/70 R14
Front Left Side:	Yokohama 5 mm	Rear Left Side:	Yokohama 5 mm
Front Right Side:	Yokohama 5 mm	Rear Right Side:	Yokohama 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (\$\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	08/06/2020	
Date Inspected:	08/06/2020 Inspected At:	Harmony Motor Pte Ltd (HQ) BLK 10 ANG MO KIO IND. PARK 2A #02-12 AMK AUTOPOINT Singapore 568047
Estimated Period of Repair:	6.0 days	

Adjuster: XING GUO QIANG**Manager:** YVONNE WONG YIN CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR NUMBER PLATE	Bent	0.00 F	*- F
2	1		*REAR NUMBER PLATE BASE	Deformed	0.00 F	*- F
3	1		*REAR NUMBER PLATE LAMP	Cracked	0.00 F	*- F
4	1		*REAR BUMPER	Deformed	0.00 F	*- F
5	1		*REAR BUMPER CLIPS	Necessary	0.00 F	*- F
6	2		*REAR BUMPER SIDE RETAINER	Deformed	0.00 F	*- F
7	1		*REAR BUMPER PROTECTOR	Deformed	0.00 F	*- F
8	1		*REVERSE SENSOR	Damaged	0.00 F	*- F
9	1		*REAR END PANEL	Bent	0.00 F	*- F
10	1		*REAR END PANEL TOP GARNISH	Deformed	0.00 F	*- F
11	1		*REAR LH TAILLAMP	Cracked	0.00 F	*- F
12	1		*REAR RH TAILLAMP	Cracked	0.00 F	*- F
13	2		*REAR APRON PANEL	Deformed	0.00 F	*- F
14	1		*BOOTLID	Buckled	0.00 F	*- F
15	3		*BOOTLID EMBLEM	Necessary	0.00 F	*- F
16	1		*BOOTLID LOCK	Bent	0.00 F	*- F
17	1		*BOOTLID RUBBER	Twisted	0.00 F	*- F
18	2		*BOOTLID HINGE	Bent	0.00 F	*- F
19	1		*SPARE TYRE PANEL	Repair	0.00 F	*- F
20	1		*REAR EXHAUST PIPE	Repair	0.00 F	*- F
21	1		*REAR LH FENDER	Repair	0.00 F	*- F
22	1		*REAR RH FENDER	Repair	0.00 F	*- F

F=Franchise part.

Total Parts (\$\$)
0.00
0.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >