

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG20006195/KKA3Q2**Date:** 03/12/2020REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 0999993880
Claimant
Vehicle No : SLQ4335B **Insured Vehicle No :** GBF4508X
Date of Loss: 13/01/2020 Nature of Claim: TP Claim No: 6823282483SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLQ4335B**
Make & Model: TOYOTA VIOS, 1.5 E (A) Engine No: 2NRX163430
Reg. Date: 11/07/2017 (Man. Year: 2017) Chassis No: MHFB29F3702012681
Colour: Metallic Silver Odometer: 107377 km
Engine Capacity: 1496 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/50 R16 Rear Tyre Size: 195/50 R16
Front Left Side: Yokohama 4 mm Rear Left Side: Yokohama 5 mm
Front Right Side: Yokohama 4 mm Rear Right Side: Yokohama 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,822.37	1,137.38	2,684.99	70.24
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,740.00	1,275.00	1,465.00	53.47
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,562.37	2,412.38	4,149.99	63.24
Approved Total (Overridden) (S\$)		1,950.00		
(S\$)	6,562.37	1,950.00	4,612.37	70.29
+ GST 7.00/7.00% (S\$)	459.37	136.50	322.87	70.29
Nett Amount (S\$)	7,021.74	2,086.50	4,935.24	70.29
+ Loss of Use (4.0 x S\$60.00/day) (S\$)		240.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		2,333.95		
Global Sum Settlement (S\$)		2,330.00		

INSPECTION

Date of Assignment: 12/06/2020
Date Inspected: 15/06/2020 Inspected At: Esteem Performance Pte Ltd (HQ)
Blk 5033 Ang Mo Kio Ind Park 2, #01-259
Singapore 569536
Estimated Period of Repair: 4.0 days

Adjuster: KENNETH KONG

Manager: Khanchna Pothuraj

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REVERSE SENSOR	Serviceable	200.00 FS	*- FS
2	1		*REAR NUMBER PLATE	Serviceable	45.00 FS	*- FS
3	1		*REAR BUMPER	Buckled	497.10 FL	*497.10 FL
4	10		*REAR BUMPER CLIP	Necessary	42.10 FL	*42.10 FL
5	1		*REAR BUMPER SIDE RETAINER LH	Serviceable	113.90 FL	*- FL
6	1		*REAR BUMPER SIDE RETAINER RH	Serviceable	113.90 FL	*- FL
7	1		*REAR BUMPER BRACKET LH	Repair	127.75 FL	*- FL
8	1		*REAR BUMPER BRACKET RH	Repair	127.75 FL	*- FL
9	1		*REAR BUMPER SPONGE (NPA)	Serviceable	0.00 FL	*- FL
10	1		*REAR BUMPER REINFORCEMENT	Repair	335.80 FL	*- FL
11	1		*REAR BUMPER REFLECTOR LH	Serviceable	242.67 FL	*- FL
12	1		*REAR BUMPER REFLECTOR RH	Serviceable	242.67 FL	*- FL
13	1		*BOOTLID	Bent	820.61 FL	*820.61 FL
14	1		*BOOTLID LOCK	Dented	108.80 FL	*108.80 FL
15	1		*BOOTLID HINGE LH	Repair	87.40 FL	*- FL
16	1		*BOOTLID HINGE RH	Repair	87.40 FL	*- FL
17	1		*WORDING VIOS	Necessary	47.90 FL	*47.90 FL
18	1		*TAIL END PANEL	Repair	721.80 FL	*- FL
19	1		*TAIL END PANEL GARNISH	Serviceable	229.40 FL	*- FL
20	1		*BOOT WEATHERSTRIP	Serviceable	195.10 FL	*- FL
21	1		*TAIL LAMP LH	Serviceable	313.89 FL	*- FL
22	1		*TAIL LAMP RH	Serviceable	313.89 FL	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	5,014.83	1,516.51
- List Item Discount on L Items 25.00/25.00% (\$\$)	1,192.46	379.13
Total Parts (\$\$)	3,822.37	1,137.38

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA (REAR BUMPER ,BOOTLID ,END PANEL,SPARE TYRE COMPARTMENT)	New	1,000.00	500.00
2	TO PUTTY ,RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA (REAR BUMPER ,BOOTLID ,END PANEL,SPARE TYRE COMPARTMENT)	New	1,000.00	600.00
3	TO CHECK WIRING	New	50.00	15.00
4	TO REMOVE & REFIT SPARE TYRE ,SPARE TYRE BOARD ,CARPET TRIM TO ASSIST WORK LOAD	New	150.00	60.00
5	TO TUFF COAT	New	150.00	0.00
6	TO TRANSFER BOOT MECHANISM TO NEW BOOT	New	150.00	50.00
7	TO CONDUCT WATER LEAKAGE TESTS TO ENSURE PROPER AIR AND SEALING	New	120.00	0.00
8	TO REMOVE & REFIT REVERSE SENSOR	New	120.00	50.00
Gross Labour Cost (S\$)			2,740.00	1,275.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >