



(e) Signature of surveyor

ESTEEM PERFORMANCE PTE LTD

385 Sur Ming Drice (Auside Victori) Surgations (4/571).

Real Total H. Berry B. W. J. J.	Fax: 6451-0394 0005455N - Q51 Reg (sc.	: 20-0005481 A	Rearing Bapaing lump sum USing 819501
Repair Estimates	SLQ 4335 B		Rearing Byon
Annals as the control of the control	Finalited		1 State
Parts (a) Cost / List Price Items	\$ (516-5) 4,7	769.83	lump sum
Plus/Less 25%	\$ 379-13 1,1	192.46	USuny 81850
Total of Cost / List	\$ [137-38 3,5	577.37	1 5.120%
(b) Nett Price Items			LKK Auto Consultants hence notify
Less			To resurvey before/after spray painting To display damaged pages a first spray painting
Total of Nett Item	Secretario de la constanti de		Third party survey is on a "Without So."
(c) Special Nett Items	\$ 2	245.00	No illegal modification(s) is allowed Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company
Total Parts Cost	\$ 3,8	222.37	Acknowledged by Repairer Signature;
Labour	\$ 1275-00 2,7	40.00	Dete:
Total	\$)412.37 6,5	62.37 - 20	
The above total will be subjected to	7% G.S.T.	= \$193000	
Name of Curvayar		Kenneth	described on the following consistence of the construction of the first of the construction of the constru
Name of Surveyor		LICK	
Company Survey conducted on		15/6/20	at 1():00am
The state of the s	***************************************		The second secon
Remarks By Surveyor			
(a) The repair of this vehicle is	authorized / is not author	orized until further notice.	
(b) Recommended Days of Rep	pair :	4- 1 de	ay(s)
(c) Resurvey	: Required /	Not Required	
(d) Excess	:\$		

Date: _____15/6/26



ESTEEM PERFORMANCE PTE LTD

by applying the collection for all three distributions and a market adjusts

Tel: 6484 1221 Fax 6484 782

455 Sin Librar Drive Barnie Stram) Sugarate a/573

Tel: 6753 2112 Fax: 6452 0394

Co. Reg No. 200005485N GSI Reg No. : 20-0065485-K

Spare Parts

Vehicle No. :

Make & Model : Chassis No : SLQ 4335 B

TOYOTA VIOS

MHFB29F3702012681

Submit By

Year Manufacture :

Engine No.

Cost / List

JENNY 2017

S/No.	Part Description		Qty	Unit Price	Price	Disposition by Surveyor
1	Reverse sensor	Sa	. 1	\$200.00	S.N	X
2	Rear number plate	Sep	1	\$45.00	S,N	X
3	Rear bumper	13/	. 1	\$497.10		· ·
4	Rear bumper clip	ne	10	\$42.10		X
5	Rear bumper side retainer LH	Si	1	\$113.90		X
6	Rear bumper side retainer RH	1	- 1	\$113.90		X
7	Rear bumper bracket LH	R	1	\$127.75		3
8	Rear bumper bracket RH	n	1	\$127.75		X
9	Rear bumper sponge	J.	_1_	N/A		
10	Rear bumper reinforcement	n	1	\$335.80		1
11	Rear bumper reflector LH	Su.	1	\$242.67		×
12	Rear bumper reflector RH	Su.	1	\$242.67		X
13	Bootlid	4	1	\$820.61		Commen
14	Bootlid lock	ne	1	\$108.80		2
15	Bootlid hinge LH	18	1	\$87.40		× ×
16	Bootlid hinge RH	R	1	\$87.40		^
17	Wording "VIOS"	14	4 1	\$47.90		
18	Tail end panel	R.	1	\$721.80		7
19	Tail end panel garnish	In	1	\$229.40		7
20	Boot weatherstrip	Jen .	1	\$195.10		X
21	Tail lamp LH	Sen	1	\$313.89		X
22	Tail lamp RH	Su	1	\$313.89		X
23	·					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.



Blk 5033 Ang Mo Kio Industrial Para Z. #01-251/01-251. 5 mgas erro 1695-25

Tel: 6484 1221

Fore: 648: 7820

385 Sin (Ming Drive (Fraude Vurom) Singapore a/S/TE fel: 6753 2112

Fex. 6851 0394

Co. Reg No.: 200005485N

GST Rep No. 1 20-0005485-N

Labour

SLQ 4335 B Carmen Lim Submit By Vehicle No. 2017 TOYOTA VIOS Year of Manufacture: Make & Model :

	& Widdel : TOTOTA VIOS Teal of Walldracture	•	2011
S/No	Labour Description	Esimated Price	Adjusted Price
1	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT		
	REPAIR AREA. (REAR BUMPER,BOOTLID,END PANEL,	\$1,000.00	500 7 6
	SPARE TYRE COMPARTMENT)	and the second s	
	TO PUTTY, RESPRAY PAINT FOR AFFECTED ACCIDENT		- 1
	REPAIR AREA. (REAR BUMPER,BOOTLID,END PANEL,	\$1,000.00	6001
	SPARE TYRE COMPARTMENT)		
3	To check wiring	\$50.00	15%
4	To remove & refit spare tyre, spare tyre board, carpet trim	\$150.00	601
to a	to assist work load.		
5	To tuff coat.	\$150.00	XX
6	To transfer boot mechanism to new boot	\$150.00	501
7	To conduct water leakage tests to ensure proper air and sealing	\$120.00	X X
8	To remove & refit reverse sensor	\$120.00	506

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.