

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20006231/T1KA3Q2

Date: 10/11/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1700090785

Claimant
Vehicle No : SLJ2595S **Insured Vehicle No :** SLV1019H

Date of Loss: 03/06/2020 Nature of Claim: TP Claim No: 0589665270SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLJ2595S	Engine No:	CAX726386
Make & Model:	AUDI A1, 1.4 (A)	Chassis No:	WAUZZZ8X0BB063218
Reg. Date:	14/04/2011 (Man. Year: 2011)	Odometer:	50322 km
Colour:	Red		
Engine Capacity:	1390 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/45R17	Rear Tyre Size:	215/45R17
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,989.60	3,751.74	1,237.86	24.81
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,280.00	1,210.00	1,070.00	46.93
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	7,269.60	4,961.74	2,307.86	31.75
Approved Total (Overridden) (\$\$)		4,000.00		
Nett Amount (\$\$)	7,269.60	4,000.00	3,269.60	44.98
Global Sum Settlement (\$\$)		0.00		

INSPECTION

Date of Assignment: 05/06/2020

Date Inspected: 05/06/2020 Inspected At: Advant Auto (HQ)
50 Bukit Batok Street 23
Singapore 659578

Estimated Period of Repair: 5.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: Khanchna Pothuraj

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	1,300.00 FL	*1,125.60 FL
2	1		*FRONT BUMPER SIDE RETAINER	O/s Cracked/N/s Not Necessary	76.00 FL	*38.00 FL
3	1		*RH HEADLAMP	Cut	950.00 FL	*950.00 FL
4	1		*FRONT RH FENDER	Repair	490.00 FL	*- FL
5	1		*FRONT RH FENDER INNER SHIELD	Deformed	225.00 FL	*225.00 FL
6	1		*FRONT RH RIM	Dented	1,500.00 FL	*1,000.00 FL
7	1		*FRONT RH SHOCK ABSORBER	Bent	210.00 FL	*210.00 FL
8	1		*FRONT RH KNUCKLE ARM	Bent	390.00 FL	*390.00 FL
9	1		*FRONT RH LOWER ARM	Bent	230.00 FL	*230.00 FL
10	1		*ANTI-ROLL BAR	Not Necessary	105.00 FL	*- FL
11	1		*RH ANTI-ROLL BAR LINK	Not Necessary	68.00 FL	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	5,544.00	4,168.60
- List Item Discount on L Items 10.00/10.00% (\$\$)	554.40	416.86

Total Parts (\$\$)	4,989.60	3,751.74
---------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TOWING	New	100.00	0.00
2	TO CHECK WIRING SYSTEM	New	80.00	30.00
3	TO RESET AND PROGRAM AFTER REPAIR	New	350.00	150.00
4	TO R&R FRONT RH UNDERCARRIAGE	New	250.00	120.00
5	TO CONDUCT WHEEL ALIGNMENT	New	120.00	80.00
6	TO R&R FRONT BUMPER,RH HEADLAMP,FRONT RH FENDER AND ATTACHMENTS	New	500.00	350.00
7	TO RESPRAY ON FRONT FENDER,FRONT BUMPER,FRONT RH DOOR AND ACCIDENT AFFECTED AREA	New	800.00	450.00
8	RUST PROOFING	New	80.00	30.00
Gross Labour Cost (\$\$)			2,280.00	1,210.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >