Page 1 of 3 Adjuster Report

#### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

#### VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG20006232/EYF3E2

Date: 24/06/2020

REFERENCE

No:

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1900253461 Claimant Vehicle <sub>GZ9317H</sub> Insured Vehicle No: SFL3579T

Date of Loss: 06/06/2020 Nature of Claim: TP Claim No: 8196085008SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

Reg No: GZ9317H

Make & Model: TOYOTA HIACE, 1.8 D SUPER GL DARK PRIME (A) Engine No: 1GD8368101 Reg. Date: 24/07/2019 (Man. Year: 2018) Chassis No: GDH2012004328

Colour: Odometer: 32943 km Silver

**Engine Capacity:** 2754 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): **Engine Modification:** No Pre-accident Condition: Yes

**CONDITION OF TYRES** 

195/80 R15 Front Tyre Size: 195/80 R15 Rear Tyre Size: Front Left Side: Rear Left Side: Bridgestone 5 mm Bridgestone 5 mm Bridgestone 5 mm Rear Right Side: Front Right Side: Bridgestone 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$	0.00	0.00	0.00	

**INSPECTION** 

08/06/2020 Date of Assignment:

Date Inspected: 09/06/2020 Inspected At: Hock Motors Workshop (HQ)

NO 1 KAKI BUKIT AVENUE 6, #02-38

AUTOBAY @ KAKI BUKIT

Singapore 417883

Estimated Period of Repair: 10.0 days

Manager: YVONNE WONG YIN CHENG CHEN TSUE YEE Adjuster:

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 2 of 3

# **REPAIR DETAILS**

# **Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT BUMPER	Broken	0.00 F	*- F
2	2		*FRT BUMPER BRACKET	Broken	0.00 F	*- F
3	1		*FRT BUMPER REINFORCEMENT (LOWER)	Bent	0.00 F	*- F
4	1		*FRT RH BUMPER FOG LAMP COVER	Crushed	0.00 F	*- F
5	1		*FRT RH HEADLAMP ASSY	Broken	0.00 F	*- F
6	1		*BONNET	Dented	0.00 F	*- F
7	1		*AIR FILTER ASSY	Broken	0.00 F	*- F
8	1		*AIR FILTER DUCT	Crushed	0.00 F	*- F
9	1		*FRT RH FENDER	Dented	0.00 F	*- F
10	1		*FRT RH DOOR	Dented	0.00 F	*- F
11	2		*FRT RH DOOR HINGE	Bent	0.00 F	*- F
12	1		*FRT RH DOOR LOCK	Jammed	0.00 F	*- F
13	1		*FRT RH DOOR GLASS REGULATOR	Bent	0.00 F	*- F
14	1		*FRT RH DOOR RUBBER	Torn	0.00 F	*- F
15	1		*FRT RH DOOR INNER TRIM BOARD	Broken	0.00 F	*- F
16	1		*FRT DOOR FRT PILLAR (RH)	Dented	0.00 F	*- F
17	1		*FRT WHEEL ARCH PANEL GARNISH (RH)	Crushed	0.00 F	*- F
18	1		*FRT STEP PANEL (RH)	Dented	0.00 F	*- F
F=Fra	nchise	part.		Total Douts (OA)	0.00	0.00
				Total Parts (S\$)	0.00	0.00

Report was unsubmitted during this print-out.

Adjuster Report Page 3 of 3

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

### Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >