

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI20006233/UQF3E2

Date: 14/07/2020

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSN15298919044	
Claimant Vehicle No :	SLH1632K	Insured Vehicle No :	SJP73L	
Date of Loss:	12/06/2020	Nature of Claim:	TP	Claim No: SNM20D202106/C02/LOWCT

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLH1632K	Engine No:	MRA8354147R
Make & Model:	NISSAN SYLPHY, 1.8 (A)	Chassis No:	MNTBAAB17Z0008629
Reg. Date:	26/10/2016 (Man. Year: 2016)	Odometer:	77074 km
Colour:	Grey		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/60 R16	Rear Tyre Size:	195/60 R16
Front Left Side:	Yokohama 7 mm	Rear Left Side:	Yokohama 7 mm
Front Right Side:	Yokohama 7 mm	Rear Right Side:	Yokohama 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,872.18	2,479.92	6,392.26	72.05
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,658.00	2,858.00	1,800.00	38.64
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	13,530.18	5,337.92	8,192.26	60.55
+ GST 7.00/7.00% (S\$)	947.11	373.65	573.46	60.55
Nett Amount (S\$)	14,477.29	5,711.57	8,765.72	60.55

INSPECTION

Date of Assignment:	15/06/2020		
Date Inspected:	15/06/2020	Inspected At:	Autolution Industrial Pte Ltd (HQ) 19 UBI ROAD 4 Singapore 408623
Estimated Period of Repair:	6.0 days		

Adjuster: MARCUS CHUA

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

(REPAIR COST NOT CONCLUDE)

(EXCLUDE CHECK ITEMS S\$5,518.74 NETT)

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 14 Jul 2020)
Parts:	143	NISSAN SYLPHY 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLH1632K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	* Check	50.00 FS	*- FS
2	1		*FRT RH DRIVE SHAFT	* Check	1,245.90 FS	*- FS
3	1		*FRT RH SPINDLE KNUCKLE	* Check	435.00 FS	*- FS
4	1		*FRT RH WHEEL HUB	* Check	407.70 FS	*- FS
5	1		*FRT RH SHOCK MOUNTING	* Check	104.00 FN	*- FN
6	1		*BRG STRUT MTG	* Check	55.10 FS	*- FS
7	1		*FRT RH SEAT RUBBER LOWER SPRING	* Check	22.80 FN	*- FN
8	1		*FRT RH SHOCK ABSORBER BUMPER BOUND	* Check	40.30 FS	*- FS
9	1		*FRT RH SHOCK ABSORBER	* Check	428.60 FS	*- FS
10	1		*BAR-TORSION FRT	* Check	227.30 FS	*- FS
11	1		*FRT SUSPENSION MEMBER STAY	* Check	95.80 FS	*- FS
12	1		*FRT CROSS MEMBER	* Check	485.90 FN	*- FN
13	1		*ROO-STABILIZER FRT RH	* Check	36.60 FN	*- FN
14	1		*FRT RH LOWER ARM	* Check	229.30 FN	*- FN
15	6		*CLIP FRT RH WHEEL HOUSE PROTECTOR	Necessary	8.40 FN	*8.40 FN
16	1		*CLIP FRT BUMPER	Necessary	1.30 FN	*1.30 FN
17	1		*RH SIDE RETAINER BRACKET FRT BUMPER	Cracked	20.60 FN	*20.60 FN
18	1		*FRT RH FENDER LOWER BRACKET	Bent	24.40 FN	*24.40 FN
19	1		*INSULATOR FRT RH FENDER	* Check	42.00 FN	*- FN
20	1		*FRT RH FENDER LOWER DEFLECTOR MUDGUARD	Torn	115.60 FN	*115.60 FN
21	1		*FRT RH FENDER WHEELHOUSE PROTECTOR	Torn	102.10 FN	*102.10 FN
22	1		*FRT RH FENDER	Buckled	752.80 FN	*752.80 FN
23	1		*RH SIDE UPPER RADIATOR SUPPORT	Repair	186.70 FN	*- FN
24	1		*RADIATOR TOP MOULDING BRACKET	* Check	397.90 FN	*- FN
25	1		*RADIATOR GRILLE	* Check	796.80 FN	*- FN
26	1		*INNER BRACKET APRON FRT BUMPER	Torn	210.70 FN	*210.70 FN
27	1		*LOWER GRILLE FRT BUMPER	Not Necessary	302.50 FN	*- FN
28	1		*FOGLAMP GARNISH	Torn	87.70 FN	*87.70 FN
29	1		*RH FOGLAMP	* Check	600.80 FS	*- FS
30	1		*RH HEADLAMP	Broken	815.00 FN	*815.00 FN
31	1		*LH HEADLAMP	Not Necessary	815.00 FN	*- FN
32	1		*FRONT BUMPER	Distorted	561.30 FN	*561.30 FN
33	1		*FRONT BUMPER SKIRTING	Distorted	320.00 FS	*320.00 FS
34	1		*WASHER TANK (NPA)	Deformed	0.00 FN	*- FN
35	1		*WASHER TANK COVER (NPA)	Missing	0.00 FN	*- FN
36	1		*LH FOGLAMP GARNISH	Not Necessary	87.70 FN	*- FN

F=Franchise part. S=SpcNett. N=NettItemDisc.

Sub Total (\$\$) **10,113.60** **3,019.90**
- Nett Item Discount on N Items 20.00/20.00% (\$\$) 1,241.42 539.98

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
				Total Parts (S\$)	8,872.18	2,479.92

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	LABOR CHARGES TO REPAIR RH SIDE RADIATOR SUPPORT FRT RH DOOR, RENEW FRT RH FENDER, FRONT BUMPER AND FRONT BUMPER SKIRTING	New	2,340.00	1,170.00
2	CHARGES TO SPRAY PAINTING SAME	New	1,600.00	1,250.00
3	RENEW RH HEADLAMP AND FOCUS	New	48.00	48.00
4	REMOVE AND INSTALL RH SIDE SKIRT TO FACILITATE FRT RH FENDER REPLACEMENT	New	120.00	80.00
5	REMOVE AND INSTALL FRT RH UNDERCARRIAGE REPLACE PARTS IF NECESSARY (* Check)	New	240.00	0.00
6	RENEW FRT RH WHEEL RIM, TYRE AND BALANCING	New	15.00	15.00
7	PERFORM WHEEL ALIGNMENT	New	95.00	95.00
8	CHECK BRAKE SYSTEM (UNUSUAL SOUND WHEN PRESSING THE BRAKE PEDAL)	New	120.00	120.00
9	TOWING FEE. TOWING WORK ORDER NO.T176744	New	80.00	80.00
Gross Labour Cost (\$\$)			4,658.00	2,858.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >