

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG20006236/GVF3E2

Date: 22/06/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1700039939
Claimant Vehicle No : SLX3799R	Insured Vehicle No :	SJS2292S
Date of Loss: 04/04/2020	Nature of Claim: TP	Claim No: 8469312522SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLX3799R	Engine No:	4B11BQ1358
Make & Model:	MITSUBISHI LANCER, 2.0 (A)	Chassis No:	JMFSNCZ4A9U000237
Reg. Date:	29/05/2009 (Man. Year: 2008)	Odometer:	216180 km
Colour:	Blue	Engine Capacity:	1998 cc
Market Value/New Car Price:	N/A	Sum Insured (S\$):	Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	245/40 R18	Rear Tyre Size:	245/40 R18
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	08/06/2020
Date Inspected:	09/06/2020 Inspected At:
	160 Sin Ming Drive #02-09 Sin Ming Autocity Repairer : 833 Motorsports (HQ)
Estimated Period of Repair:	3.0 days

Adjuster: XING GUO QIANG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*REAR BUMPER	Deformed	0.00 F	*- F	
2	1		*REAR BUMPER LOWER	Deformed	0.00 F	*- F	
3	1		*REAR BUMPER TOW COVER	Cut	0.00 F	*- F	
4	1		*REAR BUMPER SIDE RETAINER	Deformed	0.00 F	*- F	
5	1		*REAR END PANEL	Repair	0.00 F	*- F	
					Total Parts (\$)	0.00	0.00

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >