

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20006238/QDS3Q2

Date: 27/08/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1900242658

Claimant
Vehicle No : SJJ3207E **Insured Vehicle No :** SLD6702E

Date of Loss: 09/06/2020 Nature of Claim: TP Claim No: 6274306627SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJJ3207E		
Make & Model:	TOYOTA VIOS, 1.5 E (A)	Engine No:	1NZX793295
Reg. Date:	09/09/2008 (Man. Year: 2008)	Chassis No:	MR053HY9305077896
Colour:	Green	Odometer:	250149 km
Engine Capacity:	1497 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/60R15	Rear Tyre Size:	185/60R15
Front Left Side:	Goodyear 6 mm	Rear Left Side:	Goodyear 6 mm
Front Right Side:	Goodyear 6 mm	Rear Right Side:	Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,844.00	2,397.75	446.25	15.69
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,010.00	1,690.00	320.00	15.92
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,854.00	4,087.75	766.25	15.79
Approved Total (Overridden) (S\$)		3,250.00		
Nett Amount (S\$)	4,854.00	3,250.00	1,604.00	33.04
+ Car Rental (4.0 x S\$55.00/day) (S\$)		220.00		
Nett Liability (S\$)		3,470.00		

INSPECTION

Date of Assignment: 12/06/2020

Date Inspected: 12/06/2020 Inspected At:

Mohamed Automobile (HQ)
38 WOODLANDS INDUSTRIAL PARK
E1 #01-16
Singapore 757700

Estimated Period of Repair: 4.0 days

Adjuster: OI SUN PIN

Manager: CHAN JIA LE

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Crumpled	680.00 FL	*680.00 FL
2	2		*REAR BUMPER SIDE RETAINERS	Broken	68.00 FL	*68.00 FL
3	1		*REAR BUMPER CLIPS	Necessary	6.00 FL	*6.00 FL
4	2		*REAR BUMPER REFLECTORS	Serviceable	85.00 FL	*- FL
5	1		*REAR PANEL	Dented	280.00 FL	*280.00 FL
6	1		*REAR PANEL GARNISH	Crumpled	120.00 FL	*120.00 FL
7	1		*REAR PANEL CLIPS	Necessary	15.00 FL	*15.00 FL
8	2		*TAIL LAMP	Cracked	560.00 FL	*560.00 FL
9	2		*CLIPS	Necessary	15.00 FL	*15.00 FL
10	1		*REAR BOOT	Dented	580.00 FL	*580.00 FL
11	1		*REAR BOOT RUBBER	Cut	130.00 FL	*130.00 FL
12	1		*REAR BOOT LOCK	Jammed	160.00 FL	*160.00 FL
13	1		*REAR BOOT LATCH	Serviceable	85.00 FL	*- FL
14	1		*REAR BOOT LOGO	Necessary	58.00 FL	*58.00 FL
15	2		*REAR BOOT HINGES	Bent	120.00 FL	*120.00 FL
16	1		*SPARE TYRE SPONGE (RH)	Serviceable	60.00 FL	*- FL
17	1		*SPARE TYRE SPONGE (LH)	Serviceable	60.00 FL	*- FL
18	1		*PANEL SEALANT	Necessary	100.00 FL	*40.00 FL
19	2		*REVERSE SENSOR	Shorted	300.00 FL	*200.00 FL
20	1		*REAR SKIRTING	Cracked	165.00 FL	*165.00 FL
21	1		*SPOILER	Serviceable	145.00 FL	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	3,792.00	3,197.00
- List Item Discount on L Items 25.00/25.00% (\$\$)	948.00	799.25
Total Parts (\$\$)	2,844.00	2,397.75

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	LABOUR CHARGE PANEL BEATING	New	890.00	800.00
2	SPRAY PAINTING	New	900.00	800.00
3	RUST PROOFING	New	120.00	50.00
4	TRANSFER REAR BOOT ATTACHMENTS	New	100.00	40.00
Gross Labour Cost (\$\$)			2,010.00	1,690.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >