

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG20006240/ACF3E2

Date: 10/03/2021

REFERENCE

Insured/Claimant:	SAYAKA OKANO DAYAL	Policy No:	2070058594		
Date of Loss:	11/05/2020	Nature of Claim:	OD	Claim No:	6902199800SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMT1725B	Engine No:	CZD892043
Make & Model:	AUDI Q3, 1.4 TFSI (A)	Chassis No:	WAUZZZF35L1081981
Reg. Date:	30/03/2020 (Man. Year: 2020)	Odometer:	1097 km
Colour:	Blue		
Engine Capacity:	1395 cc		
Market Value/New Car Price:	S\$143,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/65 R17	Rear Tyre Size:	215/65 R17
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,135.00	6,837.04	3,297.96	32.54
Miscellaneous Items	0.00	0.00	0.00	
Labour	19,912.00	11,077.00	8,835.00	44.37
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	30,047.00	17,914.04	12,132.96	40.38
- Excess (S\$)	800.00	800.00	0.00	0.00
(S\$)	29,247.00	17,114.04	12,132.96	41.48
+ GST 7.00/7.00% (S\$)	2,047.29	1,197.98	849.31	41.48
Nett Amount (S\$)	31,294.29	18,312.02	12,982.27	41.48

INSPECTION

Date of Assignment:	10/06/2020		
Date Inspected:	09/06/2020	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	15.0 days		

Adjuster: ADRIAN LING

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR SIDE PANEL - RH	Dented	3,052.00 FS	*2,441.60 FS
2	1		*SIDE WINDOW - RH	Necessary	577.00 FS	*461.60 FS
3	1		*REAR DOOR - RH	Dented	2,512.00 FS	*2,009.60 FS
4	1		*REAR DOOR OUTER SEAL - RH	Necessary	127.00 FS	*101.60 FS
5	1		*REAR DOOR ATTACHMENT PARTS	Not Necessary	293.00 FS	*- FS
6	1		*REAR DOOR CATCH	Not Necessary	113.00 FS	*- FS
7	1		*REAR DOOR COVER - RH REAR	Cut	242.00 FS	*193.20 FS
8	1		*EXTERIOR DOOR HANDLE - RH	Repair	190.00 FS	*- FS
9	1		*DOOR HANDLE HOUSING - RH	Repair	26.00 FS	*- FS
10	1		*REAR MOUNTING BAR	Not Necessary	154.00 FS	*- FS
11	1		*BOWDEN CABLE	Not Necessary	50.00 FS	*- FS
12	2		*REAR WHEEL COVER - LH / RH	Necessary	506.00 FS	*404.80 FS
13	1		*REAR ALUMINIUM RIM - RH	Not Necessary	720.00 FS	*- FS
14	1		*ACRYLIC SEALANT	Necessary	180.00 FS	*180.00 FS
15	1		*CAVITY WAX	Necessary	140.00 FS	*140.00 FS
16	1		*STONE CHIP	Necessary	180.00 FS	*180.00 FS
17	1		*METAL FILLER POWDER	Necessary	280.00 FS	*280.00 FS
18	1		*1/4 GLASS SEALANT	Necessary	100.00 FS	*100.00 FS
19	1		*SUNDRIES	Necessary	400.00 FS	*110.24 FS
20	1		*REAR END PANELLING OUTER	Necessary	293.00 FS	*234.40 FS

F=Franchise part. S=SpcNett.

Total Parts (S\$)	10,135.00	6,837.04
-------------------	-----------	----------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR. CHECK FUNCTION AND RENEW ACCORDING TO DAMAGE	New	360.00	0.00
2	TO RENEW RHS 1/4 GLASS TO FACILITATE FENDER RENEWAL	New	300.00	300.00
3	TO INSTALL SOLAR FILM FOR 1/4 GLASS	New	400.00	400.00
4	TO DISLODGE AND REINSTALL REAR WIRE HARNESS FOR LIGHTS, BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO EQUIPMENT	New	1,400.00	1,400.00
5	TO REMOVE AND REINSTALL REAR SEAT, BACK REST, HAT TRAY, ABCD PILLAR TRIMS, LUGGAGE COMPARTMENT TRIMS. DISLODGE ROOF LINER AND DISENGAGE CURTAIN AIRBAG ETC	New	1,400.00	1,400.00
6	TO REMOVE AND TRANSFER RHS REAR DOORS MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES	New	280.00	280.00
7	TO DISMANTLE REAR BUMPER AND RHS REAR DOOR. CUT OUT AND WELD RHS REAR FENDER. TO RENEW RHS REAR DOOR. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	6,400.00	3,500.00
8	TO RESPRAY RHS REAR DOOR, DOOR HANDLE, RHS REAR FENDER, RHS SILL PANEL, DOOR ENTRANCES, ROOF CHANNEL, DRAIN PANEL AND END PANELLING. TO CARRY OUT STONE CHIP TREATMENT AND JOINT SEALER WORKS	New	5,700.00	2,575.00
9	TO RENEW RHS REAR RIM AND CARRY OUT WHEEL ALIGNMENT	New	280.00	280.00
10	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
11	TO CUT OUT REAR END PANELLING OUTER	New	3,200.00	750.00
Gross Labour Cost (\$\$)			19,912.00	11,077.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >