

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/III20006243/KBA3Q2

Date: 14/08/2020

REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No:	MCOM0015
Claimant		
Vehicle No : SJR568R	Insured Vehicle No :	SHA7221H
Date of Loss: 05/06/2020	Nature of Claim: TP	Claim No: MCT20060045

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJR568R		
Make & Model:	TOYOTA NOAH HYBRID, 1.8 X CVT (A)	Engine No:	2ZR0E18994
Reg. Date:	13/01/2020 (Man. Year: 2019)	Chassis No:	ZWR800400642
Colour:	Metallic Black	Odometer:	42237 km
Engine Capacity:	1797 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Goodyear 6 mm	Rear Left Side:	Goodyear 6 mm
Front Right Side:	Goodyear 6 mm	Rear Right Side:	Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,553.95	0.00	1,553.95	100.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,700.00	400.00	1,300.00	76.47
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	3,253.95	400.00	2,853.95	87.71
+ GST 7.00/7.00% (\$\$)	227.78	28.00	199.78	87.71
Nett Amount (\$\$)	3,481.73	428.00	3,053.73	87.71
+ Loss of Use (2.0 x S\$80.00/day) (\$\$)		160.00		
+ Doc/Search Fee (\$\$)		7.45		
Nett Liability (\$\$)		595.45		

INSPECTION

Date of Assignment:	09/06/2020	
Date Inspected:	09/06/2020 Inspected At:	Wei Lee Motor Works (HQ) BLOCK 9 SIN MING INDUSTRIAL ESTATE #01-32 Singapore 575644
Estimated Period of Repair:	1.0 days	

Adjuster: KENNETH KONG

Manager: CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 04 Aug 2020)
Parts:	M1-MPV	TOYOTA NOAH HYBRID 1.8 X CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJR568R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Repair	660.90 FL	*- FL
2	1		*REAR BUMPER RETAINER	Serviceable	166.90 FL	*- FL
3	1		*REAR BUMPER REFLECTOR	Serviceable	82.33 FL	*- FL
4	1		*REAR FENDER RH	Repair	1,161.80 FL	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (S\$)	2,071.93	0.00
- List Item Discount on L Items 25.00/25.00% (S\$)	517.98	0.00
Total Parts (S\$)	1,553.95	0.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE/REINSTALL FENDER GLASS	New	150.00	0.00
2	TO REMOVE DAMAGED PARTS N ATTACHMENTS CUT N WELD DAMAGED PANEL REPLACE /ALIGN ALL PARTS INTO POSITION	New	950.00	100.00
3	TO SPRAY PAINT	New	600.00	300.00
Gross Labour Cost (\$\$)			1,700.00	400.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >