

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/FWD20006245/KYF3E2

**Date:** 25/05/2023

### REFERENCE

Handling Insurer: FWD Singapore Pte. Ltd. Policy No: PNMC2019-00003387  
**Claimant Vehicle No :** SKP6647E **Insured Vehicle No :** FBH3184S  
Date of Loss: 23/12/2019 Nature of Claim: TP Claim No: 1201900041810

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKP6647E**  
Make & Model: TOYOTA WISH, 1.8 CVT (A) Engine No: 2ZR1438207  
Reg. Date: 29/09/2014 (Man. Year: 2014) Chassis No: JTDGG20W30J001602  
Colour: Metallic Pearl White Odometer: 199222 km  
Engine Capacity: 1798 cc  
Market Value/New Car Price: N/A  
Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15  
Front Left Side: APLUS 8 mm Rear Left Side: APLUS 8 mm  
Front Right Side: APLUS 8 mm Rear Right Side: APLUS 8 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,221.30	1,215.47	2,005.83	62.27
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,080.00	1,150.00	1,930.00	62.66
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>6,301.30</b>	<b>2,365.47</b>	<b>3,935.83</b>	<b>62.46</b>

### INSPECTION

Date of Assignment: 09/06/2020  
Date Inspected: 09/06/2020 Inspected At: BLK 160 Sin Ming Drive #08-13 Sin Ming Autocity  
Estimated Period of Repair: 4.0 days Repairer: Heng Yap Seng Auto Services (HQ)

**Adjuster:** KENNETH KONG

**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 09 Jul 2021)
<b>Parts:</b>	M1-MPV	TOYOTA WISH 1.8 CVT (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	<b>LKK Auto Consultants Pte Ltd/SKP6647E/25/05/2023 16:58</b>	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Buckled / Dented	698.40 F	*491.90 FL
2	2		*REAR BUMPER BRACKETS	Repair	130.60 F	*- FL
3	1		*REAR BUMPER RETAINERS	O/S Distorted	132.20 F	*66.10 FL
4	2		*REAR BUMPER REFLECTORS	Serviceable	132.20 F	*- FL
5	1		*SET REAR BUMPER CLIPS	Necessary	40.00 F	*40.00 FL
6	1		*REAR FENDER RH (LOCAL REPAIR)	Dented	806.20 FS	*250.00 FS
7	1		*REAR TAILGATE LAMP RH	Cracked	303.10 F	*277.60 FL
8	1		*TAILLAMP RH	Cracked	593.40 F	*411.70 FL
9	1		*TAIL LAMP PANEL RH	Repair	385.20 F	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>3,221.30</b>	<b>1,537.30</b>
<b>- List Item Discount on L Items 0.00/25.00% (\$\$)</b>	0.00	321.83

<b>Total Parts (\$\$)</b>	<b>3,221.30</b>	<b>1,215.47</b>
---------------------------	-----------------	-----------------

**LKK Auto Consultants Pte Ltd/SKP6647E/25/05/2023 16:58.** Not valid without Reference section.

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

# Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	LABOUR CHARGE TO REMOVE, CUT OUT DAMAGE PORTION, JACK OUT, STRAIGHTEN, PANEL BEATING, WELDING, ALIGN AND RENEW REPLACED PARTS	New	1,500.00	480.00
2	TO PUTTY AND RESPRAY PAINTING ON AFFECTED AREAS	New	1,200.00	550.00
3	TO REMOVE, REPLACE REAR FENDER FITTINGS TO FACILITATE REPAIR	New	300.00	100.00
4	TO CHECK WIRING AND LIGHTINGS	New	80.00	20.00
<b>Gross Labour Cost (\$\$)</b>			<b>3,080.00</b>	<b>1,150.00</b>

LKK Auto Consultants Pte Ltd/SKP6647E/25/05/2023 16:58. Not valid without Reference section.

< END OF ESTIMATES >