


ASS. REC. BY: T. C. Lim REF: **CS/CTI20006247/Bvf3**

ASSIGNMENT

From: _____ Date: 9/6/2020
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: SMM 6539B
 at Workshop m/s: Dean Auto pro
 of 160 Sin Ming Dr. #01-14
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

Veh No: SMM 6539B Yr Regn: 8/4/2005
 Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 : Truck / Trailer or _____
 Make: Toyota Corolla Altis cc 1598
 Colour: Silver A/C: Insured / Std / NI / NA
 Sp. Reading: 192838 T/Radio: Insured / Std / NI / NA
 Eng/No: 12RY161093
 C/No: MR053REH104529468
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Mod: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 205/55/16
 R: 205/55/16

(Policy Condition)
 Remark: The veh had commenced its
 repair at the time of inspection.



Bal. or Market Value: 48,000/2
 IDAC Accident Report: _____ Consistent?: Yes or No
 GIA / PR Seen: _____ Consistent?: Yes or No
 Est. Repairs: 8 days Res: Yes or No
 Lum Sum: _____ % 3 Val: Yes or No
 CA / REV / REP. / 24 HRS WP
 Date: _____ Person Contacted: _____ Vehicle: IN / OUT

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or CST
 Front Rear
 R/Bal. 6 mm R/Bal. 6 mm
 L/Bal. 6 mm L/Bal. 6 mm
 D.O.A. 8/6/2020 D.O.I. 9/6/2020
 Survey held at Dean Auto pro
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	Range <u>7,000/2 - 8,000/2</u>
	<u>L/S 7,000/2</u> <u>10/6/2020</u> (Red 7894.45, 53%)
	<u>MV 48,000/2</u>
	<u>PV 40,135/2</u>
	<u>NV 7,815/2</u>

Date/Time, File Pass to? ☐ : Prel. Report
☐ : Final Report
 1) _____
 Date/Time, File Return to?
 2) 17/6/20-Typist
 Rep. Formet: Merimen
 Lump Sum / I.E.S. / LS \$7000

Days Of Repair: 8
 Resurvey No. of Trip: 1
 Add Fee: ☐ : Site Insp (\$) ☐ : Interview (\$) ☐ : Tech. Invs (\$) ☐ : Weekend (\$)
 Survey Fee: _____
 Transportation: _____ \$ + RS _____ \$
 Photos _____
 Others _____
 TOTAL _____

SJE :
Date of Survey :
Date of ReSurvey :
Contacts :
Vehicle Nos : SMM 6539 B
Model : Toyota Altis
Year :
Chassis No :

* AGREED Cost Of Repair and Repair Day/s with SJE *

Amount:

Working Day:

Nos.	PARTS	Qty	Unit S\$	TOTAL S\$	
1	Bootlid	1	\$ 780.50	\$ 780.50	BD ✓
2	Bootlid logo	1	\$ 85.50	\$ 85.00	NECV
3	Bootlid emblem 'corolla'	1	\$ 68.00	\$ 40.00	NECV
4	Bootlid emblem 'Altis'	1	\$ 65.37	\$ 40.00	NECV
5	Bootlid outer chrome garnish	1	\$ 482.60	\$ 380.00	BRV ✓
6	Bootlid reflector	2	\$ 485.30	\$ 970.60	BRV ✓
7	Bootlid inner lock	1	\$ 253.00	\$ 253.00	BT ✓
8	Bootlid striker	1	\$ 65.00	\$ 65.00	NDX
9	Bootlid inner trim board	1	\$ 352.80	\$ 352.80	NSX
10	Bootlid weatherstrip	1	\$ 285.60	\$ 285.60	TNV
11	Reverse camera	1	\$ 425.80	\$ 300.00	CUTV
12	Rear bumper	1	\$ 689.50	\$ 689.50	BRV ✓
13	Rear bumper reinforcement	1	\$ 487.30	\$ 487.30	BT ✓
14	Rear bumper side retainer	2	\$ 102.00	\$ 150.00	NECV
15	Rear bumper bracket	2	\$ 85.60	\$ 171.20	NSX
16	Rear bumper carrier	2	\$ 48.50	\$ 97.00	NSX
17	Rear bumper reflector	2	\$ 157.80	\$ 315.60	NNX
18	Reverse sensor <i>Original</i>	2	\$ 268.00	\$ 300.00	SCV
19	Rear end panel	1	\$ 672.60	\$ 672.60	DDV ✓
20	Rear end panel top garnish	1	\$ 146.00	\$ 146.00	DLV
21	Taillamp	2	\$ 594.60	\$ 1,189.20	BRV ✓
22	Taillamp lower bracket	2	\$ 82.00	\$ 164.00	NECV ✓
23	Rear fender LH	1	\$ 742.30	\$ 742.30	IRX
24	Rear fender inner trim board	2	\$ 289.60	\$ 579.20	NNX
25	Rear windscreen moulding	1	\$ 241.30	\$ 241.30	NECV
26	Exhaust pipe	1	\$ 786.30	\$ 786.30	RX
27	Exhaust mounting	2	\$ 68.60	\$ 137.20	NDX
28	Exhaust heat shield	1	\$ 145.80	\$ 145.80	NDX

Parts Sub Total : \$7,133.47 11,139.27
25% Discount : \$1,783.35 2,784.82
PARTS TOTAL : \$5,350.12 8,354.45

Nos.	SPECIAL NETT	Qty	Unit S\$	TOTAL S\$
1	Sundries	1	\$ 80.00	\$ 80.00
2	Bootlid sealant	1	\$ 100.00	\$ 30.00
3	Bootlid reflector seal	2	\$ 50.00	\$ 60.00
4	Bootlid reflector clips	2	\$ 50.00	\$ 60.00
5	Bootlid outer chrome garnish clips	1	\$ 50.00	\$ 20.00
6	Bootlid inner trim board clips	1	\$ 50.00	\$ 50.00
7	Rear bumper clips	1	\$ 50.00	\$ 50.00
8	Rear end panel sealant	1	\$ 50.00	\$ 20.00
9	Rear end panel top garnish clips	1	\$ 100.00	\$ 40.00
10	Taillamp seal	2	\$ 80.00	\$ 30.00
11	Taillamp clips	2	\$ 50.00	\$ 80.00
12	Rear fender sealant	1	\$ 100.00	\$ 40.00
13	Rear fender inner trim board clips	2	\$ 50.00	\$ 60.00
14	Tailgate windscreen inner seal	1	\$ 120.00	\$ 80.00
15	Tailgate windscreen sealant	1	\$ 80.00	\$ 40.00
16	Tailgate windscreen primer and cleaner	1	\$ 60.00	\$ 60.00
17	Reverse sensor seal	2	\$ 45.00	\$ 90.00
SPECIAL NETT TOTAL:				\$530.00 1,490.00

NXX

NECV

NXX

NECV

NXX

NECV

NXX

NXX

Nos.	LABOUR	S\$
1	R&R bootlid component	\$ 60.00
2	R&R reverse sensor	\$ 60.00
3	R&R exhaust pipe	\$ 50.00
4	R&R rear windscreen	\$ 120.00
5	Panel beat	\$ 140.00
6	Upholstery	\$ 80.00
7	Rust proofing	\$ 60.00
8	Spray painting	\$ 100.00
9	Check wiring	\$ 50.00
LABOUR TOTAL:		\$2280.00 5,050.00

Survey 7/6/2020

Terum Hin

1600 hrs

Resurvey 10/6/2020

Terum Hin

1420 hrs

Lump sum repair

Repair days 8

PARTS TOTAL: \$5350.05 8,354.45

SPECIAL NETT TOTAL: \$ 530.00 1,490.00

LABOUR TOTAL: \$2280.00 5,050.00

GRAND TOTAL: \$ 14,894.45

8760.05

@ 22% 1752.01

7,008.04

L/S 7,000/h

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Printed by Eric (8269-9999) Page 2 of 2

Terum Hin

10/6/2020