

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/FWD20006249/KBA3Q2

Date: 15/09/2020

REFERENCE

Handling Insurer: FWD Singapore Pte. Ltd. Policy No: PNPV2018-00002996-02

Claimant Vehicle No : SJS8238K **Insured Vehicle No :** SLA2265S

Date of Loss: 10/06/2020 **Nature of Claim:** TP **Claim No:** 1202000018374

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJS8238K		
Make & Model:	BMW 528I, 2.0 AT D/AB LED NAV HUD (A)	Engine No:	B0601209N20B20A
Reg. Date:	04/11/2015 (Man. Year: 2015)	Chassis No:	WBA5A52030G389685
Colour:	Metallic Silver	Odometer:	96091 km
Engine Capacity:	1997 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	245/45 R18	Rear Tyre Size:	275/40 R18
Front Left Side:	Pirelli 9 mm	Rear Left Side:	Pirelli 9 mm
Front Right Side:	Pirelli 9 mm	Rear Right Side:	Pirelli 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,191.40	5,455.75	3,735.65	40.64
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,650.00	1,290.00	1,360.00	51.32
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	11,841.40	6,745.75	5,095.65	43.03
Approved Total (Overridden) (\$\$)		5,400.00		
Nett Amount (\$\$)	11,841.40	5,400.00	6,441.40	54.40
+ Car Rental (6.0 x S\$100.00/day) (\$\$)		600.00		
+ Doc/Search Fee (\$\$)		7.45		
Nett Liability (\$\$)		6,007.45		
Global Sum Settlement (\$\$)		6,000.00		

INSPECTION

Date of Assignment: 11/06/2020

Date Inspected: 16/06/2020 **Inspected At:**

Ngs Automotive (HQ)
BLK 10 AMK IND PK 2A #02-01
Singapore 568047

Estimated Period of Repair: 5.0 days

Adjuster: KENNETH KONG

Manager: CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 21 Aug 2020)
Parts:	143	BMW 528I 2.0 AT D/AB LED NAV HUD (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJS8238K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Bent	1,680.97 FL	*1,680.97 FL
2	1		*TRUNK LID	Bent	1,765.50 FL	*1,765.50 FL
3	1		*GUIDE ,BOTTOM CENTER	Serviceable	58.85 FL	*- FL
4	1		*GUIDE ,CENTER REAR	Cracked	71.69 FL	*71.69 FL
5	2		*PROTECTION FOIL ,RH/LH	Not Necessary	22.00 FL	*- FL
6	1		*SET OF MOUNTS ,PDC SENSOR	Not Necessary	62.06 FL	*- FL
7	1		*TRIGGER CONTACT PDC SENSOR	Not Necessary	144.45 FL	*- FL
8	4		*DECOUPLING PDC	Necessary	22.00 FL	*22.00 FL
9	1		*COVER ,TOW EYE	Serviceable	50.29 FL	*- FL
10	2		*MOUNT ,REAR RH/LH	Serviceable	396.80 FL	*- FL
11	3		*BLIND RIVET NUT	Not Necessary	10.50 FL	*- FL
12	6		*EXPANDING RIVET	Not Necessary	21.00 FL	*- FL
13	1		*CARRIER ,REAR BUMPER	Bent	829.25 FL	*829.25 FL
14	1		*ADAPTER ,REAR BUMPER	Bent	116.63 FL	*116.63 FL
15	1		*RUBBER ,TRUNK LID	Serviceable	70.62 FL	*- FL
16	1		*TAILLAMP LH/RH	N/S Cut	1,337.50 FL	*668.75 FL
17	2		*REAR LAMP,TRUNK LID RH/LH	Serviceable	789.66 FL	*- FL
18	2		*GASKET ,TAILLAMP	Not Necessary	77.04 FL	*- FL
19	2		*REFLECTOR ,REAR BUMPER RH/LH	Serviceable	79.18 FL	*- FL
20	1		*END PANEL	Repair	889.17 FL	*- FL
21	2		*PARKING SENSOR	Shorted (1 PCS ONLY)	791.80 FL	*395.90 FL
22	1		*REAR END GARNISH	Serviceable	136.00 FL	*- FL
23	1		*EMBLEM 528I	Necessary	68.50 FS	*68.50 FS
24	1		*BADGE	Necessary	75.95 FS	*75.95 FS
25	2		*GROMMET	Not Necessary	7.00 FS	*- FS
26	1		*NO PLATE	Serviceable	50.00 FS	*- FS
27	1		*COVERING LOWER RIGHT	Cracked	40.15 FL	*40.15 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	9,664.56	5,735.29
- List Item Discount on L Items 5.00/5.00% (\$)	473.16	279.54
Total Parts (\$)	9,191.40	5,455.75

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE ALL DAMAGED PART WITH ALL NECESSARY COMPONENT /ATTACHMENT ,STRAIGHTEN CHASSIS MEMBER,REPAIR /RESHAPE DENTED BODY PANEL REPLACE DAMAGED PART REFIT INTO POSTION	New	1,400.00	550.00
2	TO SPRAY PAINTING	New	1,000.00	660.00
3	TO TRANSFER TRUNK LID MECHANISM	New	150.00	60.00
4	CHECK WIRING & LIGHT FUNCTION	New	100.00	20.00
Gross Labour Cost (S\$)			2,650.00	1,290.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >