Adjuster Report Page 1 of 3

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG20006251/R1TF3E2

Date: 23/07/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:

Claimant Vehicle SLN190T Insured Vehicle No : SMP7325D

Date of Loss: 12/06/2020 Nature of Claim: TP Claim No: 6507056009SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLN190T

Make & Model: MERCEDES-BENZ E200 (R18), 2.0 (A) Engine No: 27492030961121

Reg. Date: 20/04/2017 (Man. Year: 2017) Chassis No: WDD2130422A210266

Colour: Blue Odometer: 34526 km

Engine Capacity: 1991 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 245/45R F18 Rear Tyre Size: 245/45R F18
Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm
Front Right Side: Bridgestone 6 mm
Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 15/06/2020

Date Inspected: 16/06/2020 Inspected At: Tg 2k Spray Painting Centre

Blk 1010 Bukit Merah Lane 3, #01-117

Singapore 159724

Estimated Period of Repair: 3.0 days

Adjuster: MOHD RASUL Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 2 of 3

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Scratched	0.00 F	*- F
2	1		*REAR RH FENDER	Repair	0.00 F	*- F
F=Fra	anchise	part.		Total Parts (S\$)	0.00	0.00
			Report was uns	ubmitted during this print-out.		

Adjuster Report Page 3 of 3

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >