

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG20006252/UDS3Q2

Date: 13/08/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 0999993965

Claimant
Vehicle No : SME8617M **Insured Vehicle No :** GBH3358H

Date of Loss: 11/06/2020 Nature of Claim: TP Claim No: 9149486235SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SME8617M		
Make & Model:	HONDA FIT, 1.5 HYBRID (A)	Engine No:	LEB6071300
Reg. Date:	19/10/2018 (Man. Year: 2018)	Chassis No:	GP53416447
Colour:	Yellow	Odometer:	35705 km
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	175/70R14	Rear Tyre Size:	175/70R14
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	16,118.80	7,818.08	8,300.72	51.50
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,380.00	2,820.00	1,560.00	35.62
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	20,498.80	10,638.08	9,860.72	48.10
Approved Total (Overridden) (S\$)		8,500.00		
(S\$)	20,498.80	8,500.00	11,998.80	58.53
+ GST 7.00/7.00% (S\$)	1,434.92	595.00	839.92	58.53
Nett Amount (S\$)	21,933.72	9,095.00	12,838.72	58.53
+ Car Rental (7.0 x S\$100.00/day) (S\$)		700.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		9,802.45		

INSPECTION

Date of Assignment: 12/06/2020

Date Inspected: 12/06/2020 Inspected At:

Fastech Auto Pte Ltd (HQ)
1 Kaki Bukit Ave 6, #01-46/48/50
Autobay
Singapore 417883

Estimated Period of Repair: 6.0 days

Adjuster: MARCUS CHUA**Manager:** CHAN JIA LE

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Distorted	715.30 F	*615.30 FL
2	1		*FRONT BUMPER SIDE RETAINER O/S	Cracked	45.80 F	*20.50 FL
3	1		*FRONT BUMPER FOG LAMP COVER O/S	Twisted	150.50 F	*145.30 FL
4	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	288.20 F	*- FL
5	1		*SET FRONT BUMPER CLIPS	Necessary	39.00 F	*39.00 FL
6	1		*HEADLAMP O/S	Cracked	1,820.20 F	*1,170.60 FL
7	1		*FRONT FENDER O/S	Dented / Bent	665.20 F	*406.90 FL
8	1		*FRONT FENDER HYBRID O/S	Necessary	85.80 F	*85.80 FL
9	1		*FRONT FENDER INNER SHIELD O/S	Torn	185.20 F	*122.60 FL
10	1		*SET FRONT FENDER INNER SHIELD CLIPS O/S	Necessary	39.00 F	*39.00 FL
11	1		*FRONT FENDER INNER PANEL O/S	Repair	311.60 F	*- FL
12	1		*FRONT SHOCK ABSORBER O/S	Twisted	485.20 F	*485.20 FL
13	1		*FRONT LOWER ARM O/S	Bent	499.50 F	*481.20 FL
14	1		*FRONT KNUCKLE ARM O/S	Bent	482.30 F	*455.50 FL
15	1		*FRONT KNUCKLE ARM BEARING O/S	Necessary	285.50 F	*285.50 FL
16	1		*FRONT DRIVE SHAFT O/S	Not Necessary	1,148.20 F	*- FL
17	1		*FRONT DOOR O/S	Repair	866.20 F	*- FL
18	1		*FRONT DOOR RUBBER O/S	Not Necessary	122.30 F	*- FL
19	1		*FRONT DOOR VIEW MIRROR ASSY O/S	Damaged / Cut	850.50 F	*688.50 FL
20	1		*FRONT DOOR FRAME BLACK STICKER O/S	Not Necessary	86.00 F	*- FL
21	1		*REAR DOOR O/S	Bent / Warped	815.30 F	*815.30 FL
22	1		*REAR DOOR RUBBER O/S	Necessary	121.30 F	*121.30 FL
23	1		*REAR DOOR GLASS REGULATOR O/S	Not Necessary	199.50 F	*- FL
24	1		*REAR DOOR GLASS REGULATOR MOTOR O/S	Not Necessary	355.20 F	*- FL
25	1		*REAR DOOR FRAME BLACK STICKER O/S	Necessary	86.00 F	*68.00 FL
26	1		*REAR DOOR OUTER HANDLE O/S	Not Necessary	145.30 F	*- FL
27	1		*REAR FENDER O/S	Dented / Bent	866.50 F	*841.50 FL
28	1		*REAR FENDER GLASS O/S	Necessary	485.00 F	*325.50 FL
29	1		*REAR WHEEL HUB BEARING O/S	Damaged	255.00 F	*255.00 FL
30	1		*REAR SHOCK ABSORBER O/S	Not Necessary	362.20 F	*- FL
31	1		*REAR TAILLAMP O/S	Cracked	482.30 F	*366.00 FL
32	1		*REAR BUMPER	Torn	705.20 F	*566.50 FL
33	1		*REAR BUMPER SIDE RETAINER O/S	Not Necessary	45.50 F	*- FL
34	1		*SET REAR BUMPER CLIPS	Necessary	39.00 F	*39.00 FL
35	1		*REAR BUMPER SPLASH SHIELD O/S	Torn	148.50 F	*85.60 FL
36	1		*REAR AIR VENT O/S	Cracked	85.50 F	*85.50 FL
37	1		*FRONT SPORT RIM O/S	Dented / Bent	850.00 FS	*450.00 FS
38	1		*REAR SPORT RIM O/S	Dented / Bent	850.00 FS	*450.00 FS
39	1		*REAR FENDER GLASS O/S	Necessary	50.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) 16,118.80 9,540.10
- List Item Discount on L Items 0.00/20.00% (\$\$) 0.00 1,722.02

Total Parts (\$\$) 16,118.80 7,818.08

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO CHECK WIRING	New	50.00	20.00
2	TO DISMANTLE & REFIX REVERSE SENSOR	New	80.00	50.00
3	TO TRANSFER REAR DOOR MECHANISM	New	80.00	60.00
4	TO CONDUCT WHEEL ALIGNMENT	New	150.00	100.00
5	TO DISMANTLE & REPLACED REAR FENDER GLASS O/S	New	100.00	100.00
6	TO DISMANTLE & REFIX CUSHION UPHOLSTERY	New	120.00	80.00
7	TO DISMANTLE & REPLACE FRONT ,REAR UNDER CARRIAGE	New	380.00	240.00
8	TO SPRAY RUST PROOFING	New	120.00	90.00
9	LABOUR FOR PANEL BEATING & REPLACE PARTS	New	1,500.00	880.00
10	TO PUTTY & SPRAY PAINTING	New	1,800.00	1,200.00
Gross Labour Cost (\$\$)			4,380.00	2,820.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >