

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI20006255/EQF3E2

Date: 24/06/2020

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd.	Policy No: DMPCSN30156219033	
Claimant Vehicle No : GBB9156R	Insured Vehicle No : SJR7364R	
Date of Loss: 04/06/2020	Nature of Claim: TP	Claim No: SNM20D202057/C02/TKL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBB9156R	
Make & Model:	TOYOTA HIACE, 3.0 D (M)	Engine No: 1KD2024421
Reg. Date:	20/09/2010 (Man. Year: 2010)	Chassis No: JTFHT02P300061001
Colour:	Black	Odometer: 222518 km
Engine Capacity:	2982 cc	
Market Value/New Car Price:	N/A	
Sum Insured (S\$):	Market Value/New Car Price	

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195 R15C	Rear Tyre Size:	195 R15C
Front Left Side:	Yokohama 5 mm	Rear Left Side:	Yokohama 5 mm
Front Right Side:	Yokohama 5 mm	Rear Right Side:	Yokohama 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,320.01	1,540.26	779.75	33.61
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,730.00	1,040.00	690.00	39.88
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,050.01	2,580.26	1,469.75	36.29
Approved Total (Overridden) (S\$)		2,050.00		
Nett Amount (S\$)	4,050.01	2,050.00	2,000.01	49.38

INSPECTION

Date of Assignment:	09/06/2020	
Date Inspected:	10/06/2020 Inspected At:	My Car Consultant Pte Ltd (Ubi) 53 Ubi Ave 1, #01-33, Paya Ubi Industrial Park Singapore 408934
Estimated Period of Repair:	5.0 days	

Adjuster: CHEN TSUE YEE

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 23 Jun 2020)	
Parts:	N/A	TOYOTA HIACE 3.0 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBB9156R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*LH REAR FENDER	Dented	1,120.10 FL	*1,120.10 FL
2	1		*LH REAR TAILLAMP	Cut	277.20 FL	*277.20 FL
3	1		*LH REAR TAILLAMP LOWER APRON PANEL	Broken	322.60 FL	*158.70 FL
4	2		*LH REAR TAILLAMP LOWER APRON PANEL CLIPS	Necessary	11.78 FL	*11.78 FL
5	1		*REAR BUMPER	Cut	399.20 FL	*399.20 FL
6	1		*LH REAR BUMPER SIDE RETAINER	Broken	46.70 FL	*46.70 FL
7	1		*LH REAR FENDER AIR VENT	Not Necessary	112.30 FL	*- FL
8	1		*LH FRONT RIM	Not Necessary	256.80 FL	*- FL
9	1		*SET REAR BUMPER CLIP	Necessary	80.00 FS	*30.00 FS
10	1		*SET REAR END PANEL GARNISH CLIP	Not Necessary	30.00 FS	*- FS
11	1		*FLOOR PANEL SEALANT	Not Necessary	50.00 FS	*- FS
12	1		*END PANEL SEALANT	Not Necessary	50.00 FS	*- FS
13	1		*MISCELLANEOUS	Not Necessary	200.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	2,956.68	2,043.68
- List Item Discount on L Items 25.00/25.00% (\$)	636.67	503.42
Total Parts (\$)	2,320.01	1,540.26

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK ELECTRICAL WIRING	New	80.00	30.00
2	TO RESPRAY UNDERCOATING	New	100.00	30.00
3	APPLY ANTI RUST ON AFFECTED AREAS	New	150.00	30.00
4	SPRAY PAINTING ON AFFECTED AREAS	New	600.00	350.00
5	PANEL BEATING ON AFFECTED AREAS	New	800.00	600.00
			Gross Labour Cost (S\$)	1,730.00
				1,040.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >