

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC6/III20006256/UBS3Q2

**Date:** 14/08/2020

### REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No:	MCOM0015
<b>Claimant</b>		
<b>Vehicle No :</b> GBG4687G	<b>Insured Vehicle No :</b>	SHC1333Y
Date of Loss: 08/06/2020	Nature of Claim: TP	Claim No: MCT20060069

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>GBG4687G</b>		
Make & Model:	SSANGYONG ACTYON SPORTS, 2.0 D/CAB 2.0 AT AIRBAG 2WD (A)	Engine No:	67196022687744
Reg. Date:	18/08/2017 (Man. Year: 2017)	Chassis No:	KPADA1ETSH304165
Colour:	Grey	Odometer:	140525 km
Engine Capacity:	1998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	225/75 R16	Rear Tyre Size:	225/75 R16
Front Left Side:	Nexen 6 mm	Rear Left Side:	Nexen 6 mm
Front Right Side:	Nexen 6 mm	Rear Right Side:	Nexen 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	11,469.70	5,973.35	5,496.35	47.92
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,550.00	1,300.00	1,250.00	49.02
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>14,019.70</b>	<b>7,273.35</b>	<b>6,746.35</b>	<b>48.12</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>5,800.00</b>		
<b>Nett Amount (S\$)</b>	<b>14,019.70</b>	<b>5,800.00</b>	<b>8,219.70</b>	<b>58.63</b>
<b>+ Loss of Use (4.0 x S\$120.00/day) (S\$)</b>		480.00		
<b>Nett Liability (S\$)</b>		<b>6,280.00</b>		

### INSPECTION

Date of Assignment:	09/06/2020	
Date Inspected:	09/06/2020 Inspected At:	Choo Motor Spray Painter (HQ) 1 Kaki Bukit Avenue 6, #01-39 AutoBay @ Kaki Bukit Singapore 417883
Estimated Period of Repair:	4.0 days	

**Adjuster:** MARCUS CHUA

**Manager:** CHUA ZHEN LI

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 23 Jul 2020)
<b>Parts:</b>	M1-SUV	SSANGYONG ACTYON SPORTS 2.0 D/CAB 2.0 AT AIRBAG 2WD (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for GBG4687G)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*FRONT BUMPER	Deformed / Torn	1,480.00 F	*1,250.00 FL
2	1	*FRONT BUMPER SIDE RETAINER N/S	Cracked	88.50 F	*66.50 FL
3	1	*SET FRONT BUMPER CLIPS	Necessary	50.00 F	*50.00 FL
4	1	*FRONT BUMPER FOG LAMP N/S	Cracked	685.00 F	*425.00 FL
5	1	*FRONT BUMPER REINFORCEMENT	Not Necessary	699.00 F	*- FL
6	1	*HEADLAMP N/S	Cracked	1,820.30 F	*1,150.00 FL
7	1	*FRONT SUPPORT PANEL	Repair	945.20 F	*- FL
8	1	*FRONT FENDER N/S	Dented / Bent	921.30 F	*688.00 FL
9	1	*FRONT FENDER INNER SHIELD N/S	Torn	295.40 F	*226.00 FL
10	1	*SET FRONT FENDER INNER SHIELD CLIPS N/S	Necessary	50.00 F	*50.00 FL
11	1	*WIPER WASHER TANK	Deformed	288.00 F	*245.00 FL
12	1	*FRONT SHOCK ABSORBER N/S	Not Necessary	750.00 F	*- FL
13	1	*FRONT TOP ARM N/S	Twisted	615.00 F	*311.50 FL
14	1	*FRONT LOWER ARM N/S	Bent	1,022.00 F	*699.30 FL
15	1	*FRONT KNUCKLE ARM N/S	Bent	945.00 F	*788.20 FL
16	1	*FRONT KNUCKLE ARM BEARING N/S	Necessary	450.00 F	*450.00 FL
17	1	*FRONT TIE ROD END N/S	Twisted	215.00 F	*182.00 FL
18	1	*FRONT STEEL RIM N/S	Bent	150.00 FS	*50.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (S\$)</b>	<b>11,469.70</b>	<b>6,631.50</b>
<b>- List Item Discount on L Items 0.00/10.00% (S\$)</b>	<b>0.00</b>	<b>658.15</b>
<b>Total Parts (S\$)</b>	<b>11,469.70</b>	<b>5,973.35</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	TO CHECK WIRING	New	50.00	20.00
2	TO SPRAY RUST PROOFING	New	80.00	30.00
3	TO CONDUCT WHEEL ALIGNMENT	New	120.00	80.00
4	TO DISMANTLE & REPLACED FRONT UNDER CARRIAGE	New	180.00	120.00
5	TO REFILL AIR CON GAS	New	120.00	0.00
6	LABOUR FOR PANEL BEATING & RELACED PARTS	New	800.00	450.00
7	TO PUTTY & SPRAY PAINTING	New	1,200.00	600.00
<b>Gross Labour Cost (\$\$)</b>			<b>2,550.00</b>	<b>1,300.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >