



ABSOLUTE APPRAISAL SERVICES PTE LTD
LOSS ADJUSTERS & MOTOR APPRAISERS

160 Sin Ming Drive #05-16 Sin Ming AutoCity (S) 575722

Mobile: 9688-0413 Fax: 6266-7396

Email: absolute.app.svcs@gmail.com

Invoice

Customer: Lumens Auto Pte Ltd
C/o: 160 Sin Ming Drive #05-16
Sin Ming AutoCity (S) 575722

Date: 15.10.2019

Invoice No: NS-2019-290

Description		Amount
Vehicle No:	SMF1571B	
Make & Model:	Toyota Prius Plus (A)	
Our reference:	AAS/2019/290	
Services rendered for appraiser / inspection report		
Survey Fee		
Photographs		
Transport Fees		
Re-inspection Fees		
SGD Dollar : Five hundred and twelve dollar only	Total:	SGD \$ 512.00

Notes:


All cheques payment should be crossed and made payment to "Absolute Appraisal Services Pte Ltd"

Please indicate our "Invoice No." on the reverse side of the cheque.

Please do not hesitate to contact us should you have any enquires.



Absolute Appraisal Services Pte Ltd



ABSOLUTE APPRAISAL SERVICES PTE LTD
LOSS ADJUSTERS & MOTOR APPRAISERS

160 Sin Ming Drive #05-16 Sin Ming AutoCity (S) 575722

Mobile: 9688-0413 Fax: 6266-7396

Email: absolute.app.svcs@gmail.com

Vehicle Inspection Report

To: Lumens Auto Pte Ltd
C/o: 160 Sin Ming Drive #05-16
Sin Ming AutoCity (S) 575722

Date of report: 15.10.2019
Date of request: 13.06.2019
Date of inspection: 13.06.2019
Date of accident: 02.06.2019
Claim type: Third Party Claim

Report No: AAS/2019/290

Particulars of affected vehicle:

Registration no: SMF1571B
Make/Model: Toyota Prius Plus (A)
Year of registration: 2018
Colour: Metallic Black

Odometer: 45062 km
Engine Capacity: 1798 cc
Engine no: 2ZR0C56808
Chassis no: JTDZS3EU70J034171

Condition of tires:

Front Left: 6mm
Make: Yokohama
Rear Left: 6mm
Make: Yokohama

Front Right: 6mm
Make: Yokohama
Rear Right: 6mm
Make: Yokohama

Type of road wheel: Alloy (The above represent the remaining life of the tire thread)

Pre-accident condition (Static tests only)

General Bodywork	: Good
Paintwork	: Good
Handbrake	: In order
Footbrake	: In order
Steering	: In order
Apparent engine modification	: Nil

The Assignment

The inspection was conducted at M/s. Toh Motor Enterprise
160 Sin Ming Drive #05-16
Sin Ming AutoCity (S) 575722

(Subsequent inspection was conducted)

Assessment

Repairer's estimate:	\$ 6,695.26
Revised estimate:	\$ 5,348.01
Recommended reserve:	\$ 4,300.00 (Lump sum)

Estimated normal duration of repairs : 8 Working days



ABSOLUTE APPRAISAL SERVICES PTE LTD
LOSS ADJUSTERS & MOTOR APPRAISERS

160 Sin Ming Drive #05-16 Sin Ming AutoCity (S) 575722

Mobile: 9688-0413 Fax: 6266-7396

Email: absolute.app.svcs@gmail.com

Vehicle No: SMF1571B

Report No: AAS/2019/290

W/O PREJUDICE

Point of impact

At the rear portion.

General description of damages

The tailgate, rear bumper, rear bumper lower, rear end panel, etc.

Other parts were also found damaged. (See schedule for details)

Recommendation

The estimate cost of repair submitted by M/s Toh Motor Enterprise as per schedule attached have been revise and scrutinize. We list the breakdown of our findings and recommendation as per attached.

Our adjusted amount for the cost of repair is SGD \$5,348.01

Conclusion

The repairer has agreed to undertake the repair at a lumpsum of SGD \$4,300.00

Under normal circumstances, the repair of the damaged vehicle should be completed within a reasonable period of 8 working days.

We have **Not Authorised** and/or instruction to the repairer to proceed with the repairs. This inspection was conducted entirely on a '**Without Prejudice**' basis.

We are pleased to advise that the inspection was carried out accordingly and hereby submit our appraisal report which includes 52 photographs.

Your Faithfully

Absolute Appraisal Services Pte Ltd



Nicky Seah

Automobile Appraiser

MSAAA / MSMCTA



ABSOLUTE APPRAISAL SERVICES PTE LTD LOSS ADJUSTERS & MOTOR APPRAISERS

160 Sin Ming Drive #05-16 Sin Ming AutoCity (S) 575722

Mobile: 9688-0413 Fax: 6266-7396


Email: absolute.app.svcs@gmail.com

Vehicle No: SMF1571B

Report No: AAS/2019/290

Appraisement Schedule

S/N	Parts Description	Qty	Condition		Repairer's Est	Revised Est
1	Rear bumper ✓	1	Dented/Torn		\$ 594.60	523.9 \$ 594.60
2	Rear bumper lower trim ✓	1	Dented/Grazed		\$ 761.70	728.9 \$ 761.70
3	Rear bumper retainer LH/RH ✓	2	Cracked	\$ 120.49	\$ 240.98	227.2 \$ 240.98
4	Rear bumper support LH/RH ✓	2	Cracked	\$ 87.40	\$ 174.80	134 \$ 174.80
5	Rear bumper undercover	1	Serviceable		\$ 422.30	-
6	Rear bumper reinforcement ✓	1	Dented		\$ 345.70	✓ \$ 345.70
7	Rear bumper reinforcement bracket LH/RH X SVC	2	Dented	\$ 201.95	\$ 403.90	X \$ 403.90
8	Tailgate nameplate 'Prius+' ✓	1	Necessary		\$ 71.70	50 \$ 71.70
9	Tailgate nameplate 'Hybrid' ✓	1	Necessary		\$ 69.80	52.3 \$ 69.80
10	Tailgate sensor ✓	1	Dented		\$ 189.40	169.5 \$ 189.40
11	Rear end panel X REPAIR	1	Dented		\$ 678.10	X \$ 678.10
12	Rear end panel trim	1	Serviceable		\$ 240.70	-
				2231.5	Total:	\$ 4,193.68 \$ 3,530.68
				-25%: 1673.63	-25%	\$ 1,048.42 \$ 882.67
					List total:	\$ 3,145.26 \$ 2,648.01
1	Rear bumper clips ✓	1set	Necessary		\$ 50.00	✓ \$ 30.00
2	Reverse sensor ✓	1set	Malfunctioned		\$ 300.00	200 \$ 250.00
3	Joint sealant X SVC	1	Necessary		\$ 60.00	X \$ 40.00
					Special nett total:	\$ 410.00 \$ 320.00
						230
					Parts Total:	\$ 3,555.26 \$ 2,968.01



ABSOLUTE APPRAISAL SERVICES PTE LTD
LOSS ADJUSTERS & MOTOR APPRAISERS

160 Sin Ming Drive #05-16 Sin Ming AutoCity (S) 575722

Mobile: 9688-0413 Fax: 6266-7396

Email: absolute.app.svcs@gmail.com

Vehicle No: SMF1571B		Report No: AAS/2019/290	
S/N	Labour Description	Repairer's Est	Revised Est
1	Check rear lighting and wirings.	\$ 60.00	\$ X 40.00
2	Anti rust on rear replacement & affected parts.	\$ 50.00	\$ X 30.00
3	Renew reverse sensor.	\$ 80.00	\$ 40 50.00
4	Remove & reinstall rear trimmings.	\$ 100.00	\$ ✓ 60.00
5	Remove & renew rear damaged parts.	\$ 1,250.00	500 \$ 1,000.00
6	Respray rear damaged parts.	1140 \$ 1,600.00	600 \$ 1,200.00
Labour Total:		\$ 3,140.00	\$ 2,380.00

Grand Total: \$ 6,695.26 \$ 5,348.01

The final adjusted lump sum amount is \$4,300.00

Under normal circumstances, the repair should be completed within a reasonable period of 8 working days.

3043.63

-20%: 2400

52 Photographs were taken at the time of inspection.

4 DAYS

