

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

### VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC4/FWD20006262/AGS3Q2

**Date:** 06/01/2021

#### REFERENCE

Handling Insurer: FWD Singapore Pte. Ltd. Policy No: PNPV2018-00008358-01

**Claimant**  
**Vehicle No :** SMP1674K **Insured Vehicle No :** SKU8187B

Date of Loss: 10/06/2020 Nature of Claim: TP Claim No: 1202000018345

#### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SMP1674K</b>	Engine No:	3ZZ4939306
Make & Model:	TOYOTA COROLLA ALTIS, 1.6 (A)	Chassis No:	MR053ZEE106157434
Reg. Date:	28/10/2009 (Man. Year: 2009)	Odometer:	148154 km
Colour:	Silver		
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

#### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

#### CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,569.77	903.65	2,666.12	74.69
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,660.00	940.00	1,720.00	64.66
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>6,229.77</b>	<b>1,843.65</b>	<b>4,386.12</b>	<b>70.41</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>1,400.00</b>		
(S\$)	6,229.77	1,400.00	4,829.77	77.53
<b>+ GST 7.00/7.00% (S\$)</b>	436.08	98.00	338.08	77.53
<b>Nett Amount (S\$)</b>	<b>6,665.85</b>	<b>1,498.00</b>	<b>5,167.85</b>	<b>77.53</b>
<b>+ Loss of Use (5.0 x S\$60.00/day) (S\$)</b>		300.00		
<b>+ Doc/Search Fee (S\$)</b>		7.45		
<b>Nett Liability (S\$)</b>		<b>1,805.45</b>		

#### INSPECTION

Date of Assignment: 11/06/2020

Date Inspected: 12/06/2020 Inspected At:

MG Solution Pte Ltd (HQ)  
23 Kaki Bukit Avenue 4 #02-03B,  
VICOM Inspection Centre  
Singapore 415933

Estimated Period of Repair: 4.0 days

---

**Adjuster:** ADRIAN LING

**Manager:** Chong Pui Lin

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 07 Oct 2020)
<b>Parts:</b> 143	TOYOTA COROLLA ALTIS 1.6 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SMP1674K)
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b> Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Not Necessary	769.60 FL	*- FL
2	1		*BOOTLID LOGO	Not Necessary	70.00 FL	*- FL
3	1		*BOOTLID EMBLEM 1.6	Not Necessary	44.00 FL	*- FL
4	1		*BOOTLID EMBLEM LX	Not Necessary	36.00 FL	*- FL
5	1		*BOOTLID EMBLEM COROLLA	Not Necessary	36.00 FL	*- FL
6	1		*BOOTLID EMBLEM ALTIS	Not Necessary	35.00 FL	*- FL
7	1		*BOOTLID TOP LOCK	Not Necessary	79.00 FL	*- FL
8	1		*BOOTLID WEATHERSTRIP	Not Necessary	157.00 FL	*- FL
9	1		*BOOTLID REFLECTOR RH	Not Necessary	140.00 FL	*- FL
10	1		*REAR BUMPER	Deformed	580.00 FL	*485.00 FL
11	2		*REAR BUMPER SIDE RETAINER	Necessary	116.00 FL	*116.00 FL
12	2		*REAR BUMPER REFLECTOR	Not Necessary	170.60 FL	*- FL
13	1		*REAR END REINFORCEMENT BAR	Not Necessary	211.30 FL	*- FL
14	1		*REAR END REINFORCEMENT SPONGE	Cracked	91.20 FL	*91.20 FL
15	2		*TAILLAMP	Not Necessary	750.00 FL	*- FL
16	1		*REAR END PANEL	Repair	708.00 FL	*- FL
17	1		*REAR END PANEL TOP GARNISH	Deformed	126.00 FL	*126.00 FL
18	1		*REAR NUMBER PLATE	Not Necessary	50.00 FS	*- FS
19	1		*SET REAR BUMPER CLIPS	Necessary	20.00 FS	*20.00 FS
20	1		*SET TAILLAMP CLIP	Not Necessary	20.00 FS	*- FS
21	1		*SET REAR END PANEL TOP GARNISH CLIPS	Necessary	20.00 FS	*10.00 FS
22	1		*REAR END PANEL INSULATION SEAL	Necessary	150.00 FS	*60.00 FS
23	1		*REVERSE SENSOR	Damaged	220.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>4,599.70</b>	<b>1,108.20</b>
<b>- List Item Discount on L Items 25.00/25.00% (\$\$)</b>	1,029.93	204.55
<b>Total Parts (\$\$)</b>	<b>3,569.77</b>	<b>903.65</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	PANEL BEATING ,REMOVAL AND REPLACING PARTS	New	1,000.00	400.00
2	TO SPRAY PAINT AFFECTED AREA	New	1,000.00	400.00
3	TUFF COAT	New	350.00	60.00
4	WIRING CHECK	New	150.00	30.00
5	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	New	80.00	50.00
6	TRANFER BOOTLID MECHANISM	New	80.00	0.00
<b>Gross Labour Cost (\$\$)</b>			<b>2,660.00</b>	<b>940.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >