

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC6/AIG20006264/APA3Q2

**Date:** 05/01/2021

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800074652
<b>Claimant</b>		
<b>Vehicle No :</b> SGU7790M	<b>Insured Vehicle No :</b>	GBC8089C
Date of Loss: 09/06/2020	Nature of Claim: TP	Claim No: 5558127357SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SGU7790M		
Make & Model:	VOLKSWAGEN GOLF, 1.4 TSI (A7) (5G13GZ)	Engine No:	CXS202473
Reg. Date:	17/07/2014 (Man. Year: 2014)	Chassis No:	WVWZZZAUZEW400716
Colour:	Silver	Odometer:	69552 km
Engine Capacity:	1395 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	225/45 R17	Rear Tyre Size:	225/45 R17
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,973.50	2,334.87	1,638.63	41.24
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,180.00	680.00	500.00	42.37
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>5,153.50</b>	<b>3,014.87</b>	<b>2,138.63</b>	<b>41.50</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>2,400.00</b>		
<b>(S\$)</b>	5,153.50	2,400.00	2,753.50	53.43
<b>+ GST 7.00/7.00% (S\$)</b>	360.75	168.00	192.75	53.43
<b>Nett Amount (S\$)</b>	<b>5,514.25</b>	<b>2,568.00</b>	<b>2,946.25</b>	<b>53.43</b>
<b>+ Car Rental (5.0 x S\$100.00/day) (S\$)</b>		500.00		
<b>Nett Liability (S\$)</b>		<b>3,068.00</b>		

### INSPECTION

Date of Assignment:	11/06/2020		
Date Inspected:	11/06/2020	Inspected At:	J-mart Motor Pte Ltd (HQ) Blk 5 Defu Lane 10, #01-578 Singapore 539186
Estimated Period of Repair:	4.0 days		

**Adjuster:** ADRIAN LING**Manager:** CHEW HSIAO TONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR RH DOOR	Dented	1,700.00 FL	*1,480.00 FL
2	1		*REAR RH DOOR OUTER HANDLE	Cracked	233.70 FL	*233.70 FL
3	1		*REAR RH DOOR OUTER MOULDING	Necessary	190.20 FL	*190.20 FL
4	1		*REAR RH DOOR W/STRIP	Necessary	200.70 FL	*200.70 FL
5	1		*REAR RH DOOR LOCK	Damaged	489.70 FL	*489.70 FL
6	1		*REAR RH DOOR TRIMBOARD	Not Necessary	1,600.70 FL	*- FL

F=Franchise part. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>4,415.00</b>	<b>2,594.30</b>
<b>- List Item Discount on L Items 10.00/10.00% (\$\$)</b>	441.50	259.43
<b>Total Parts (\$\$)</b>	<b>3,973.50</b>	<b>2,334.87</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	500.00	200.00
2	SPRAY PAINTING	New	600.00	400.00
3	TRANSFER DOORS PARTS	New	80.00	80.00
<b>Gross Labour Cost (\$\$)</b>			<b>1,180.00</b>	<b>680.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >