

ASS. REC. BY:

REF: C04/PCI20006267/Dev³

ASSIGNMENT

COE Sept 2023

From: _____ Date: _____
 Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s _____
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

Veh No: SHA 7964Y Yr Regn: 2015 / Sept
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: Hyundai I40 c.c. 1685
 Colour: Blue A/C: Insured / Std / NI / NA
 Sp. Reading: 749242 T/Radio: Insured / Std / NI / NA
 Eng/No: D4FDFU579577
 C/No: KMHLB41UMGU077270
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or _____
 Brake: In order / Jammed / Leaked / Burnt or _____
 Modi: Nil / S/Rim / STD A/Rim or _____
 Tyre Size: F: 205 / 60 R16
 R: 11

<input checked="" type="checkbox"/>	<input type="checkbox"/>
N/S	O/S

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 8 days Res.: Yes or No
 Lum Sum: 20 % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____ Vehicle: IN / OUT

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or Hankook
 Front Rear
 R/Bal. S mm R/Bal. S mm
 L/Bal. S mm L/Bal. S mm
 D.O.A. 08/06/2020 D.O.I. 12/06/2020
 Survey held at Bijrest Sin Ming
 Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or
N/S Portion
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	First Capital SH 6096S
28/09/2020 28/09/2020	Insure 2/5 11,200 - with 8 days of rep

Date/Time, File Pass to? : Prel. Report
 : Final Report
 1) _____
 Date/Time, File Return to?
 2) _____
 Report Format : _____
 Lump Sum / L.B.I: (\$) _____

Days Of Repair: _____
 Resurvey No. of Trip: _____
 Add Fee: : Site Insp (\$) _____
 : Interview (\$) _____
 : Tech. Invs (\$) _____
 : Weekend (\$) _____

Survey Fee:	_____
Transportation:	_____
S + RS, SI	_____
Photos	_____
Others	_____
TOTAL	_____

BIFROST AUTO PTE LTD

REPAIR ESTIMATE

DATE: 9-Jun-20

INSURANCE: FCI

MODEL: HYUNDAI I40

VEHICLE NO.: SHA7964Y

DESCRIPTION	QTY	LIST PRICE	AMOUNT
REAR BUMPER <i>distorted</i> 553.00	1	\$1,106.00	\$1,106.00
REAR BUMPER CLIP <i>hec</i>	1	\$19.00	\$19.00
REAR BUMPER SPONGE <i>HH</i>	1	\$119.50	\$119.50
REAR BUMPER UNDER COVER <i>HH</i>	1	\$228.00	\$228.00
REAR FENDER <i>Bnc</i>	1	\$2,171.40	\$2,171.40
REAR FENDER UNDER SHIELD(LH) <i>HH</i>	1	\$338.60	\$338.60
REAR FENDER AIR-DUCT (LH) <i>HH</i>	1	\$51.60	\$51.60
REAR FENDER TRIM BOARD (LH) <i>HH</i>	1	\$688.75	\$688.75
REAR DOOR (LH) <i>Dented</i>	1	\$2,201.10	\$2,201.10
REAR DOOR RUBBER (LH) <i>HH</i>	1	\$185.40	\$185.40
REAR DOOR HINGE UPPER (LH) <i>HH</i>	1	\$114.50	\$114.50
REAR DOOR HINGE LOWER (LH) <i>HH</i>	1	\$123.50	\$123.50
REAR DOOR CHECK (LH) <i>HH</i>	1	\$92.90	\$92.90
ROCKER PANEL OUTER GARNISH (LH) <i>cut / broken</i>	1	\$732.80	\$732.80
ROCKER PANEL OUTER <i>HH</i>	1	\$1,380.50	\$1,380.50
REAR TYRE RIM (LH) <i>2 x 1</i> 325.30	1	\$650.60	\$650.60
REAR TYRE WHEEL CAP <i>cut / 1st</i> 107.10	1	\$214.20	\$214.20
REAR WHEEL BEARING ING & HUB <i>2 Down</i> 401.40	1	\$724.00	\$724.00
REAR TRAILING ARM (LH) <i>2 distorted</i>	1	\$384.00	\$384.00
REAR ASSIST (LH) <i>2 distorted</i>	1	\$219.40	\$219.40
REAR SHOCK ABSORBER (LH) <i>2 distorted</i> 276.30	1	\$683.70	\$683.70
REAR SHOCK ABSORBER MOUNTING (LH) <i>HH</i>	1	\$162.60	\$162.60
ABS SENSOR <i>HH</i>	1	\$217.90	\$217.90
REAR LOWER ARM (LH) <i>2 distorted</i>	1	\$353.80	\$353.80
REAR KNUCKLE ARM (LH) <i>2 distorted</i>	1	\$545.60	\$545.60
FRONT FENDER (LH) <i>Dented</i>	1	\$566.30	\$566.30
FRONT FENDER SHIELD (LH) <i>SLC</i>	1	\$174.90	\$174.90
FRONT DOOR (LH) <i>Dented</i>	1	\$2,256.40	\$2,256.40
FRONT DOOR RUBBER <i>HH</i>	1	\$196.00	\$196.00
FRONT DOOR HINGE UPPER (LH) <i>HH</i>	1	\$113.60	\$113.60
FRONT DOOR HINGE LOWER (LH) <i>HH</i>	1	\$125.70	\$125.70
FRONT DOOR CHECK (LH) <i>HH</i>	1	\$91.80	\$91.80
FRONT WHEEL RIM (LH) <i>distorted</i> 325.30	1	\$650.60	\$650.60
KNUCKLE ARM (LH) <i>2 distorted</i> 552.00	1	\$595.90	\$595.90
FRONT WHEEL BEARING HUB ASSY (LH) <i>2 Down</i> 301.801	1	\$673.20	\$673.20
FRONT SUSPENSION LOWER ARM (LH) <i>2 distorted</i> 595.80 x1	1	\$1,104.00	\$1,104.00
FRONT SHOCK ABSORBER ASSY (LH) <i>2 distorted</i> 342.201	1	\$684.40	\$684.40
FRONT SHOCK ABSORBER MOUNTING (LH) <i>HH</i>	1	\$217.60	\$217.60
STG TIE ROD (LH) <i>HH</i>	1	\$186.40	\$186.40
STG TIE END (LH) <i>HH</i>	1	\$125.20	\$125.20
STABILIZER BAR ASSY <i>HH</i>	1	\$463.70	\$463.70
STABILIZER BAR LINK (LH) <i>HH</i>	1	\$68.10	\$68.10
ABS SENSOR <i>HH</i>	1	\$217.90	\$217.90

Handwritten notes and checkmarks on the right side of the table, including 'X' marks and checkmarks indicating item status or completion.

