

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SBY 9368A

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT BUMPER	сит	614.60	614.60
1	FRONT BUMPER REINFORCEMENT	BENT	675.40	500.00
1	FRONT BUMPER LOWER REINFORCEMENT	NOT DAMAGED	337.70	-
2	FRONT BUMPER BRACKET @\$173.10	SERVICEABLE	346.20	-
2	FRONT BUMPER RETAINER @\$22.90	NOT DAMAGED	45.80	-
1	FRONT BUMPER SPONGE	CRACKED	195.70	195.70
1	FRONT BUMPER TOW COVER	CUT	19.30	19.30
2	FRONT BUMPER FOG LAMP @\$150.80	NOT DAMAGED	301.60	-
2	FRONT BUMPER FOG LAMP GARNISH @\$74.70	N/S CUT	149.40	74.70
1	BONNET	NOT DAMAGED	961.90	-
2	HEADLAMP @\$559.10	N/S BROKEN	1,118.20	559.10
1	FRONT GRILLE CHROME	CUT	498.30	400.00
1	FRONT GRILLE EMBLEM	CUT	38.50	38.50
1	RADIATOR SIDE GARNISH	NOT DAMAGED	55.20	-
	LESS 30% DISCOUNT		-1,607.34	-720.57
			3,750.46	1,681.33
	SPECIAL NETT ITEMS			
1	FRONT NUMBER PLATE (SN)	BENT	45.00	25.00
1	SET FRONT BUMPER CLIPS (SN)	NECESSARY	40.00	30.00
1	SET FRONT GRILLE CLIP (SN)	NECESSARY	24.00	24.00
			109.00	79.00
	<u>LABOUR</u>			
	LABOUR CHARGE TO REMOVE-REFIT, PANEL BEAT, STRAIGHTEN, RE-ALIGN AND REPAIR OF FRONT BUMPER, HEADLAMPS BONNET, RADIATOR SUPPORT PANEL, FRONT FENDERS AND OTHERS RELEVANT ACCIDENT DAMAGES.		1,200.00	600.00
	TO CHECK WIRINGS AND LIGHTINGS.		50.00	30.00
	TO SUPPLIED AND APPLIED ANTI RUST TREATMENT TO AFFECTED PANELS.		150.00	30.00

Report Ref No. CS3/LPC20004670/Bvf3e2-1



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No. 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

2,250.00

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	TO PUTTY AND SPRAY PAINTING CHARGES.		1,000.00	400.00
			2,400.00	1,060.00
	GRAND TOTAL		6,259.46	2,820.33

Report Ref No. CS3/LPC20004670/Bvf3e2-1

RECOMMENDED COST OF LUMP SUM REPAIRS

(TO ITS PRE-ACCIDENT CONDITION)

LIM TEOW GUAN

Automotive Assessor

X.S.

ADRIAN LING WAI PING

B.Eng, AMSOE, AMIRTE, AMSAE-A, M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.