

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SERVICE ESTIMATE

85426 - C00001 SL: SERVICE SALES - PC

Ms Xie Tingting
64 Tanah Merah Kechil Avenue
#06-25

Singapore 465531

GST Reg.No:M28920628X

Inv.No. : B&P 0 Page 1

Inv.date : 05/06/2020

WIP No. : 21347

Veh.In/Out:

*Tel.No. : Mobile: 81888063

Reg.No. : SLC3770H

Reg.date : 12/05/2016

Mileage : 0

Chassis No: SAJAC12M0GPV93525

Closed by : Paul Ong Qing Yong

Svc Consultant :

Remarks : Ms Xie Tingting

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
802	TO REPLACE RH F WING MIRROR	0	1800.00	0		1,800.00	S 600
	SIGNAL LAMP, MIRROR COVER, ASSY, ETC						
800	TO SPRAYPAINT ON	0	400.00	0		400.00	S 200
	RHF WING MIRROR COVER						
280	TO CHECK WIRING INLCUDE	0	525.00	0		525.00	S 175
	RESETTING OF ALL ELECTRICAL MODULES						
	MIRROR-DOOR X	1.0 EA	1213.30			1,213.30	S
	MIRROR COVER RH XF R repair	1.0 EA	175.40			175.40	S
	LAMP SCUL	1.0 EA	159.00			159.00	S

RASU
Hp 9001068

1 day
23/07/2020 @ 1010

Revg after repair

Labour Total	2,725.00	Net.....	4,272.70
Parts Total	1,547.70	GST @ 7.0%	299.09
Package Total	0.00	Total.....	4,571.80
		Paid.....	0.00
		Please Pay..	4,571.80

GST: S=StdRated; 0=OutOfScope; Z=ZeroRated