

GOH LEE HWA AUTOMOBILE PTE LTD

Block 5033 Ang Mo Kio Industrial Park 2

#01-255 Singapore 569536

Tel No: (65) 6482 5168

Fax No. (65) 6482 4452

Co.reg no. 200808259H

Reference No: 12620**Date: 12.06.2020****Jayaraman Ramesh****18 Kasai Road****Singapore 808265****KIA Sorento 2.2A Diesel****Estimated Repair Cost for Vehicle Reg. No: SLF 9325 E****REPLACEMENT OF DAMAGED PANELS / PARTS**

1 Pc. Rear Boot	<i>dent / Dented</i>		1,799.00	✓	1178.00
1 Pc. Rear Boot Lock	<i>Dem</i>		298.60	✓	
1 Pc. Rear Boot Garnish	<i>NH</i>		428.00	X	
1 Pc. Rear Boot KIA Emblem	<i>NH</i>		50.00	✓	
2 Pcs. Rear Boot Lamp	<i>NH</i>	@ 299.00	598.00	X	
1 Pc. Rear Boot Weather Slip	<i>NH</i>		410.00	✓	128.00
2 Pcs. Rear Boot Absorber	<i>NH</i>	@ 480.00	960.00	X	
1 Pc. Rear Sorento Emblem	<i>NH</i>		48.00	✓	
1 Pc. Rear ECO Dynamics Emblem	<i>NH</i>		40.00	✓	
1 Pc. Rear C&C Logo	<i>NH</i>		30.00	✓	
2 Pcs. Rear Lamp	<i>NH</i>	@ 365.00	730.00	X	
1 Pc. Rear Bumper Top	<i>Crnt / damaged</i>		746.00	✓	605.00
1 Pc. Rear Bumper Lower	<i>Crnt</i>		720.00	✓	565.00
1 Pc. Rear Bumper Skid Plate	<i>Crnt</i>		199.00	✓	
1 Pc. Rear Bumper Towing Cover	<i>dislodged</i>		59.00	✓	
1 Pc. Rear Bumper Reinforcement	<i>Crack / broken</i>		468.00	✓	
1 Pc. Rear Bumper Under Cover	<i>NH</i>		98.30	X	
6 Pcs. Rear Bumper Parking Sensor	<i>Dem</i>	@ 305.00	610.00	✓	
1 Pc. Rear Bumper Parking Wire	<i>NH</i>		410.00	X	
2 Pcs. Rear Bumper Side Catch	<i>o/s crack N/S NH</i>	@ 199.00	398.00	✓	70.00
12 Pcs. Rear Bumper Clips	<i>NH</i>	@ 5.80	69.60	✓	
2 Pcs. Rear Bumper Reflector	<i>o/s mirrorly crack N/S NH</i>	@ 118.00	236.00	✓	
1 Pc. Rear End Panel	<i>Dented</i>		795.00	✓	681.00
1 Pc. Rear End Panel Garnish	<i>mirrorly broken</i>		389.00	✓	213.00
1 Pc. Rear Spare Tyre Board	<i>NH</i>		389.00	X	
1 Pc. Rear Spare Tyre Sponge	<i>NH</i>		290.80	X	

GOH LEE HWA AUTOMOBILE PTE LTD

Block 5033 Ang Mo Kio Industrial Park 2

#01-255 Singapore 569536

Tel No: (65) 6482 5168

Fax No. (65) 6482 4452

Co.reg no. 200808259H

1 Pc. Rear Exhaust <i>St / dist</i>	1,760.00 ✓	892.00
2 Pcs. Rear Exhaust Mounting <i>Hu</i>	120.00 X	
1 Pc. Rear Windscreen Seal <i>Hu</i>	120.00 ✓	
1 Pc. Rear Windscreen Repair Kit <i>Hu</i>	180.00 ✓	

Total (Panels / Parts): 13,449.30 (SGD)

6622.20
10% 5959.98

LABOR CHARGES

To check wiring & remove, refit wire.	180.00 30/-	
To remove & refit interior garnish side board & all affected area.	250.00 120/-	
To remove & refit windscreen.	180.00 120/-	
To remove & refit exhaust.	180.00 60/-	
To knocking, straightening repair & renew all accident affected area.	1,200.00 750/-	
To respray painting on all accident affected area.	1,300.00 700/-	1850.00
To rust proof all accident affected area.	120.00 60/-	
To wash interior & vacuum.	280.00 80/-	
Total (Labor Charges):	<u>3,690.00 (SGD)</u>	1920.00

GOH LEE HWA AUTOMOBILE PTE LTD

Block 5033 Ang Mo Kio Industrial Park 2

#01-255 Singapore 569536

Tel No: (65) 6482 5168

Fax No. (65) 6482 4452

Co.reg no. 200808259H

TOTAL COST SUMMARY

PANELS / PARTS	13,449.30
LABOR CHARGES	3,690.00
Grand Total:	<u>17,139.30 (SGD)</u>

We shall be glad if you can forward the payment at your early convenience.

Cheque should be crossed and make payable to 'GOH LEE HWA AUTOMOBILE PTE LTD'

Alfred Quah

GOH LEE HWA AUTOMOBILE PTE LTD [WITHOUT PREJUDICE SAVE AS TO COSTS]

15/06/2020 @ 1700hrs

*Not Antenna 6
L/Sunrise 8 days.*

1 year

LKK Auto

Parts 5959.98

Labor 1920.00

7879.98

L/S 6300/-

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Check Part prices.