

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG20006270/DSF3E2
Date: 09/07/2020

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	29143960AT2
Claimant Vehicle No : SLF9325E	Insured Vehicle No :	SLN2203C
Date of Loss: 12/06/2020	Nature of Claim:	TP Claim No: 624847

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLF9325E	Engine No:	D4HBGH280421
Make & Model:	KIA SORENTO, 2.2 (A)	Chassis No:	KNAPH81BMG5236013
Reg. Date:	16/09/2016 (Man. Year: 2016)	Odometer:	72207 km
Colour:	Black		
Engine Capacity:	2199 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/55 R19	Rear Tyre Size:	235/55 R19
Front Left Side:	Kumho 5 mm	Rear Left Side:	Kumho 5 mm
Front Right Side:	Kumho 5 mm	Rear Right Side:	Kumho 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,449.30	5,959.98	7,489.32	55.69
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,690.00	1,920.00	1,770.00	47.97
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	17,139.30	7,879.98	9,259.32	54.02
Approved Total (Overridden) (S\$)		6,300.00		
Nett Amount (S\$)	17,139.30	6,300.00	10,839.30	63.24

INSPECTION

Date of Assignment:	15/06/2020	
Date Inspected:	15/06/2020 Inspected At:	Goh Lee Hwa Automobile Pte Ltd (HQ) Block 5033 Ang Mo Kio Industrial Park 2 #01-255 Singapore 569536
Estimated Period of Repair:	6.0 days	

Adjuster: BRYAN TANI

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 09 Jul 2020)

Parts: M1-SUV KIA SORENTO 2.2 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SLF9325E)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT	Bent / Dented	1,799.00 F	*1,178.00 FL
2	1		*REAR BOOT LOCK	Damaged	298.60 F	*298.60 FL
3	1		*REAR BOOT GARNISH	Not Necessary	428.00 F	*- FL
4	1		*REAR BOOT KIA EMBLEM	Necessary	50.00 F	*50.00 FL
5	2		*REAR BOOT LAMP	Not Necessary	598.00 F	*- FL
6	1		*REAR BOOT WEATHER STRIP	Necessary	410.00 F	*128.00 FL
7	2		*REAR BOOT ABSORBER	Not Necessary	960.00 F	*- FL
8	1		*REAR SORENTO EMBLEM	Necessary	48.00 F	*48.00 FL
9	1		*REAR ECO DYNAMICS EMBLEM	Necessary	40.00 F	*40.00 FL
10	1		*REAR C&C LOGO	Necessary	30.00 F	*30.00 FL
11	2		*REAR LAMP	Not Necessary	730.00 F	*- FL
12	1		*REAR BUMPER TOP	Cut / Distorted	746.00 F	*605.00 FL
13	1		*REAR BUMPER LOWER	Cut	720.00 F	*565.00 FL
14	1		*REAR BUMPER SKID PLATE	Cut	199.00 F	*199.00 FL
15	1		*REAR BUMPER TOWING COVER	Dislodged	59.00 F	*59.00 FL
16	1		*REAR BUMPER REINFORCEMENT	Cracked / Broken	468.00 F	*468.00 FL
17	1		*REAR BUMPER UNDER COVER	Not Necessary	98.30 F	*- FL
18	1		*REAR BUMPER PARKING SENSOR (6PCS)	Damaged	610.00 F	*610.00 FL
19	1		*REAR BUMPER PARKING WIRE	Not Necessary	410.00 F	*- FL
20	1		*REAR BUMPER SIDE CATCH	O/S Cracked / N/S NotNecessary	398.00 F	*70.00 FL
21	12		*REAR BUMPER CLIPS	Necessary	69.60 F	*69.60 FL
22	1		*REAR BUMPER REFLECTOR	O/SMtgCracked/N/SNotNecessary	236.00 F	*118.00 FL
23	1		*REAR END PANEL	Dented	795.00 F	*681.00 FL
24	1		*REAR END PANEL GARNISH	Mtg Broken	389.00 F	*213.00 FL
25	1		*REAR SPARE TYRE BOARD	Not Necessary	389.00 F	*- FL
26	1		*REAR SPARE TYRE SPONGE	Not Necessary	290.80 F	*- FL
27	1		*REAR EXHAUST	Bent / Distorted	1,760.00 F	*892.00 FL
28	2		*REAR EXHAUST MOUNTING	Not Necessary	120.00 F	*- FL
29	1		*REAR WINDSCREEN SEAL	Necessary	120.00 F	*120.00 FL
30	1		*REAR WINDSCREEN REPAIR KIT	Necessary	180.00 F	*180.00 FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$) 13,449.30 6,622.20
- List Item Discount on L Items 0.00/10.00% (\$\$) 0.00 662.22

Total Parts (\$\$) 13,449.30 5,959.98

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO CHECK WIRING & REMOVE, REFIT WIRE	New	180.00	30.00
2	TO REMOVE & REFIT INTERIOR GARNISH SIDE BOARD & ALL AFFECTED AREA	New	250.00	120.00
3	TO REMOVE & REFIT WINDSCREEN	New	180.00	120.00
4	TO REMOVE & REFIT EXHAUST	New	180.00	60.00
5	TO KNOCKING, STRAIGHTENING REPAIR & RENEW ALL ACCIDENT AFFECTED AREAS	New	1,200.00	750.00
6	TO RESPRAY PAINTING ON ALL ACCIDENT AFFECTED AREA	New	1,300.00	700.00
7	TO RUST ROOF ALL ACCIDENT AFFECTED AREA	New	120.00	60.00
8	TO WASH INTERIOR & VACUUM	New	280.00	80.00
Gross Labour Cost (S\$)			3,690.00	1,920.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >