

ASS. REC. BY:

CC4/III 20006152/DBA³

ASSIGNMENT

CDE March 2024

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

7

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Date / Time

Action / Instruction

III SHD 3165Y

28/09/2020

jmw

L/S 11,600/-

with 7 days

J. W.

Date/Time, File Pass to?

1)

Date/Time, File Return to?

2)

Report Format :

Lump Sum / I.B.I. (\$) _____

☐ : Prel. Report
☐ : Final Report

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee:

☐ : Site Insp (\$)
☐ : Interview (\$)
☐ : Tech. Invs (\$)
☐ : Weekend (\$)

☐ : Site Insp (\$)
☐ : Interview (\$)
☐ : Tech. Invs (\$)
☐ : Weekend (\$)

Survey Fee:

Transportation:

S + RS \$ _____

Photos

Others

TOTAL

Veh No:

SHC 8761Z

Yr Regn:

2016, March

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Hyundai I40

c.c

1685

Colour

Blue

A/C: Insured / Std / NI / NA

Sp. Reading

554612

T/Radio: Insured / Std / NI / NA

Eng/No:

D4FDFU595660

C/No:

KMHLB41UMGU085434

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: 205/60 R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Hankook

Front

Rear

R/Bal.

S

mm

R/Bal.

S

mm

L/Bal.

S

mm

L/Bal.

S

mm

D.O.A.

31/05/2020

D.O.I.

08/06/2020

Survey held at

Bjv18t sin ming

Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or

N/S Portion

The U/C / Chassis frame / Body Structure affected due to collision.

BIFROST AUTO PTE LTD

REPAIR ESTIMATE

DATE: 1-Jun-20

INSURANCE: III

MODEL: HYUNDAI I40

VEHICLE NO.: SHC8761Z

DESCRIPTION	QTY	LIST PRICE	AMOUNT
REAR BUMPER NEW <i>Repair</i>	1	\$1,106.00	\$1,106.00
REAR BUMPER CLIP NEW <i>SVC</i>	1	\$19.00	\$19.00
REAR BUMPER RUBBER MAT / I40 PLATE <i>NN</i>	1	\$50.00	\$50.00
REAR FENDER <i>Dent</i>	1	\$2,171.40	\$2,171.40
REAR FENDER UNDER SHIELD(LH) <i>NN</i>	1	\$338.60	\$338.60
REAR DOOR (LH) <i>Dent</i>	1	\$2,201.10	\$2,201.10
REAR DOOR RUBBER (LH) <i>NN</i>	1	\$185.40	\$185.40
REAR DOOR REGULATOR (LH) <i>NN</i>	1	\$660.90	\$660.90
REAR DOOR POWER WINDOW MOTOR <i>NN</i>	1	\$386.20	\$386.20
REAR DOOR LOCK ASSY <i>NN</i>	1	\$468.20	\$468.20
ROCKER PANEL OUTER GARNISH (LH) <i>cut photo</i>	1	\$732.80	\$732.80
REAR TYRE RIM (LH) <i>NN</i>	1	\$650.60	\$650.60
REAR TYRE WHEEL CAP <i>NN</i>	1	\$214.20	\$214.20
REAR WHEEL BEARING ING & HUB <i>401.40</i>	1	\$724.00	\$724.00
REAR TRAILING ARM (LH) <i>NN</i>	1	\$384.00	\$384.00
REAR ASSIST (LH) <i>NN</i>	1	\$219.40	\$219.40
REAR SHOCK ABSORBER (LH) <i>distorted</i> <i>27630</i>	1	\$683.70	\$683.70
REAR SHOCK ABSORBER MOUNTING (LH) <i>NN</i>	1	\$162.60	\$162.60
ABS SENSOR <i>NN</i>	1	\$217.90	\$217.90
REAR CROSS MEMBER <i>NN</i>	1	\$2,021.50	\$2,021.50
STABILIZER BAR <i>NN</i>	1	\$199.60	\$199.60
STABILIZER LINK <i>NN</i>	1	\$85.90	\$85.90
REAR UPPER ARM (LH) <i>NN</i>	1	\$335.75	\$335.75
REAR LOWER ARM (LH) <i>distorted</i>	1	\$353.80	\$353.80
REAR KNUCKLE ARM (LH) <i>distorted</i>	1	\$545.60	\$545.60
BONNET <i>NN</i>	1	\$2,265.90	\$2,265.90
BONNET INSULATOR CLIPS <i>NN</i>	1	\$15.00	\$15.00
FRONT BUMPER COVER <i>1st</i>	1	\$1,052.20	\$1,052.20
FRONT BUMPER GRILLE (LH) <i>NN</i>	1	\$149.20	\$149.20
FRONT BUMPER BRACKET TOP (LH) <i>NN</i>	1	\$44.80	\$44.80
FRONT BUMPER BRACKET (LH) <i>NN</i>	1	\$49.20	\$49.20
FRONT BUMPER RETAINER MOUNTING <i>NN</i>	1	\$76.20	\$76.20
FRONT BUMPER GRILLE AIR DUCT (LH) <i>NN</i>	1	\$126.20	\$126.20
HEADLAMP SUPPORT PANEL ASSY <i>2 grade</i>	1	\$907.40	\$907.40
HEADLAMP (LH) <i>2 monobly broken</i> <i>1388.00</i>	1	\$2,776.00	\$2,776.00
HEADLAMP SUPPORT TOP COVER <i>NN</i>	1	\$222.60	\$222.60
FRONT FENDER (LH) <i>NN</i>	1	\$566.30	\$566.30
FRONT FENDER APRON PANEL (LH) <i>NN</i>	1	\$637.00	\$637.00
FRONT FENDER SHIELD (LH) <i>distorted</i>	1	\$174.90	\$174.90
FRONT DOOR MIRROR SIDE GARNISH <i>NN</i>	1	\$225.00	\$225.00
FRONT DOOR MIRROR (LH) <i>NN</i>	1	\$670.00	\$670.00
FRONT DOOR (LH) <i>Dent</i>	1	\$2,256.40	\$2,256.40
FRONT DOOR RUBBER <i>NN</i>	1	\$196.00	\$196.00

FRONT DOOR GEAR/REGULATOR (LH) <i>HH</i>		1	\$776.80	\$776.80	X
FRONT DOOR POWER MOTOR <i>HH</i>		1	\$442.10	\$442.10	X
FRONT DOOR HINGE UPPER (LH) <i>HH</i>		1	\$113.60	\$113.60	X
FRONT DOOR HINGE LOWER (LH) <i>HH</i>		1	\$125.70	\$125.70	X
FRONT DOOR CHECK (LH) <i>HH</i>		1	\$91.80	\$91.80	X
FRONT WHEEL RIM (LH) <i>2.5t</i>	325.30	1	\$650.60	\$650.60	✓
KNUCKLE ARM (LH) <i>2.5t</i>	552.00	1	\$595.90	\$595.90	✓
FRONT WHEEL BEARING HUB ASSY (LH) <i>2.5t</i>	301.80	1	\$673.20	\$673.20	✓
FRONT SUSPENSION LOWER ARM (LH) <i>2.5t</i>	595.80	1	\$1,104.00	\$1,104.00	✓
FRONT SHOCK ABSORBER ASSY (LH) <i>2.5t</i>	342.20	1	\$684.40	\$684.40	✓
FRONT SHOCK ABSORBER MOUNTING (LH) <i>HH</i>		1	\$217.60	\$217.60	X
STG TIE ROD (LH) <i>2.5t</i>		1	\$186.40	\$186.40	X
STG TIE END (LH) <i>2.5t</i>		1	\$125.20	\$125.20	X
STABILIZER BAR ASSY <i>HH</i>		1	\$463.70	\$463.70	X
STABILIZER BAR LINK (LH) <i>HH</i>		1	\$68.10	\$68.10	X
ABS SENSOR <i>HH</i>		1	\$217.90	\$217.90	X
FRONT DRIVE SHAFT (LH) <i>HH</i>		1	\$2,061.60	\$2,061.60	X
RACK & PINION ASSY <i>HH</i>		1	\$1,820.00	\$1,820.00	X
INTER COOLER <i>HH</i>		1	\$1,032.50	\$1,032.50	X
	14578.40				
SUB TOTAL				\$38,979.55	
LESS 20%	11662.72			\$7,795.91	
DISCOUNTED TOTAL				\$31,183.64	
Rear Door Comfortdelgro & Apps Sticker(LH) <i>HH</i>	SN	1	\$ 80.00	\$ 80.00	✓
REAR TYRE (LH) <i>HH</i>	SN	1	\$216.00	\$216.00	X
FRONT TYRE (LH) <i>HH</i>	80.00	SN	\$216.00	\$216.00	X
SUB TOTAL				\$512.00	
Labour Charge					
Panel Beating		1	\$1,600.00	\$1,600.00	1000/-
Spray Painting Charge		1	\$1,400.00	\$1,400.00	1000/-
Wiring Charge		1	\$100.00	\$100.00	30/-
Tuff Kote		1	\$120.00	\$120.00	40/-
Towing Charge		1	\$80.00	\$80.00	HH
Remove/Refix Cushion & Upholstery Rear		1	\$150.00	\$150.00	80/-
Remove/Refix Rear Windscreen Glass		1	\$120.00	\$120.00	HH
Remove/Refix Reverse Sensor		1	\$120.00	\$120.00	HH
Remove/Refix Undercarriage (RR)		1	\$400.00	\$400.00	150/-
Re-set Rear ABS System		1	\$400.00	\$400.00	HH
Remove/Refix Fuel Tank		1	\$80.00	\$80.00	HH
Remove/Refix Exhaust Pipe		1	\$80.00	\$80.00	HH
Transfer of Door Mechanism FRONT		1	\$80.00	\$80.00	60/-
Re-set Frt Power Window System		1	\$200.00	\$200.00	HH
Transfer of Door Mechanism REAR		1	\$80.00	\$80.00	60/-
Re-set Rear Power Window System		1	\$200.00	\$200.00	HH
Four Wheel Alignment		1	\$120.00	\$120.00	60/-
Remove/Refix Undercarriage (Frt)		1	\$400.00	\$400.00	150/-
Re-set Frt ABS System	2780.00	1	\$200.00	\$200.00	150/-
Remove/Refix Radiator		1	\$90.00	\$90.00	HH
Remove/Refix Aircon & Refill Gas		1	\$130.00	\$130.00	HH
TOTAL LABOUR				\$6,150.00	

ESTIMATE TOTAL**\$ 37,845.64**

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

03/06/2020 e 0900hrs

Not Antenna

2/Summer 7 days.

1 nja

LKK Auto



14522.72
L/S 11,600/-

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Phone Number:

Fax Number:

Customer:		Date:	3/6/2020 10:17 AM
Company:		VIN	
License NO:	SHC8761Z	Technician:	
Odometer:		Order NO:	

VEHICLE ALIGNMENT REPORT

HYUNDAI, i40 G 1.6 GDI, 11-11 (Customized)

Primary Angles			Initial	Specifications		Final
				Min.	Max.	
Front	Caster	Left	----	4°12'	5°12'	----
		Right	----	4°12'	5°12'	----
	Camber	Left	-0°46'	-1°00'	0°00'	-0°46'
		Right	-0°04'	-1°00'	0°00'	-0°05'
	Toe	Left	0°19' *	0°00'	0°12'	0°59' *
		Right	-0°34' *	0°00'	0°12'	-0°45' *
Total		-0°15' *	0°00'	0°24'	0°14'	
Rear	Camber	Left	-1°38' *	-1°30'	-0°30'	-2°12' *
		Right	-2°02' *	-1°30'	-0°30'	-2°04' *
	Toe	Left	0°08'	-0°03'	0°09'	-0°16' *
		Right	-0°05' *	-0°03'	0°09'	-0°05' *
		Total	0°03'	-0°06'	0°18'	-0°20' *
	Thrust Angle		-0°06'	99°59'		0°05'
Secondary Angles			Initial	Specifications		Final
				Min.	Max.	
SAI		Left	----	13°18'	14°18'	----
		Right	----	13°18'	14°18'	----
Included Angle		Left	----	99°59'	99°59'	----
		Right	----	99°59'	99°59'	----
Toe Out On Turns		Left	----	99°59'	99°59'	----
		Right	----	99°59'	99°59'	----
Max Turn Inside		Left	----	99°59'	99°59'	----
		Right	----	99°59'	99°59'	----
Toe Curve Change		Left	----	0°00'	199°59'	----
		Right	----	0°00'	199°59'	----
Setback		Front	0.05" *	99.99"	99.99"	0.05" *
		Rear	-0.32" *	99.99"	99.99"	-0.32" *
Track Width Diff.			0.03"			0.03"
Wheel Base Diff.			0.37"			0.37"
Front Ride Height		Left	----	99.99"	99.99"	----
		Right	----	99.99"	99.99"	----
Rear Ride Height		Left	----	99.99"	99.99"	----
		Right	----	99.99"	99.99"	----
Frame Angle						----