

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20006284/KRA3Q2

Date: 14/01/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100510045

Claimant Vehicle No : PC7958K Insured Vehicle No : SJA3202R

Date of Loss: 29/05/2020 Nature of Claim: TP Claim No: 3528913996SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **PC7958K**
 Make & Model: TOYOTA HIACE, 2.8 D COMMUTER GL (A) Engine No: 1GD8384189
 Reg. Date: 05/04/2019 (Man. Year: 2019) Chassis No: GDH2232001427
 Colour: White Odometer: 72458 km
 Engine Capacity: 2754 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195 R15X8 Rear Tyre Size: 195 R15X8
 Front Left Side: Triangle 9 mm Rear Left Side: Triangle 9 mm
 Front Right Side: Triangle 9 mm Rear Right Side: Triangle 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	530.47	232.57	297.90	56.16
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,220.00	980.00	240.00	19.67
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	1,750.47	1,212.57	537.90	30.73
+ GST 7.00/7.00% (S\$)	122.53	84.88	37.65	30.73
Nett Amount (S\$)	1,873.00	1,297.45	575.55	30.73
+ Loss of Use (4.0 x S\$60.00/day) (S\$)		240.00		
Nett Liability (S\$)		1,537.45		

INSPECTION

Date of Assignment: 05/06/2020

Date Inspected: 18/06/2020 Inspected At:

Cheng Hoe Motor Pte Ltd (Yishun)
 Blk 1019 #01-374/382, Yishun
 Industrial Park A
 Singapore 768761

Estimated Period of Repair: 4.0 days

Adjuster: KENNETH KONG

Manager: Jaslin Kok Chin Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Repair	357.40 FL	*- FL
2	6		*REAR BUMPER CLIP	Necessary	21.00 FL	*21.00 FL
3	1		*REAR BUMPER SIDE RETAINER RH	Serviceable	39.80 FL	*- FL
4	1		*TAILLAMP RH	Cracked	289.10 FL	*289.10 FL
F=Franchise part. L=ListItemDisc.						
					Sub Total (\$)	707.30
					- List Item Discount on L Items 25.00/25.00% (\$)	310.10
						176.83
					Total Parts (\$)	232.57

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE AND REFIX REAR BUMPER ,TAILLAMP ,KNOCK AND REPAIR REAR RH SIDE PANEL AND RE-ALIGN TO SAME	New	500.00	400.00
2	TO REMOVE AND REFIX REAR SEAT ,CARPET ,GARNISH ETC	New	120.00	80.00
3	TO PUTTY AND RESPRAY ON REAR RH SIDE PANEL ,TAILLAMP LOWER GARNISH ,REAR BUMPER	New	600.00	500.00
Gross Labour Cost (\$)			1,220.00	980.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >