

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)
 51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
 Singapore 408933
 Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG20006285/QRS3Q2
Date: 25/03/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.	Policy No: 1900113290	
Claimant Vehicle No : SMB37E	Insured Vehicle No : GBH4451P	
Date of Loss: 03/06/2020	Nature of Claim: TP	Claim No: 7538877788SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SMB37E		
Make & Model: MERCEDES-BENZ OC500LE1830H, 12.0 D (A)	Engine No: 45795400127888	
Reg. Date: 28/11/2008 (Man. Year: 2008)	Chassis No: WEB63442021000098	
Colour: Black	Odometer: 852058 km	
Engine Capacity: 11967 cc		
Market Value/New Car Price: N/A		
Sum Insured (S\$): Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable): Yes	Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes	Engine Modification: No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 275/70 R22.5	Rear Tyre Size: 275/70 R22.5	
Front Left Side: Continental 6 mm	Rear Left Side: Continental 6 mm	
Front Right Side: Continental 6 mm	Rear Right Side: Continental 6 mm	

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,125.00	1,125.00	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	530.00	265.00	265.00	50.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	1,655.00	1,390.00	265.00	16.01
Approved Total (Overridden) (S\$)		1,150.00		
Nett Amount (S\$)	1,655.00	1,150.00	505.00	30.51
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment: 08/06/2020		
Date Inspected: 08/06/2020	Inspected At:	SMRT Automotive Services Pte Ltd (Woodlands) 60 Woodlands Industrial Park E4 Singapore 757705
Estimated Period of Repair: 5.0 days		

Adjuster: OI SUN PIN

Manager: Jaslin Kok Chin Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*MIRROR VIEW :REAR ELECTRICAL ,LH ,MBOC500	Cracked	1,250.00 FL	*1,250.00 FL
F=Franchise part. L=ListItemDisc.						
Sub Total (\$)					1,250.00	1,250.00
- List Item Discount on L Items 10.00/10.00% (\$)					125.00	125.00
Total Parts (\$)					1,125.00	1,125.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE & INSTALL FRONT VIEW MIRROR LH	New	530.00	265.00
Gross Labour Cost (S\$)			530.00	265.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >