## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd. Our File No: CC3/AIG20006287/ACF3E2 AIG Building, 78 Shenton Way, #09-16

05/03/2021 Date: Singapore 079120

**REFERENCE** 

Insured/Claimant: WOON VOON CHING Policy No: 1800072803

Nature of Claim: Date of Loss: 05/06/2020 OD Claim No: 4138096735SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

Reg No: SMA9045C

AUDI A3, 999cc SEDAN TFSI (A) Engine No: Make & Model: CHZ442513

Reg. Date: 22/06/2018 (Man. Year: 2018) Chassis No: WAUZZZ8V9J1059509

Colour: Grey Odometer: 37514 km

999 cc **Engine Capacity:** Market Value/New Car Price: S\$87,000.00

Sum Insured (S\$): **Market Value/New Car Price** 

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Footbrake (Serviceable): Yes Yes

**Engine Modification:** Pre-accident Condition: Handbrake (Serviceable): Yes No

**CONDITION OF TYRES** 

205/55 R16 Rear Tyre Size: Front Tyre Size: 205/55 R16 Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		12,307.00	9,033.92	3,273.08	26.60
Miscellaneous Items		0.00	0.00	0.00	
Labour		18,432.00	12,107.00	6,325.00	34.32
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Calculated Gross Total (S\$)	30,739.00	21,140.92	9,598.08	31.22
	- Excess (S\$)	600.00	600.00	0.00	0.00
	(S\$)	30,139.00	20,540.92	9,598.08	31.85
	+ GST 7.00/7.00% (S\$)	2,109.73	1,437.86	671.87	31.85
	Nett Amount (S\$)	32,248.73	21,978.78	10,269.95	31.85

**INSPECTION** 

Date of Assignment: 10/06/2020

Premium Automobiles Pte Ltd (UBI)

55 Ubi Road 1 Date Inspected: 10/06/2020 Inspected At:

Singapore 408699

Estimated Period of Repair: 14.0 days

Adjuster: **ADRIAN LING** Manager: **CELINE FONG** 

# **REPAIR DETAILS**

# **Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SECTIONAL PART - SIDE PANEL - LH	Dented	2,195.00 FS	*1,756.00 FS
2	1		*REAR WINDSCREEN	Necessary	766.00 FS	*612.80 FS
3	1		*SIDE WINDOW - LH	Necessary	537.00 FS	*429.60 FS
4	1		*PRIMER	Necessary	19.00 FS	*15.20 FS
5	1		*FRONT DOOR - LH	Dented	2,375.00 FS	*1,900.00 FS
6	1		*FRONT DOOR OUTER SEAL	Necessary	151.00 FS	*120.80 FS
7	1		*BONDING AGENT	Necessary	46.00 FS	*36.80 FS
8	1		*CLEANING SOLUTION	Necessary	64.00 FS	*51.20 FS
9	1		*FRONT DOOR ATTACHMENT PARTS	Not Necessary	121.00 FS	*- FS
10	1		*FRONT DOOR CATCH	Not Necessary	89.00 FS	*- FS
11	1		*DOOR HINGE HAL-UPPER PART-LH UPPER	Not Necessary	75.00 FS	*- FS
12	1		*DOOR HINGE HALF-LOWER PART-LH UPPER	Not Necessary	45.00 FS	*- FS
13	1		*DOOR HINGE HALF-UPPER PART-LH LOWER	Not Necessary	45.00 FS	*- FS
14	1		*DOOR HINGE HALF-LOWER PART-LH LOWER	Not Necessary	75.00 FS	*- FS
15	1		*REAR DOOR - LH	Dented	2,375.00 FS	*1,900.00 FS
16	1		*REAR DOOR OUTER SEAL - LH	Necessary	151.00 FS	*120.80 FS
17	1		*BONDING AGENT	Necessary	46.00 FS	*36.80 FS
18	1		*CLEANING SOLUTION	Necessary	64.00 FS	*51.20 FS
19	1		*DOOR ATTACHMENT PARTS	Not Necessary	227.00 FS	*- FS
20	1		*REAR DOOR CATCH	Damaged	99.00 FS	*79.20 FS
21	1		*WHEEL HOUSING LINER	Not Necessary	226.00 FS	*- FS
22	1		*WHEEL HOUSING LINER ATTACHMENT PARTS	Not Necessary	84.00 FS	*- FS
23	1		*ACRYLIC SEALANT	Necessary	180.00 FS	*180.00 FS
24	1		*CAVITY WAX	Necessary	140.00 FS	*140.00 FS
25	1		*STONE CHIP	Necessary	180.00 FS	*180.00 FS
26	1		*METAL FILLER POWDER	Necessary	280.00 FS	*280.00 FS
27	1		*1/4 GLASS SEALANT	Necessary	100.00 FS	*100.00 FS
28	1		*REAR WINDSCREEN SEALANT	Necessary	200.00 FS	*200.00 FS
29	1		*SUNDRIES	Necessary	400.00 FS	*81.92 FS
30	1		*WING MIRROR MOUNTING LHS	Damaged	952.00 FS	*761.60 FS
F=Fra	anchise	part. S=SpcN	lett.	Total Parts (S\$)	12,307.00	9,033.92

Report was unsubmitted during this print-out.

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

# Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	TO REMOVE AND TRANSFER REAR PARKING AID. CHECK FUNCTION AND RENEW ACCORDING TO DAMAGE	New	280.00	280.00
2	TO RENEW REAR WINDSCREEN AND LHS 1/4 GLASS TO FACILITATE FENDER RENEWAL	New	600.00	600.00
3	TO INSTALL SOLAR FILM FOR REAR WINDSCREEN AND 1/4 GLASS	New	400.00	400.00
4	TO DISLODGE AND REINSTALL REAR WIRE HARNESS FOR LIGHTS, BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO EQUIPMENT	New	1,400.00	1,400.00
5	TO REMOVE AND REINSTALL REAR SEAT, BACK REST, HAT TRAY, ABCI PILLAR TRIMS, LUGGAGE COMPARTMENT TRIMS. DISLODGE ROOF LINER AND DISENGAGE CURTAIN AIRBAG ETC	D New	1,400.00	1,400.00
6	TO REMOVE AND TRANSFER LHS REAR DOOR AND LHS FRONT DOORS MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES	New	560.00	560.00
7	TO DISMANTLE REAR BUMPER, REAR LID, LHS REAR DOOR AND LHS FRONT DOOR. CUT OUT AND WELD LHS REAR FENDER. TO RENEW LHS REAR DOOR AND LHS FRONT DOOR. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	7,000.00	4,000.00
8	TO RESPRAY LHS REAR FENDER, LHS REAR DOOR, LHS FRONT DOOR DOOR HANDLE, LHS SILL PANEL, DOOR ENTRANCES, ROOF CHANNEL DRAIN PANEL AND END PANELLING. TO CARRY OUT STONE CHIP TREATMENT AND JOINT SEALER WORKS		5,950.00	3,125.00
9	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
10	TO RESPRAY LHS WING MIRROR COVER	New	300.00	150.00
11	TO DISMANTLE LHS FRONT DOOR PANEL TRIM. TO REMOVE AND REINSTALL LHS WING MIRROR ASSY	New	350.00	0.00
	Gross Labou	r Cost (S\$)	18,432.00	12,107.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >