



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

LONPAC INSURANCE BHD
300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555

INV No. AC2005618
INV Date 17/08/2020
Reference CC4/LPC20006289/R1bs3n2
Code LPC2



PROFESSIONAL SERVICE FEE

Vehicle No. SKD 8870B
Insured Veh. GBC 9220H
Claim No. 20/20/20/VC05/023386
Policy No. Z/20/VC05/004578-001
Accident Date 09/06/2020
Inspection Date 10/06/2020

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

HYN



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

LONPAC INSURANCE BHD

Ref : CC4/LPC20006289/R1bs3n2

300 BEACH ROAD
#17-04/07 THE CONCOURSESINGAPORE 199555

Date : 17-08-2020



Code : LPC2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBC 9220H	Veh. Inspected	SKD 8870B
Policy No.	Z/20/VC05/004578-001	Coverage (\$)	0.00
Claim No.	20/20/20/VC05/023386	Excess (\$)	0.00
Assign From	KENNY LIM	Assign Date	10/06/2020

2. Vehicle Particulars & Condition

Make & Model	TOYOTA COROLLA ALTIS 1.6	c.c	1598
Engine No.	HIDDEN	Year of Reg.	2012
Chassis No.	MR053REE104128095	Colour	GREY
Odometer	180525	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/55 R15	DUNLOP	6 mm
L/H Front Tyre	195/55 R15	DUNLOP	6 mm
R/H Rear Tyre	195/55 R15	DUNLOP	6 mm
L/H Rear Tyre	195/55 R15	DUNLOP	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	09/06/2020	Inspection Date	10/06/2020
Survey held at	JUN TAIYO (S) PTE LTD NO. 8 FOURTH LOK YANG ROAD SINGAPORE 629705 (JURONG)		

5a. Remarks

- A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	5 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKD 8870B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT BUMPER	DEFORMED	486.00	486.00
10	FRONT BUMPER CLIP @\$5.50	NECESSARY	55.00	55.00
1	FRONT BUMPER RETAINER RH	CRACKED	58.00	58.00
1	CENTER GRILLE	SERVICEABLE	343.00	-
1	HEADLAMP RH	BROKEN	650.00	650.00
1	FRONT FENDER RH	BENT	610.00	610.00
1	FRONT FENDER SHIELD RH	TORN	237.00	237.00
10	FRONT FENDER SHIELD CLIP @\$5.50	NECESSARY	55.00	55.00
1	SUPPORT PANEL	TO REPAIR SEE LABOUR	721.00	-
	LESS 25% DISCOUNT		-803.75	-537.75
			2,411.25	1,613.25
<u>LABOUR</u>				
	PANEL BEAT,CUT,WELD,RE-ALIGN & REPLACE DAMAGED PARTS OF FRONT AFFECTED AREA.INCLUSIVE OF THE REPAIR OF SUPPORT PANEL.		1,250.00	500.00
	PUTTY,BLEND AND SPRAY PAINT ON FRONT AFFECTED AREA.		1,000.00	600.00
	CHECK WIRING,RE-ALIGN HEADLAMPS AND ENSURE PROPER FUNCTIONING.		80.00	40.00
	CHECK,RE-ADJUST AND COMPUTERISE WHEEL ALIGNMENT/SIDE SLIP TEST. (ADDITIONAL)		180.00	80.00
			2,510.00	1,220.00
GRAND TOTAL			4,921.25	2,833.25
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,250.00

Report Ref No. CC4/LPC20006289/R1bs3n2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SKD 8870B

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SKD 8870B

RE-INSPECTION

