

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road, #16-00 Springleaf Tower
Singapore 079909

Our File No: CS/CTI20006293/GTF3E2

Date: 04/11/2020

REFERENCE

Insured/Claimant: AMBULANCE MEDICAL
SERVICES PTE LTD

Policy No: DMCVSNA00000712000

Date of Loss: 10/06/2020

Nature of
Claim: OD

Claim
No: SNM20D202104/C02/TANGHL2

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKS9790M**

Make & Model: NISSAN NV350 HR MICROBUS, 2.5 D 2.5 4DR 5AT
ABS D/A (A)

Engine No: YD25362984A

Reg. Date: 18/05/2015 (Man. Year: 2014)

Chassis No: JN1UC4E26Z0002290

Colour: Silver

Odometer: 211783 km

Engine Capacity: 2488 cc

Market Value/New Car Price: S\$64,000.00

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195R15

Rear Tyre Size: 195R15

Front Left Side: Bridgestone 6 mm

Rear Left Side: Bridgestone 6 mm

Front Right Side: Bridgestone 6 mm

Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	19,960.38	13,425.29	6,535.09	32.74
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,450.00	2,350.00	1,100.00	31.88
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	23,410.38	15,775.29	7,635.09	32.61
- Excess (S\$)	1,000.00	1,000.00	0.00	0.00
(S\$)	22,410.38	14,775.29	7,635.09	34.07
+ GST 7.00/7.00% (S\$)	1,568.73	1,034.27	534.46	34.07
Nett Amount (S\$)	23,979.11	15,809.56	8,169.55	34.07

INSPECTION

Date of Assignment: 15/06/2020

Date Inspected: 12/06/2020 Inspected At:

Autosoon Pte Ltd (HQ)
BLK 176 SIN MING DRIVE #01-10, Sin
Ming Autocare
Singapore 575721

Estimated Period of Repair: 8.0 days

Adjuster: XING GUO QIANG**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 04 Nov 2020)	
Parts:	N/A	NISSAN NV350 HR MICROBUS 2.5 D 2.5 4DR 5AT ABS D/A (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKS9790M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*WINDSCREEN PANEL ASSY (WCP)	Buckled	1,350.20 F	*946.14 F
2	1		*WINDSCREEN PANEL GARNISH (WCP)	Cracked	206.80 F	*145.76 F
3	1		*WIPER MOTOR PANEL (WCP)	Bent	164.30 F	*115.01 F
4	1		*WIPER LINKAGE PANEL ASSY (WCP)	Not Necessary	416.30 F	*- F
5	1		*RADIATOR GRILLE ASSY (WCP)	Cracked	521.50 F	*364.70 F
6	1		*RADIATOR GRILLE EMBLEM (WCP)	Necessary	79.90 F	*55.93 F
7	1		*BUMPER FACIAL (WCP)	Distorted	943.70 F	*660.59 F
8	6		*BUMPER FACIAL CLIPS (WCP)	Necessary	22.80 F	*15.96 F
9	1		*BUMPER REINFORCEMENT ASSY (WCP)	Torn	987.00 F	*690.90 F
10	1		*BUMPER SIDE RETAINER (WCP)	O/s Cracked/N/s Not Necessary	362.00 F	*123.40 F
11	1		*O/S FOG LAMP ASSY (WCP)	Cracked	311.80 F	*218.30 F
12	1		*O/S FOG LAMP COVER (WCP)	Cracked	120.70 F	*84.00 F
13	1		*O/S HEAD LAMP ASSY (WCP)	Distorted	443.30 F	*310.31 F
14	1		*O/S PANEL ASSY (WCP)	Buckled	534.60 F	*373.80 F
15	1		*TURBO CHARGER INTERCOOLER HOSE (WCP)	Cut	80.00 F	*56.00 F
16	1		*STEERING COLUMN ASSY (WCP)	Jammed	1,354.00 F	*947.80 F
17	1		*PEDALS COMBINATION BRACKET (WCP)	Bent	189.30 F	*132.50 F
18	1		*RADIATOR GRILLE SUPPORT PANEL (WCP)	Buckled	212.30 F	*148.60 F
19	1		*RADIATOR GRILLE O/S SUPPORT STAY (WCP)	Bent	89.30 F	*62.51 F
20	1		*RADIATOR SECONDARY COWLING (WCP)	Cracked	191.00 F	*133.70 F
21	1		*BUMPER O/S BRACKET (WCP)	Bent	117.20 F	*82.04 F
22	1		*FRONT PANEL LOWER SUPPORT ASSY (WCP)	Buckled	355.30 F	*248.70 F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
23	1		*FRONT O/S HEAD LAMP SUPPORT PANEL (WCP)	Buckled	155.10 F	*108.50 F
24	1		*STEERING COLUMN SHAFT COVERING (WCP)	Deformed	89.30 F	*62.51 F
25	1		*ENGINE OIL COOLER ASSY (WCP)	Distorted	588.30 F	*411.80 F
26	1		*BRAKE BOOSTER ASSY-USED (WCP)	Not Necessary	1,271.90 F	*- F
27	1		*BRAKE VACUUM BOOSTER PIPE ASSY (WCP)	Broken	129.30 F	*90.50 F
28	1		*AIR CON EVAPORATOR COIL AND HOUSING (WCP)	Cracked	2,290.00 F	*1,603.00 F
29	1		*TURBO CHARGER INTERCOOLER ASSY (WCP)	Distorted	2,121.60 F	*1,909.44 F
30	1		*AIR CON BLOWER MOTOR HOUSING UNIT (WCP)	Cracked	714.00 F	*642.60 F
31	1		*INSTRUMENT DASH BOARD ASSY (WCP)	Broken	1,233.70 F	*1,110.30 F
32	1		*INSTRUMENT SUPPORT REINFORCEMENT ASSY (WCP)	Bent	499.30 F	*349.51 F

F=Franchise part.

Sub Total (S\$)	18,145.80	12,204.81
+ Margin on L,N Items 10.00/10.00% (S\$)	1,814.58	1,220.48
Total Parts (S\$)	19,960.38	13,425.29

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO SUPPLY WINDSCREEN SEALANT AND DAM RUBBER	New	180.00	50.00
2	TO REMOVE WINDSCREEN TO FACILITATE REPLACE PANELS	New	150.00	100.00
3	TO REMOVE INSTRUMENT BOARD,STEERING COLUUM,PEDALS TO FACILITATE CUT/HOT WORKS AND WELD PANELS	New	280.00	250.00
4	TO REMOVE INTERIOR AIR CON EVAPORATOR,HEAT EXCHANGER COIL,BLOWER MOTOR HOUSING TO REPLACE PANELS.REFILL GAS	New	280.00	200.00
5	TO REWIRE AFFECTED SECTION AND REFOCUS HEAD LAMP BEAM	New	80.00	30.00
6	TO PUTTY AND RESPRAY DAMAGED FRONT SECTION INCLUDE DOOR	New	850.00	650.00
7	TO CUT/REMOVE DAMAGED PANEL,RESTRAIGHTEN/RECONDITION WINDSCREEN PILLARS,FRONT CHASSIS CROSSMEMBER INCLUDE WELD/FIX REPLACE/REALIGN BUMPER AND PANELS IN REPAIR	New	1,400.00	900.00
8	TO REMOVE AND REPLACE TURBO CHARGES INTERCOOLER	New	50.00	30.00
9	TO COMPUTER WHEEL REALIGNMENT AFTER REFIX STEERING ASSY	New	80.00	40.00
10	TO TOW AMBULANCE ON DOLLY WHEELS,RECEIPT ENCLOSED	New	100.00	100.00
Gross Labour Cost (\$\$)			3,450.00	2,350.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >