



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLE 8023M

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	FRONT SUPPORT PANEL	NOT NECESSARY	1,024.00	-
1	FRONT L/H HEADLAMP ASSY	CRACKED	2,355.00	2,355.00
1	FRONT L/H HEADLAMP TOP RUBBER MOULDING	NOT NECESSARY	125.00	-
1	FRONT RADIATOR GRILLE ASSY	CRACKED	595.00	595.00
1	FRONT BUMPER FACE	DEFORMED	1,890.00	1,890.00
1	FRONT BUMPER REINFORCEMENT	NOT NECESSARY	865.00	-
1	FRONT BUMPER REINFORCEMENT SUPPORT GARNISH	DEFORMED	125.00	125.00
8	FRONT BUMPER CLIPS	NECESSARY	50.00	50.00
2	FRONT BUMPER SIDE SUPPORT CLIPS	NECESSARY	30.00	30.00
	LESS 10% DISCOUNT		-	-504.50
			7,059.00	4,540.50
<b><u>LABOUR</u></b>				
	TO DISM/REWIRE FRONT DAMAGED PORTION AND REFOCUS HEADLAMP.		100.00	30.00
	TO RESET ECU AFTER REPAIR.		120.00	80.00
	TO PANEL BEAT DAMAGED CHASSIS FRAME PORTION AND RENEW PARTS.		700.00	350.00
	TO PUTTY AND RESPRAY DAMAGED PORTION.		600.00	250.00
			1,520.00	710.00
<b>GRAND TOTAL</b>			<b>8,579.00</b>	<b>5,250.50</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>4,200.00</b>

Report Ref No. CS/AWA20006301/Acf3e2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.