

友尼摩哆公司 UNIMOTOR COMPANY

一號加基武吉六道一樓門牌九十四號 新加坡郵區四一七八八三

AUTOBAY @ KAKI BUKIT

No. 1 KAKI BUKIT AVE 6 #01-94 SINGAPORE 417883

TELEPHONE: 6748 2795 FAX: 6747 2373

Registration No.: 203165/00D

YVIAS84ABE1181314. TP AWA. LKK (MOTOR CLAIM DEPT) DATE:11/06/2020 OUR REF:UAPL1389 REPAIR ESTIMATE TO YOUR ABOVE VOLVO S80 NO: SLE8023M SPECIAL NETT: 1024 X 1 FRONT SUPPORT PANEL NEM ruch 2355 1 FRONT L/H HEADLAMP ASSY 125 x 1 FRONT L/H HEADLAMP TOP RUBBER MOULDING 1 FRONT RADIATOR GRILLE ASSY Could
1 FRONT BUMPER FACE Deland 1 FRONT BUMPER REFORCEMENT New 125 ~ 1 FRONT BUMPER REFORCEMENT SUPPORT GARNISH 50. 8 FRONT BUMPER CLIPS 30. 2 FRONT BUMPER SIDE SUPPORT CLIPS PLL

LABOUR CHARGES:-

TO DISM/REWIRE FRONT DAMAGED PORTION AND REFOCUS HEADLAMP,

TO RESET ECU AFTER REPAIR

TO PANEL BEAT DAMAGED CHASSIS FRAME PORTION AND RENEW PARTS

TO PUTTY AND RESPRAY DAMAGED PORTION

454050

\$ 100.00 30

120.00 100 80

700.00 350

\$ 600.00 250.

710

LKK Auto Consultants hence notify the Repairer of the following:

- . To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- · Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

tole: 525050

43: 42K

03Days

(42K)