

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC4/AIG20006302/TEA3Q2**Date:** 19/04/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800064356
<b>Claimant Vehicle No :</b>	SH9432K	<b>Insured Vehicle No :</b>	FBM9587Y
Date of Loss:	12/06/2020	Nature of Claim:	TP
		Claim No:	9351161718SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SH9432K</b>		
Make & Model:	HYUNDAI I40, 1.7 D CRDI F/L ABS AIRBAG 4DR (A)	Engine No:	D4FDGU614116
Reg. Date:	12/05/2016 (Man. Year: 2016)	Chassis No:	KMHLB41UMGU087940
Colour:	Blue	Odometer:	486447 km
Engine Capacity:	1685 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	West Lake 6 mm	Rear Left Side:	West Lake 6 mm
Front Right Side:	West Lake 6 mm	Rear Right Side:	West Lake 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	952.16	934.24	17.92	1.88
Miscellaneous Items	0.00	0.00	0.00	
Labour	600.00	480.00	120.00	20.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>1,552.16</b>	<b>1,414.24</b>	<b>137.92</b>	<b>8.89</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>1,150.00</b>		
<b>(S\$)</b>	1,552.16	1,150.00	402.16	25.91
<b>+ GST 7.00/7.00% (S\$)</b>	108.65	80.50	28.15	25.91
<b>Nett Amount (S\$)</b>	<b>1,660.81</b>	<b>1,230.50</b>	<b>430.31</b>	<b>25.91</b>
<b>Global Sum Settlement (S\$)</b>		<b>0.00</b>		

INSPECTION

Date of Assignment:	15/06/2020	
Date Inspected:	15/06/2020	Inspected At: ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive Singapore 508969
Estimated Period of Repair:	2.0 days	

**Adjuster:** MOHD TAUFIKH BIN HAMID**Manager:** Asher Sng Rong Yi*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BUMPER W LIP & FOG	Deformed	1,052.20 FL	*1,052.20 FL
2	10		*HYUNDAI BUMPER COVER CLIP	Necessary	22.00 FL	*22.00 FL
3	1		*BRKT ASSY -FR BPR UP	Not Necessary	22.40 FL	*- FL
4	1		*COVER -FR FOG BLANKI	Cut	93.60 FL	*93.60 FL
F=Franchise part. L=ListItemDisc.						
					Sub Total (S\$)	1,190.20 1,167.80
					- List Item Discount on L Items 20.00/20.00% (S\$)	238.04 233.56
					Total Parts (S\$)	952.16 934.24

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	PANEL BEATING	New	350.00	280.00
2	SPRAYPAINT ON AFFECTED AREA	New	250.00	200.00
<b>Gross Labour Cost (S\$)</b>			<b>600.00</b>	<b>480.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >