

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Lonpac Insurance Bhd
300 Beach Road, #17-04/07 The Concourse
Singapore 199555

Our File No: CS/LPC20006303/KSF3E2

Date: 07/08/2020

REFERENCE

Insured/Claimant: YEW HUAT SCAFFOLDING &
CONSTRUCTION PTE LTD

Policy No: Z19VC05002971

Date of Loss: 01/06/2020

Nature of Claim: OD Claim No: 19/20/20/VC05/023378

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: YN8545Y

Make & Model: ISUZU NPR75UH5A, 5.2 D (M)

Engine No: 4HK1357154

Reg. Date: 11/08/2015 (Man. Year: 2015)

Chassis No: JAANPR75HF7104330

Colour: Green

Odometer: 194827 km

Engine Capacity: 5193 cc

Market Value/New Car Price: S\$34,000.00

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/75 R17.5	Rear Tyre Size:	215/75 R17.5 (D)
Front Left Side:	Bridgestone 9 mm	Rear Left Side:	TAITONG 9/9 mm
Front Right Side:	Bridgestone 9 mm	Rear Right Side:	TAITONG 9/9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,799.00	10,712.25	1,086.75	9.21
Miscellaneous Items	1,388.00	1,363.00	25.00	1.80
Labour	5,925.00	4,425.00	1,500.00	25.32
Paintwork Labour	0.00	0.00	0.00	
Towing	80.00	0.00	80.00	100.00
Calculated Gross Total (S\$)	19,192.00	16,500.25	2,691.75	14.03
Approved Total (Overridden) (S\$)		13,200.00		
- Excess (S\$)	0.00	700.00	-700.00	
(S\$)	19,192.00	12,500.00	6,692.00	34.87
+ GST 7.00/7.00% (S\$)	1,343.44	875.00	468.44	34.87
Nett Amount (S\$)	20,535.44	13,375.00	7,160.44	34.87

INSPECTION

Date of Assignment: 10/06/2020 Present Location:

Date Inspected: 11/06/2020 Inspected At:

S & H Motor Pte Ltd (Sin Ming)

S & H Motor Pte Ltd (Sin Ming)

160 Sin Ming Drive #07-02, Sin Ming

AutoCity

Singapore 575722

Estimated Period of Repair: 18.0 days

Adjuster: KENNETH KONG**Manager:** Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 07 Aug 2020)

Parts: N/A ISUZU NPR75UH5A 5.2 D (M) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for YN8545Y)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*Rear number plate lamp (WCP)	Cracked	30.00 F	*30.00 F
2	1		*Front bumper (WCP)	Bent	550.00 F	*550.00 F
3	1		*LH front bumper bracket (WCP)	Bent	150.00 F	*150.00 F
4	1		*LH front bumper fog lamp (WCP)	Mtg Cracked	150.00 F	*150.00 F
5	1		*LH head lamp (WCP)	Broken	320.00 F	*320.00 F
6	1		*LH signal lamp (WCP)	Cracked	125.00 F	*125.00 F
7	1		*LH top end garnish (WCP)	Cracked	190.00 F	*190.00 F
8	1		*LH outer mirror big (WCP)	Missing	145.00 F	*145.00 F
9	1		*LH outer mirror small (WCP)	Missing	95.00 F	*95.00 F
10	1		*LH outer mirror arm handle (WCP)	Missing	320.00 F	*320.00 F
11	1		*LH outer mirror cover top (WCP)	Missing	35.00 F	*35.00 F
12	2		*LH outer mirror black cover top (WCP)	Missing	30.00 F	*30.00 F
13	1		*Front windscreen glass (WCP)	Cracked	850.00 F	*850.00 F
14	1		*Front windscreen glass moulding (WCP)	Necessary	220.00 F	*220.00 F
15	1		*RH rear fuel tank (WCP)	Bent	680.00 F	*680.00 F
16	1		*RH rear fuel tank filter (WCP)	Serviceable	120.00 F	*- F
17	1		*Gearbox mounting (WCP)	Cracked	115.00 F	*115.00 F
18	1		*Gearbox mounting bracket (WCP)	Distorted	160.00 F	*160.00 F
19	1		*RH engine mounting (WCP)	Cracked	145.00 F	*145.00 F
20	1		*LH engine mounting (WCP)	Cracked	145.00 F	*145.00 F
21	1		*RH engine mounting bracket (WCP)	Distorted	170.00 F	*170.00 F
22	1		*LH engine mounting bracket (WCP)	Distorted	170.00 F	*170.00 F
23	1		*Engine fan blade (WCP)	Distorted	180.00 F	*180.00 F
24	1			Repair	-	*- F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
			*Front drive cabin hinge (NPA)			
Supplementary #1						
25	1		*Front right cabin lock (WCP)	Distorted	480.00 F	*480.00 F
26	1		*Front left cabin lock (WCP)	Distorted	480.00 F	*480.00 F
27	1		*Front lock pin-link pin (WCP)	Bent	280.00 F	*280.00 F
28	1		*Radiator (WCP)	Punctured	1,300.00 F	*1,300.00 F
29	1		*Engine mounting lower cross member (WCP)	Bent	480.00 F	*480.00 F
30	1		*Fan Cowling (WCP)	Cracked	180.00 F	*180.00 F
31	1		*Front drive cabin front hinger (WCP)	Repair	550.00 F	*- F
32	1		*Front driver cabin rear right hinge (WCP)	Distorted	460.00 F	*460.00 F
33	1		*Front driver cabin rear left hinge (WCP)	Distorted	460.00 F	*460.00 F
34	1		*Oil Tank bracket (WCP)	Bent	220.00 F	*220.00 F
35	1		*Gear box mounting (WCP)	Repeated	115.00 F	*- F
36	1		*Gear box mounting bracket (WCP)	Repeated	160.00 F	*- F

F=Franchise part.

Sub Total (S\$)	10,260.00	9,315.00
+ Margin on L,N Items 15.00/15.00% (S\$)	1,539.00	1,397.25
Total Parts (S\$)	11,799.00	10,712.25

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	Front number plate (BENT)	35.00	25.00
2	1	Front windscreen inner rubber seal (NECESSARY)	45.00	45.00
3	1	Front windscreen sealant (NECESSARY)	68.00	68.00
4	1	IU Bracket (NECESSARY)	25.00	25.00
5	1	Prop shaft coupling (used) (JAMMED)	200.00	200.00
6	1	Prop shaft front (used) (BENT)	450.00	450.00
7	1	Prop shaft rear (used) (BENT)	450.00	450.00
8	1	Rear number plate (BENT)	35.00	20.00
9	1	Rear number plate top wood (CRACKED)	80.00	80.00
Sub Total (\$\$)			1,388.00	1,363.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	To remove and reinstall front windscreen and conduct water leak test	New	150.00	100.00
2	To disconnect wire harness to facilitate repairs and check for damage and reconnect wiring system and check for full functionality. To focus headlamp	New	35.00	35.00
3	To repair rear cargo wood panels	New	220.00	150.00
4	To remove and replace rear fuel tank. To repair fuel tank brackets	New	80.00	60.00
5	To remove and check engine, gearbox, radiator, engine & gearbox mountings, for damage and reinstall components and check engine running functionality	New	480.00	300.00
6	To remove and check RH & LH rear suspension system and rear differential	New	380.00	0.00
7	To perform large vehicle wheel alignment	New	130.00	80.00
8	To remove front damaged parts, to jack out front panel, front body, and cut out damaged parts, to reshape and repair front panel, front grille, LH head lamp inner panel, , LH door hinge pillar, drive cabin rear windscreen panel, drive cabin hinge panel, and adjust body panel alignment	New	1,200.00	1,000.00
9	To reweld, and repair vehicle chassis. To remove and reinstall necessary parts to facilitate repairs	New	2,500.00	2,000.00
10	To spray paint affected front and inner damaged portion inclusive of preparatory works and material	New	750.00	700.00
Gross Labour Cost (\$\$)			5,925.00	4,425.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >