Page 1 of 5 Adjuster Report

#### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

#### VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI20006305/KTF3E2

Date: 18/11/2020

**REFERENCE** 

China Taiping Insurance Handling Insurer: (Singapore) Pte. Ltd.

Policy No: DMPCSNA00041502000

Claimant Vehicle SDU1000K

**Insured Vehicle** SKS8913H

No:

No:

Claim No:

Date of Loss: 02/06/2020

Nature of Claim: TP

SNM20D202075

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

Reg No: **SDU1000K** 

Make & Model: TOYOTA WISH, 1.8 X (A) Engine No: 2ZR1622994 Reg. Date: 15/12/2015 (Man. Year: 2015) Chassis No: ZGE206025992 Metallic Pearl White Colour: Odometer: 123622 km

**Engine Capacity:** 1797 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

Steering (Serviceable): Yes Footbrake (Serviceable): General Condition: Yes

Pre-accident Condition: Handbrake (Serviceable): Yes Engine Modification:

CONDITION OF TYRES

225/45R17 Front Tyre Size: 225/45R17 Rear Tyre Size: Front Left Side: Michelin 7 mm Rear Left Side: Michelin 7 mm Michelin 7 mm Rear Right Side: Michelin 7 mm Front Right Side:

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	300.00	200.00	100.00	33.33
Paintwork Labour	0.00	0.00	0.00	
Towing  Gross Total (S\$)	0.00	0.00	0.00	
	300.00	200.00	100.00	33.33
+ GST 7.00/7.00% (S\$)	21.00	14.00	7.00	33.33
Nett Amount (S\$)	321.00	214.00	107.00	33.33

INSPECTION

Date of Assignment: 27/07/2020

Date Inspected: 11/06/2020 Inspected At: Ah Lim Motor Company (AMK)

10 Ang Mo Kio Industrial Park 2A, #01-09

**AMK** Autopoint Singapore 568047

Estimated Period of Repair: 1.0 days

https://singapore.merimen.com/claims/index.cfm?fusebox=MTRadjuster&fuseaction=gen... 18/11/2020

Adjuster Report Page 2 of 5

Adjuster: KENNETH KONG Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 5

(REPAIR COST NOT CONCLUDE)

Adjuster Report Page 4 of 5

## **REPAIR DETAILS**

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 18 Nov 2020)

Parts: M1-MPV TOYOTA WISH 1.8 X (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SDU1000K)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page

numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

#### **Recommended Parts**

There are no new parts selected.

Report was unsubmitted during this print-out.

Adjuster Report Page 5 of 5

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

### Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount				
Lab	<u>Labour Items</u>							
1	TO SPRAY REAR DOOR RH	New	300.00	200.00				
		Gross Labour Cost (S\$)	300.00	200.00				
		Report was unsubmitted during this print-out.						

< END OF ESTIMATES >