

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC3/AIG20006306/AES3Q2
Date: 19/05/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1700083504-02
Claimant Vehicle No :	SGD223U	Insured Vehicle No :	SDE8008C
Date of Loss:	09/06/2020	Nature of Claim:	TP
		Claim No:	4191889783SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SGD223U		
Make & Model:	AUDI A4, 1.4 TFSI S TRONIC (A)	Engine No:	CVN022715
Reg. Date:	23/01/2017 (Man. Year: 2016)	Chassis No:	WAUZZZF44HA063309
Colour:	Silver	Odometer:	79491 km
Engine Capacity:	1395 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	245/35 R19	Rear Tyre Size:	245/35 R19
Front Left Side:	Falken 6 mm	Rear Left Side:	Falken 6 mm
Front Right Side:	Falken 6 mm	Rear Right Side:	Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,961.00	1,693.84	2,267.16	57.24
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,952.00	2,152.00	1,800.00	45.55
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	7,913.00	3,845.84	4,067.16	51.40
+ GST 7.00/7.00% (S\$)	553.91	269.21	284.70	51.40

Nett Amount (S\$)	8,466.91	4,115.05	4,351.86	51.40
+ Loss of Use (4.0 x S\$60.00/day) (S\$)		240.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		4,357.05		

INSPECTION

Date of Assignment: 11/06/2020

Date Inspected: 11/06/2020

Estimated Period of Repair: 4.0 days

Inspected At: Premium Automobiles Pte Ltd (UBI)
55 Ubi Road 1
Singapore 408699

Adjuster: ADRIAN LING**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	2,079.00 FS	*1,663.20 FS
2	1		*REAR BUMPER FIXING PARTS	Not Necessary	69.00 FS	*- FS
3	1		*REAR BUMPER SECURING STRIP	Not Necessary	210.00 FS	*- FS
4	1		*REAR BUMPER SPOILER	Not Necessary	234.00 FS	*- FS
5	1		*REAR LIGHT REFLECTOR -RH REAR	Not Necessary	39.00 FS	*- FS
6	1		*LED TAIL LIGHT -RH	Not Necessary	959.00 FS	*- FS
7	1		*TAIL LIGHT TRIM -RH	Not Necessary	28.00 FS	*- FS
8	1		*REAR BUMPER GUIDE SECTION -RH	Not Necessary	43.00 FS	*- FS
9	1		*SUNDRIES	Necessary	300.00 FS	*30.64 FS
F=Franchise part. S=SpcNett.						
Total Parts (S\$)					3,961.00	1,693.84

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR .CHECK FUNCTION AND RENEW ACCORDING TO DAMAGE	New	360.00	360.00
2	TO DISMANTLE AND RENEW REAR BUMPER .TO REPAIR RHS REAR FENDER .RE-ORGANISE REAR CRASH MANAGEMENT COMPONENTS .REINSTALL ALL PARTS REMOVED	New	1,400.00	500.00
3	TO RESPRAY REAR BUMPER AND RHS REAR FENDER	New	2,000.00	1,100.00
4	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (S\$)			3,952.00	2,152.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >