

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/EGI20006307/ETF3E2

Date: 01/07/2020

REFERENCE

Handling Insurer: ERGO Insurance Pte. Ltd.

Policy No:

Claimant Vehicle No : GBK2141G

Insured Vehicle No : YQ849H

Date of Loss: 09/06/2020

Nature of Claim:

TP

Claim No: CDMCG20000765

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBK2141G**

Make & Model: TOYOTA HIACE, 3.0 D TURBO 5 DR (M)

Engine No: 1KDB024634

Reg. Date: 28/02/2020 (Man. Year: 2019)

Chassis No: JTFHT02P000250169

Colour: White

Odometer: 921 km

Engine Capacity: 2982 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195 R15C

Rear Tyre Size:

195 R15C

Front Left Side: Bridgestone 5 mm

Rear Left Side:

Bridgestone 5 mm

Front Right Side: Bridgestone 5 mm

Rear Right Side:

Bridgestone 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,273.65	6,174.00	2,099.65	25.38
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,500.00	2,650.00	850.00	24.29
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	11,773.65	8,824.00	2,949.65	25.05
+ GST 7.00/7.00% (S\$)	824.16	617.68	206.48	25.05
Nett Amount (S\$)	12,597.81	9,441.68	3,156.13	25.05

INSPECTION

Date of Assignment: 10/06/2020

Date Inspected: 10/06/2020 Inspected At:

Efficient Motor & Engineering Works Pte
Ltd (HQ)
56 Loyang Way #06-07, Loyang Enterprise
Building
Singapore 508775

Estimated Period of Repair: 10.0 days

Adjuster: CHEN TSUE YEE

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 01 Jul 2020)
Parts:	213	TOYOTA HIACE 3.0 D TURBO 5 DR (M) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBK2141G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*RH HEADLAMP ASSY	Cut	750.00 FL	*750.00 FL
2	1		*RH FRONT CORNER PANEL	Repair	195.00 FL	*- FL
3	1		*RH SIDE MIRROR ASSY	Broken	1,015.00 FL	*1,015.00 FL
4	1		*RH FRONT DOOR	Dented	1,794.00 FL	*1,794.00 FL
5	1		*RH FRONT DOOR OUTER MOULDING	Cut	82.00 FL	*82.00 FL
6	1		*RH QUARTER PANEL	Dented	1,062.00 FL	*1,062.00 FL
7	1		*RH SLIDE DOOR	Dented	1,600.00 FL	*1,600.00 FL
8	1		*RH SLIDE DOOR WEATHERSTRIP	Crushed	359.00 FL	*359.00 FL
9	1		*RH SLIDE DOOR RAIL GUIDE	Not Necessary	460.00 FL	*- FL
10	1		*RH SLIDE DOOR LOCK REAR	Bent	280.00 FL	*280.00 FL
11	1		*RH SLIDE DOOR LOCK FRONT	Bent	145.00 FL	*145.00 FL
12	1		*RH SLIDE DOOR LOCK ACTUATOR	Bent	145.00 FL	*145.00 FL
13	1		*RH SLIDE DOOR HANDLE INNER	Not Necessary	75.00 FL	*- FL
14	1		*RH SLIDE DOOR LOCK FULL OPEN STOP	Not Necessary	185.00 FL	*- FL
15	1		*RH SLIDE DOOR HINGE CENTER	Bent	150.00 FL	*150.00 FL
16	1		*RH SLIDE DOOR ROLLER LOWER	Bent	320.00 FL	*320.00 FL
17	1		*RH SLIDE DOOR ROLLER UPPER	Bent	85.00 FL	*85.00 FL
18	1		*RH SLIDE DOOR STRIKER (2PCS)	Bent (1Pc Only)	90.00 FL	*45.00 FL
19	1		*RH SLIDE DOOR STEP PANEL	Repair	1,206.20 FL	*- FL
20	1		*RH SLIDE DOOR SCUFF PLATE	Not Necessary	180.00 FL	*- FL
21	1		*RH SLIDE DOOR INNER TRIM BOARD	Crushed	280.00 FL	*280.00 FL
22	2		*FRONT / REAR WHEEL HUB CAP	Not Necessary	360.00 FL	*- FL
23	1		*SET RH SLIDE DOOR TRIMBOARD CLIP	Necessary	50.00 FS	*30.00 FS
24	1		*RH FRT DOOR CO. REG STICKER	Necessary	30.00 FS	*30.00 FS
25	1		*SEALANT	Necessary	80.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	10,978.20	8,202.00
- List Item Discount on L Items 25.00/25.00% (\$\$)	2,704.55	2,028.00
Total Parts (\$\$)	8,273.65	6,174.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CUT & WELD - DAMAGED PANELS RH SIDE PORTION / TO PANEL BEAT & ALIGN DOOR, REMOVE & REPLACE DAMAGED PARTS	New	1,500.00	1,200.00
2	TO APPLY ANTI RUST COAT AND TUFF KOTE REPAIRED AREAS	New	100.00	60.00
3	TO CHECK AND RECTIFY LIGHTING & WIRING	New	50.00	30.00
4	TO SPRAY PAINTING FOR LH PORTIONS, & AFFECTED AREAS	New	1,500.00	1,200.00
5	TO TRANSFER SLIDE DOOR COMPONENTS	New	250.00	100.00
6	TO DO TYRE BALANCING & WHEEL ALIGNMENT	New	100.00	60.00
Gross Labour Cost (S\$)			3,500.00	2,650.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >