Adjuster Report Page 1 of 4

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/AIG20006308/AVF3E2

Date: 17/07/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100497779 Claimant Vehicle SMN6178D Insured Vehicle No: SLK3458T No:

ΤP Date of Loss: 06/06/2020 Nature of Claim: Claim No: 3855239244SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SMN6178D

Make & Model: TOYOTA SIENTA, 1.5 (A) Engine No: 2NRX467329

Reg. Date: 21/08/2019 (Man. Year: 2019) Chassis No: MHFZ28H3300064245

Colour: Odometer: **Bronze** 60151 km

Engine Capacity: 1496 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

185/60 R15 Front Tyre Size: 185/60 R15 Rear Tyre Size: Front Left Side: Rear Left Side: Hankook 6 mm Hankook 6 mm Rear Right Side: Front Right Side: Hankook 6 mm Hankook 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,332.74	1,234.37	3,098.37	71.51
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,220.00	1,280.00	940.00	42.34
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,552.74	2,514.37	4,038.37	61.63
Approved Total (Overridden) (S\$)		2,000.00		
Nett Amount (S\$)	6,552.74	2,000.00	4,552.74	69.48

INSPECTION

Date of Assignment: 10/06/2020

Date Inspected: 24/06/2020 Inspected At: Yap Lee Motor (HQ)

1 Kaki Bukit Avenue 6, #01-26 Autobay @

Kaki Bukit

Singapore 417883

Estimated Period of Repair: 3.0 days

Adjuster: ADRIAN LING Manager: VERON CHEN Adjuster Report Page 2 of 4

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 4

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	788.70 FL	*566.10 FL
2	1		*REAR BUMPER RETAINER	O/S Necessary	329.80 FL	*95.00 FL
3	2		*REAR BUMPER BRACKET	Not Necessary	375.84 FL	*- FL
4	1		*REAR BUMPER PROTECTOR (CENTRE)	Not Necessary	225.00 FL	*- FL
5	1		*REAR BUMPER REFLECTOR RH	Cracked	95.00 FL	*95.00 FL
6	1		*REAR BUMPER SIDE PROTECTOR RH	Cut	280.48 FL	*280.48 FL
7	1		*REAR END PANEL	Repair	820.70 FL	*- FL
8	1		*TAILLAMP RH	Cut	477.25 FL	*477.25 FL
9	1		*TAILLAMP PANEL RH	Not Necessary	105.75 FL	*- FL
10	1		*TRUNLEWD LAMP RH	Not Necessary	341.08 FL	*- FL
11	1		*REAR FENDER RH	Repair	672.59 FL	*- FL
12	1		*REAR FENDER LINER RH	Not Necessary	236.74 FL	*- FL
13	1		*REAR FENDER AIR VENT RH	Cracked	92.00 FL	*92.00 FL
14	1		*SET REAR BUMPER CLIP	Necessary	60.00 FS	*30.00 FS
15	1		*REVERSE SENSOR	Not Necessary	350.00 FS	*- FS
16	1		*SET REAR FENDER LINER CLIP	Not Necessary	50.00 FS	*- FS
F=Fra	anchise	part. S=SpcN	Nett. L=ListItemDisc.	_		
				Sub Total (S\$)	5,300.93	1,635.83
			- List Item Discount on L Items	20.00/25.00% (S\$) _	968.19	401.46
				Total Parts (S\$)	4,332.74	1,234.37

Report was unsubmitted during this print-out.

Adjuster Report Page 4 of 4

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount			
Lab	our Items						
1	TO REMOVE & REFIX REVERSE SENSOR SYSTEM	New	120.00	50.00			
2	TO REMOVE & REFIX INNER TRIM GARNISH	New	120.00	50.00			
3	TO APPLY UNDERCOATING	New	120.00	50.00			
4	TO CHECK WIRING SYSTEM	New	60.00	30.00			
5	TO CUT, JACK, REMOVE & REPAIR THE ABOVE PARTS	New	800.00	500.00			
6	TO RE-SPRAY ON THE AFFECTED AREAS	New	1,000.00	600.00			
	Gross Labour Cost (S\$)		2,220.00	1,280.00			
	Report was unsubmitted during this print-out.						

< END OF ESTIMATES >