

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG20006309/T1RS3Q2
Date: 13/08/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1700027051-02
Claimant Vehicle No :	SHA1837X	Insured Vehicle No :	SLQ6400H
Date of Loss:	03/06/2020	Nature of Claim:	TP
		Claim No:	6296731688SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHA1837X		
Make & Model:	HYUNDAI I40, 1.7 D CRDI F/L ABS AIRBAG 4DR (A)	Engine No:	D4FDGU613746
Reg. Date:	28/04/2016 (Man. Year: 2016)	Chassis No:	KMHLB41UMGU087854
Colour:	Blue	Odometer:	506482 km
Engine Capacity:	1685 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	West Lake 6 mm	Rear Left Side:	West Lake 6 mm
Front Right Side:	West Lake 6 mm	Rear Right Side:	West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,457.16	2,129.96	1,327.20	38.39
Miscellaneous Items	0.00	0.00	0.00	
Labour	650.00	510.00	140.00	21.54
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,107.16	2,639.96	1,467.20	35.72
Approved Total (Overridden) (S\$)		2,100.00		

(S\$)	4,107.16	2,100.00	2,007.16	48.87
+ GST 7.00/7.00% (S\$)	287.50	147.00	140.50	48.87
Nett Amount (S\$)	4,394.66	2,247.00	2,147.66	48.87
+ Loss of Use (2.0 x S\$50.00/day) (S\$)		100.00		
+ Car Rental (2.0 x S\$114.95/day) (S\$)		229.90		
+ Doc/Search Fee (S\$)		7.49		
Nett Liability (S\$)		2,584.39		

INSPECTION

Date of Assignment: 08/06/2020

Date Inspected: 08/06/2020

Inspected At:

ComfortDelGro Engineering Pte Ltd (Loyang)
59 Loyang Drive
Singapore 508969

Estimated Period of Repair: 2.0 days

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** Jaslin Kok Chin Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*I40V3 BUMPER W LIP & FOG	Deformed	1,052.20 FL	*1,052.20 FL
2	1		*I40VC BRKT ASSY - FR BPR UP	Not Necessary	22.40 FL	*- FL
3	1		*I40VC BRACKET - FR BUMPER S	Not Necessary	24.60 FL	*- FL
4	10		*HYUNDAI BUMPER COVER CLIP	Necessary	246.00 FL	*22.00 FL
5	1		*I40VC LAMP ASSY-HEAD LH (Cut)	Not Consistent With The Impact	1,388.00 FL	*- FL
6	1		*I40V3 GRILLE ASSY - RADIATOR	Cracked	1,480.00 FL	*1,480.00 FL
7	1		*I40V3 SYMBOL MARK-H	Necessary	39.50 FL	*39.50 FL
8	1		*NO PLATE(S)	Cracked	25.00 FS	*25.00 FS
9	1		*NO PLATE(S) TRIM COVER	Cracked	30.00 FS	*30.00 FS
					Sub Total (S\$)	4,307.70
					- List Item Discount on L Items 20.00/20.00% (S\$)	850.54
					Total Parts (S\$)	3,457.16

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING.	New	350.00	280.00
2	SPRAY PAINTING ON AFFECTED AREA.	New	250.00	200.00
3	CHECK ALL LIGHTING.	New	50.00	30.00
Gross Labour Cost (\$\$)			650.00	510.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >