Adjuster Report Page 1 of 4

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI20006314/QSF3Q2

Date: 02/11/2020

REFERENCE

China Taiping Insurance Handling Insurer:

(Singapore) Pte. Ltd.

Policy No: DMCVSN19361119000

Claimant Vehicle No:

SLR9593J

Insured Vehicle No:

YN2279E

Date of Loss: 10/06/2020 Nature of ΤP Claim:

Claim

SNM20D202097/C02/TANKL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLR9593J**

Make & Model: HONDA GRACE HYBRID, 1.5 (A) Engine No: LEB5255510 Reg. Date: 31/08/2017 (Man. Year: 2016) Chassis No: GM41105495 Colour: Odometer: 200093 km Black

Engine Capacity: 1496 cc Market Value/New Car Price: N/A

Market Value/New Car Price Sum Insured (S\$):

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/60R15 Rear Tyre Size: 185/60R15 Front Left Side: Rear Left Side: Firenza 6 mm Firenza 6 mm Front Right Side: Rear Right Side: Firenza 6 mm Firenza 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,253.44	1,880.24	373.20	16.56
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,350.00	900.00	450.00	33.33
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	3,603.44	2,780.24	823.20	22.84
Approved Total (Overridden) (S\$)		2,200.00		
(S\$)	3,603.44	2,200.00	1,403.44	38.95
+ GST 7.00/7.00% (S\$)	252.24	154.00	98.24	38.95
Nett Amount (S\$)	3,855.68	2,354.00	1,501.68	38.95

INSPECTION

Date of Assignment: 11/06/2020

Lion City Rentals Pte Ltd (HQ) Date Inspected: 12/06/2020 Inspected At:

60 Jalan Lam Huat, #04-35/36 Carros

Centre

Singapore 737569

Estimated Period of Repair: 3.0 days

Adjuster: OI SUN PIN Manager: Hiew May Fung Adjuster Report Page 2 of 4

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 4

REPAIR DETAILS

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 02 Nov 2020)

Parts: 143 HONDA GRACE HYBRID 1.5 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SLR9593J)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*F/R FENDER	Dented	500.00 FL	*325.00 FL
2	1		*F/L FENDER INNER LINER	Serviceable	120.00 FL	*- FL
3	1		*F/L FENDER HYBRID EMBLEM	Necessary	86.80 FL	*86.80 FL
1	1		*F/L HEADLAMP	Scratched	980.00 FL	*980.00 FL
5	1		*FRONT BUMPER	Crumpled	980.00 FL	*921.00 FL
3	1		*SET BUMPER CLIPS	Necessary	120.00 FS	*30.00 FS
==Fra	anchise	part. S=SpcN	ett. L=ListItemDisc.	_		
				Sub Total (S\$)	2,786.80	2,342.80
			- List Item Discount on L Items 20.00/20.00% (S\$)			462.56
				Total Parts (S\$)	2,253.44	1,880.24

Report was unsubmitted during this print-out.

Adjuster Report Page 4 of 4

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	TO LABOUR CHARGE FOR REMOVING FRONT BUMPER AND F/R FENDER OUT TO FACILITATE REPAIRS AND REPLACEMENT OF DAMAGED PARTS	New	750.00	500.00
2	TO RESPRAY F/R FENDER AND FRONT BUMPER	New	600.00	400.00
	Gross Labo	Gross Labour Cost (S\$)		900.00
	Report was unsubmitted dur	ing this print-out.		

< END OF ESTIMATES >