

ASS. REC. BY: Sun Pin

REF:

CTI CS/CTI20006314/Qsf3

(TP) ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / N/S / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted:

Vehicle: IN / OUT

Veh No:

SLR 9593JYr Regn: 31/08/2017Type: M. Car M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda Civic 1.5 Hybrid c.c. 1496

Colour:

Black

A/C: Insured / Std / NI / NA

Sp. Reading

200093

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

GM41165495

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / SRIm / STD A/RIm or

Tyre Size:

F: 185/60 R15R: 185/60 R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Firenza

Front

Rear

R/Bal. 6 mmR/Bal. 6 mmL/Bal. 6 mmL/Bal. 6 mmD.O.A. 11/06/2020D.O.I. 12/06/2020

Survey held at

LCRDes. of Damages: Frt / Rear O/S N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

MV: 51,000PR: 39,642NV: 17,358SUN PIN CONFIRMED L/S \$ 2,200.00/3 DAYS WITH SIAK TONG
(\$ 1,283.44/RED - 37%)

Date/Time, File, Pass to?

30/10/2020

1) TYPIST



Prell. Report



Final Report

Date/Time, File Return to?

2)

Days Of Repair: 3Resurvey No. of Trip: 1

Survey Fee:

Transportation:

S + RS, SI

Phone

Others

TOTAL

Add Fee:



Site Insp (\$



Interview (\$



Tech. Invs (\$



Weat/and (\$

Report Formed:

Lump Sum / L/S: L/S \$ 2,200.00