

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/CTI20006316/T1TF3E2

**Date:** 25/06/2020

### REFERENCE

Handling Insurer: China Taiping Insurance  
(Singapore) Pte. Ltd.

Policy No: DMCVSN30599919000

**Claimant Vehicle No :** GBF9401L

**Insured Vehicle No :** GBJ7514L

Date of Loss: 13/04/2020

Nature of Claim: TP

Claim No: SNM20D202053/C02

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBF9401L**

Make & Model: KIA K2500, 2.5 D 6M/T (M)

Engine No: D4CBG107254

Reg. Date: 11/04/2017 (Man. Year: 2016)

Chassis No: KNCSJX76LG7118085

Colour: White

Odometer: 0 km

Engine Capacity: 2497 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No

Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 195 R15

Rear Tyre Size: 155 R12 (D)

Front Left Side: Yokohama 6 mm

Rear Left Side: Yokohama 6/6 mm

Front Right Side: Yokohama 6 mm

Rear Right Side: Yokohama 6/6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	70,084.31	20,588.85	49,495.46	70.62
Miscellaneous Items	0.00	0.00	0.00	
Labour	18,100.00	3,940.00	14,160.00	78.23
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>88,184.31</b>	<b>24,528.85</b>	<b>63,655.46</b>	<b>72.18</b>

### INSPECTION

Date of Assignment: 16/06/2020

Date Inspected: 15/06/2020 Inspected At:

Huafong Contractor Pte Ltd (HQ)  
9 Benoi Crescent  
Singapore 629972

Estimated Period of Repair: 0.0 days

**Adjuster:** MOHD TAUFIKH BIN HAMID

**Manager:** DENISE TAY KWEE CHENG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*



(EXCLUDE CHECK ITEMS S\$52,119.19NETT)

## REPAIR DETAILS

### Reference

**Part Source:** (Last Synchronised: 25 Jun 2020)

**Parts:** N/A KIA K2500 2.5 D 6M/T (M) (Model not available in database)

**Labour:** Repairer's (Price-denominated Standard List)

**Print Code:** (Unsubmitted, no print-code for GBF9401L)

**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*MAIN FRAME	* Check	16,738.20 F	*- F
2	1		*REAR DECK	Bent	4,850.00 F	*4,850.00 F
3	1		*FRAME ASSY FRONT	Repair	2,758.20 F	*- F
4	1		*REAR BODY MOUTING	* Check	1,620.48 F	*- F
5	1		*BODY PANEL FRONT	Repair	855.20 F	*- F
6	1		*BODY PANEL FLOOR	Repair	1,783.20 F	*- F
7	1		*SIDE BODY PANEL, RH	Bent	758.20 F	*758.20 F
8	1		*FRONT DOOR PANEL, RH	Bent	1,149.32 F	*1,149.32 F
9	1		*ROOF CANOPY ALUMINIUM	Bent	2,850.00 F	*2,850.00 F
10	1		*BODY SIDE MOULDING, RH	* Check	980.00 F	*- F
11	1		*REAR VIEW MIRROR - OUTSIDE, RH	Cracked	240.00 F	*240.00 F
12	1		*REAR VIEW MIRROR - INSIDE	Distorted	210.00 F	*210.00 F
13	1		*INTERIOR SIDE TRIM, RH	* Check	834.23 F	*- F
14	1		*WHEEL GUARD, RH	Deformed	485.31 F	*485.31 F
15	1		*FRONT BUMPER BRACKET, RH	Deformed	475.92 F	*475.92 F
16	1		*WINDSHIELD GLASS AND MOULDING ASSY	Cracked	550.23 F	*550.23 F
17	1		*FRONT DOOR WINDOW REGULATOR & GLASS	Bent	649.23 F	*649.23 F
18	1		*FRONT DOOR TRIM, RH	Deformed	173.23 F	*173.23 F
19	1		*FRONT DOOR MOULDING, RH	Deformed	183.20 F	*183.20 F
20	1		*FRONT DOOR LOCKING, RH	Bent	134.54 F	*134.54 F
21	1		*ENGINE & TRANSAXLE MOUNTING, RH	* Check	389.56 F	*- F
22	1		*COOLANT RADIATOR AND COOLANT PIPE	* Check	1,392.30 F	*- F
23	1		*FUEL TANK	Bent	1,758.36 F	*1,758.36 F
24	1		*FUEL PUMP & FUEL HOSE	* Check	392.50 F	*- F
25	1		*FUEL TANK STRAP ASSY	Deformed	83.40 F	*83.40 F
26	1		*ALTERNATOR	* Check	356.80 F	*- F
27	1		*CLUTCH BOOSTER	* Check	487.24 F	*- F
28	1		*BRAKE BOOSTER	* Check	984.34 F	*- F
29	1		*BRAKE MASTER CYLINDER	* Check	675.20 F	*- F
30	1		*COOLANT RESERVOIR	* Check	367.24 F	*- F
31	1		*INTERCOOLER	* Check	1,378.86 F	*- F
32	1		*HEADLAMP ASSY, RH & LH	O/S Cracked / N/S * Check	1,300.00 F	*650.00 F
33	1		*BODY SIDE LAMP, RH	Cracked	258.00 F	*258.00 F
34	1		*ROOM LAMP	Not Necessary	35.00 F	*- F
35	1		*CROSSMEMBER ASSY	* Check	3,948.30 F	*- F
36	1		*FRONT SUSPENSION ASSY	* Check	4,382.30 F	*- F
37	1		*FRONT SPRING AND U BOLT, RH & LH	* Check	893.24 F	*- F
38	1		*UPPER ARM & LOWER ARM ASSY, RH & LH		1,738.32 F	*869.16 F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
				O/S Bent / N/S Not Necessary		
39	1		*KNUCKLE, RH & LH	O/S Bent / N/S Not Necessary	673.42 F	*336.71 F
40	1		*STABILIZER BAR & BUSHING ASSY-FRONT	Bent	456.34 F	*456.34 F
41	1		*STRUT BAR ASSY	Bent	348.90 F	*348.90 F
42	1		*POWER STEERING ASSY INCLUDING PUMP	Bent	2,318.80 F	*2,318.80 F
43	1		*BRAKE ASSY-FRONT, RH & LH	* Check	3,648.40 F	*- F
44	1		*DRIVESHAFT ASSY-FRONT, RH & LH	Not Necessary	2,738.80 F	*- F
45	1		*WHEEL AND RIM ASSY FRONT	Bent	800.00 F	*800.00 F
F=Franchise part.						
<b>Total Parts (S\$)</b>					<b>70,084.31</b>	<b>20,588.85</b>

Report was unsubmitted during this print-out.
---

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	BODY	New	3,600.00	2,400.00
2	PAINT	New	1,500.00	1,300.00
3	LABOUR TO APPLY TUFF COTE	New	1,000.00	240.00
4	LABOUR TO STRAIGHTEN CHASSIS (* Check)	New	12,000.00	0.00
5	TO APPLY TUFF COTE (NPA)	New	0.00	0.00
<b>Gross Labour Cost (S\$)</b>			<b>18,100.00</b>	<b>3,940.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >