

24/06/20
Admin
S.S.

SLR1046A.

JMYSRCYIAG4007215.

Bumper	858	
Reinforcement.	313	
Bumper Grille.	95	
Bumper Top Cover		
Front Grille.	254	Grille Chrome
Bonnet	809	Hinge x 2
Lock	92	58 x 2 = 116.
Headlamp x 2	698 x 2 = 1396	
Fender RH.	526	
Condenser	1023	
Radiator	1161	7789
Fan Casing.	243	7010/10
Support Panel Cover	187	
Support Panel	582	
Bumper Bumper	134	
Top Beam.		

Panc Batching.	900
Spng Batching.	1000.
Wiring.	30.
Remoe, condenser, radiator	120. (2050)

Repair Range: 7K-8K
07 Days.

total: 9060.10
L/S: 7.2K
07 Days.