

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC6/III20006321/KPA3Q2**Date:** 03/09/2020REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No:	MCOM0015
<b>Claimant</b>		
<b>Vehicle No :</b> SKH2785H	<b>Insured Vehicle No :</b>	SHC8852U
Date of Loss: 13/06/2020	Nature of Claim: TP	Claim No: MCT20060130

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SKH2785H</b>		
Make & Model:	RENAULT FLUENCE, 1.6 CVT ABS D/AB 2WD (A)	Engine No:	H4MC721F126482
Reg. Date:	22/11/2012 (Man. Year: 2012)	Chassis No:	VF1LZB50TUC261634
Colour:	Metallic Black	Odometer:	126861 km
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/50R17	Rear Tyre Size:	215/50R17
Front Left Side:	Yokohama 8 mm	Rear Left Side:	Yokohama 8 mm
Front Right Side:	Yokohama 8 mm	Rear Right Side:	Yokohama 8 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	11,459.45	8,417.50	3,041.95	26.55
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,080.00	2,110.00	1,970.00	48.28
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>15,539.45</b>	<b>10,527.50</b>	<b>5,011.95</b>	<b>32.25</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>2,800.00</b>		
<b>Nett Amount (S\$)</b>	<b>15,539.45</b>	<b>2,800.00</b>	<b>12,739.45</b>	<b>81.98</b>
<b>+ Car Rental (9.0 x S\$100.00/day) (S\$)</b>		900.00		
<b>Nett Liability (S\$)</b>		<b>3,700.00</b>		

INSPECTION

Date of Assignment:	17/06/2020	
Date Inspected:	17/06/2020 Inspected At:	Ja Autocare Pte Ltd - Sin Ming (HQ) 160 SIN MING DRIVE, #08-16 SIN MING AUTO CITY Singapore 575722
Estimated Period of Repair:	9.0 days	

**Adjuster:** KENNETH KONG**Manager:** CHEW HSIAO TONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 23 Jul 2020)
<b>Parts:</b> 143	RENAULT FLUENCE 1.6 CVT ABS D/AB 2WD (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SKH2785H)
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b> Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOT LID	Bent	1,950.00 FL	*1,950.00 FL
2	1		*BOOT LID GARNISH	Serviceable	580.00 FL	*- FL
3	1		*BOOT LID RUBBER (50%)	Distorted / Cut	252.00 FS	*140.00 FS
4	1		*BOOT LID LOCK ASSY	Dented	550.00 FL	*550.00 FL
5	1		*BOOT LID LOGO	Necessary	75.00 FL	*75.00 FL
6	1		*BOOT LID CHROME	Serviceable	250.00 FL	*- FL
7	1		*BOOT FLUENCE EMBLEM	Not Necessary	220.00 FL	*- FL
8	1		*BOOT LID SPOILER	Serviceable	620.00 FL	*- FL
9	1		*BOOT REFLECTOR	N/S Serviceable / O/S Cracked	440.00 FL	*220.00 FL
10	1		*REAR BUMPER	Bent	1,850.00 FL	*1,850.00 FL
11	2		*REAR BUMPER BRACKET	Distorted	180.00 FL	*180.00 FL
12	2		*REAR BUMPER RETAINER	Cracked	130.00 FL	*130.00 FL
13	1		*REAR BUMPER CLIPS	Necessary	80.00 FL	*80.00 FL
14	1		*REAR BUMPER REINFORCEMENT	Bent	580.00 FL	*580.00 FL
15	1		*REAR BUMPER SPONGE	Serviceable	185.00 FL	*- FL
16	1		*REAR BUMPER UNDER GARNISH	Bent	380.00 FL	*380.00 FL
17	1		*REAR BUMPER UNDER GARNISH CLIPS	Necessary	80.00 FL	*80.00 FL
18	2		*REAR BUMPER REFLECTOR	N/S Missing / O/S Cracked	240.00 FL	*240.00 FL
19	1		*TAIL LAMP ASSY	O/S Cut	1,500.00 FL	*750.00 FL
20	1		*REAR EXHAUST CHROME	Dented	350.00 FL	*350.00 FL
21	1		*REAR PANEL	Bent	1,200.00 FL	*1,200.00 FL
22	1		*REAR PANEL GARNISH	Dented	360.00 FL	*360.00 FL
23	1		*REAR WINDSCREEN MOULDING	Not Necessary	180.50 FL	*- FL
24	1		*REVERSE SENSOR	Cracked	350.00 FS	*200.00 FS
25	1		*REAR NUMBER PLATE WITH CASING	Serviceable	75.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>12,657.50</b>	<b>9,315.00</b>
<b>- List Item Discount on L Items 10.00/10.00% (\$\$)</b>	1,198.05	897.50
<b>Total Parts (\$\$)</b>	<b>11,459.45</b>	<b>8,417.50</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO CHECK WIRING	New	100.00	20.00
2	TO DISMANTLE & REFIX REVERSE SENSOR	New	120.00	50.00
3	TO DISMANTLE & REFIX REAR EXHAUST	New	160.00	80.00
4	TO APPLY ANTI RUST CHEMICAL	New	100.00	60.00
5	TO KNOCK OUT DENTS ON AFFECTED AREAS AND RENEW PARTS	New	1,800.00	1,000.00
6	TO PUTTY & RESPRAY PAINTING	New	1,800.00	900.00
			<b>Gross Labour Cost (\$)</b>	<b>2,110.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >